
# Vieux Carré Commission Architecture Committee Meeting

Tuesday, May 11, 2021



## 715-721 Chartres



721 Chartres




























































**VCC Architectural Committee** 

5/4/21 1 of 2 57. LOUIS CATHEDRAL SIDE ENTRANCE








**VCC Architectural Committee** 


1/2" : 11.0" ± 5/4/21 2 of 2 37. LOUIS CATHEPRAL SIDE ENTRANCE



Page 20 of 255














813 Barracks – 1896 Sanborn map


















































### **ALTERATIONS TO 813 BARRACKS STREET**

Page 36 of 255



A SHIP MARKET AND ANALYSIS ARRESTS AND ADDRESS OF THE COMPANY OF THE

WOOK SCHOOL ACTION TO THE STATE AND ALL AND AL

an amount framework communication or country for Communication according

4 Month Service Strategy at Auditor Service Service

See the order of the control of the co

No. There is not record as some on the placement of the section of the contract of the section o

Barracks Street ന ž 8

HEVISIONS.		
fe:	Dee	loope
DRAF	JWL JAN	
DEAUTHORY REALE JOHN		CENERAL SCHOOL SE SAME

## G001

PROJECT INFORMATION

RESTRUCTION AND ADDRESS OF

PLMS

ADD SPE
ADD SPE
ADD SPECTROD SPE
ADD SPECTROD PLMS
ADD SPECTROD PLMS
ADD SPECTROD PLMS
ADD SPECTROD SPECTRO

PROJECT DIRECTORY

SHIP SHIPS IN

BUSINESS.

## GENERAL NOTES

The states, contact of one, record A. septimes removes the selection, based one of he stage.

1) NECTORNAL PRODUCT CONTROL PRODUCT OF RESPECT OF THE PRODUCT OF RESPECT OF ALL PRODUCTS AND ADMINISTRAL DATE.

COMMATING HALL MANY SHIP HOWERS FIRTHER THE STREET, DISPOSE THE SHIP HOW AND PRODUCT THE STREET, THE SHIP HOW AS

LOCAL HIS REPORT AND ARRESTS OF THE REPORT OF THE THE REPORT OF THE REPORT OF THE REPORT OF THE REPORT OF THE REPOR


Septiment for the section of the second of the filtred responsibilities (supremit septiment) from all sections on their highest section of the section of the

813 Barracks












































































429 Decatur









429 Decatur – c. 1940s



































823 Decatur

# 24.15 CLASSIC SIGNS

## 24.15.A **ELIGIBILITY**

- 1. Any person or the City may apply for designation of an existing sign, as of the date of adoption of this Ordinance, as a classic sign. Classic signs are exempt from area, setback, height, lighting, movement, flashing, placement, type, content, placement and construction materials requirements of this Ordinance.
- 2. To qualify for designation as a classic sign, the sign shall:
  - a. Be at least twenty-five (25) years old or an exact replica of an original sign where the combined age of the duplicate and original sign is at least twenty-five (25) years.
  - b. Possess unique physical design characteristics, such as configuration, message, color, texture, etc.
  - c. Be of significance to the city, regardless of the use identified by the sign.
- 3. A sign designated a classic sign may remain on the premises even if the original use to which the sign relates is no longer located on the premises.
- 4. No designated classic sign may be converted into a billboard.



## NEON

Neon signs, originally developed in the 1920s, are made of narrow, gas-filled electrified tubes. Given the Vieux Carré's unique architectural qualities and historic character, the use of neon is only allowed in the Vieux Carré Entertainment (VCE) district. In addition, neon is carefully reviewed by the VCC to determine compatibility with the building and surrounding area.



#### ILLUMINATED SIGN CABINET

Double-faced

Approximately 14 ft. tall

Painted aluminum sign cubinet with illumanted push through acrylic letters.

#### SIDEWALK VIEW









#### ILLUMINATED SIGN CABINET

Double-faced


Approximately 14 ft. fall

Painted aluminum sign cabinet with illumanted push through acrylic letters.

#### STREET VIEW













#### ILLUMINATED SIGN CABINET

Double-faced

Approximately 14 ft, tall


Painted aluminum sign cabinet with illumanted push through acrylic letters.

#### NIGHT SIDEWALK VIEW

















1041 Royal



1041 Royal

VCC Architectural Committee May 11, 2021



1041 Royal




1041 Royal




1041 Royal




1041 Royal




























Hedge higes Proposal at 1041 Royal to be modeled after artisting hedgehoss at the corner of chartes & Ursilines












615-17 Ursulines



615-17 Ursulines













615-17 Ursulines, ca. 2006








May 11, 2021











May 11, 2021



**VCC Architectural Committee** 

0.00

Two sets of double swing gates, approximately 5' tall, one set for each vestibule, as approved and permitted by the VCC.

Posts will be attached to plates which will be attached to the floor and the ceiling, similar to the set at 241 Royal Street, although there are options regarding the posts that may be dictated by the VCC.

The frame of gates will be 1 1/2" wide material, with 1/2" solid pickets, mildly pointed at the top, similar to those at 241 Royal Street.


The gates will open inward, with a latch or cane bolt or a similar mechanism to keep them open during business hours.

There will be a cane bolt or similar stabilization feature as well as brackets for a padlock or a lockbox, for security when they are closed.

This estimate is wide as there are unknowns regarding the duration and work involved with the permit process, as well as the condition of material underneath the tile floor covering/what material is above the ceiling boards.

All work to be primed and painted. A deposit of 50% will be necessary to begin work once permitted.

## 615-17 Ursulines – Current Proposal



The posts span from floor to ground and are approximately 8' tall.

The outer opening of the vestibule, where the gates fall, is approximately 70" wide.

These approximate measurements apply to both entrances, 615 and 617 Ursulines, as does this proposal.

## 615-17 Ursulines – Current Proposal

## Guide to drawing:


- A. 4"x4"x1/4" steel plate, 4 holes in each
- -the plate will be secured at ground level by 3/8" threaded rod that has been sunk into 1/2" holes drilled into tile. Concrete epoxy will keep the rod in place and washer/nut will sandwich the plate in place
- -the plate will be attached to wood ceiling with lag bolts
- B. 2"x2" square tubing, to be welded to the plates at top and bottom
- C. J-bolt adjustable hinge
- D. Verticals, and bottom horizontal frame of gate, are 1 1/2" x 1/2" flat bar
- E. Top horizontal of gate is 1 1/2" x 1/2" square punched channel, 4" centers
- F. Pickets are 1/2" solid square bar with mild point at top
- G. Square single lock box for double cylinder deadbolt
- H. Cane bolt will sink into 5/8"-3/4" hole drilled into ground, for additional security

The gates will measure 5' tall from ground to top of picket.

There will be an approximately 5" gap between bottom of gates and ground, to account for upward slope of entryway.


Given the 2" posts, space for hinges, and 1/2" gap between gates, each gate will be approximately 30" wide.


If necessary, we would also like the option to drill a small (1/2" at most) hole into the ground where inside edge of gate will be when open. We will epoxy in a hook or loop, with the corresponding piece welded to the bottom corner of the gate to keep it in a fully open position during business hours.



615-17 Ursulines – Current Proposal







615-17 Ursulines – 2016 Proposal





615-17 Ursulines – Approved Alcove "Gate" at 201 Royal St.





615-17 Ursulines – Approved Alcove "Gate" at 201 Royal St.






615-17 Ursulines – Approved Alcove "Gate" at 201 Royal St. when not in use



VCC Architectural Committee







VCC Architectural Committee

May 11, 2021






















1000 Orleans – Existing Railings on Orleans Elevation




#### Authement Iron Works (504) 467-6666 www.authement.co




1000 Orleans St








### 920 Governor Nicholls




920 Gov. Nicholls






















920 Gov. Nicholls







## **Appeals and Violations**

# 725 St Peter (withdrawn at applicant's request)





719 Toulouse
























































EXISTING CONDITIONS




1 NORTH EXTERIOR ELEVATION - DEMOLITION
A401 1/4" = 1'-0"


























EXISTING CONDITIONS




























1 EAST INTERIOR ELEVATION - DEMOLITION
|A402 1/4" = 1'-0"




















**EXISTING CONDITIONS** 























417-19 Bourbon

**VCC Architectural Committee** 









<u>417-19 Bourbon</u>

VCC Architectural Committee May 11, 2021




417-19 Bourbon

VCC Architectural Committee May 11, 2021



<u>417-19 Bourbon – Previously Existing Air Intake</u>





<u>417-19 Bourbon – Previously Existing Air Intake</u>






<u>417-19 Bourbon – Previously Existing Air Intake</u>



































420 Bourbon
















#### Primary Bourbon Street facade.

- 1. Door at left and right to be removed for new single swing glazed door to match historic profiles.
- 2. Existing shutters to be repaired.
- 3. Stucco to be repaired.
- 4. Existing cornice to remain.
- 5. Gutters / Downspouts to be replaced.
- 6. Existing composite slate roof to be repaired.
- 7. Existing dormers to be repaired. New exterior painted wood trim at dormer window surrounds and fascia.
- 8. Non-historic lights, security cameras, signage, conduit to be removed and replaced with approved fixtures.
- 9. Soffit structure to be repaired.
- 10. Window unit to be removed.


# 420 Bourbon




### 2 Existing Shutters and alleyway gate at Bourbon Street.

- 1. Privacy gate / barrier to be replaced with new to match historic profile.
- 2. Existing shutters to be repaired.
- 3. Stucco to be repaired.
- Door in photo behind shutters to be removed for new single swing door to match historic profiles.


















1 EXIST. WEST ELEV - MAIN BLDG 1/8" = 1'-0"




## 4 PROPOSED WEST ELEV - MAIN BLDG 1/8" = 1'-0"






2 EXIST. SOUTH ELEV - MAIN BLDG 1/8" = 1'-0"





5 PROPOSED SOUTH ELEV - MAIN BLDG 1/8" = 1'-0"






### View into Alleyway from Bourbon Street.

- 1. Services and conduit to be removed. New services + condout to be routed to reduce visual presence.
- 2. Former window openings to have infill structure repaired or replaced.
- 3. Shutters to be repaired; missing shutters to be replaced to match historic.
- Existing non historical structural bracing at end of alley to be evaluated by Structural engineer for removal or reconfiguration.
- 5. Spalling stucco to be removed.









### Reverse view of alley towards Bourbon.

- 1. Electrical meters, utility services and conduit to be removed. New services + conduit to be routed to reduce visual presence.
- Former window openings (not present) to have infill structure repaired or replaced.
   Shutters to be repaired; missing shutters to be replaced to match historic.
- 4. Spalling stucco to be removed.
- 5. Privacy gate / barrier to be replaced with new to match historic profile.







#### 6 Main Building Rear Facade.

- 1. Window / Glazed Door assembly to be replaced with new to match historic profiles.
- 2. Concrete curb below windows to be modified to be flush and finished with new stucco.
- 3. Non-compliant single riser to be removed.
- 4. Utility sink + temporary awning to be removed.
- 5. Conduit + Utility piping to be removed.
- 6. Speakers to be removed.
- 7. Window unit at dormer to be removed. Dormer windows to be replaced with new wood windows to match front historic windows. Window surround trim + fascia at dormers to be reconstructed.
- 8. Slate composite roof to be repaired.
- 9. Existing HM door to right of picture and transom infill wood panel to be removed. New transom glazing + new historic wood door to be fitted within existing trim.








### 7 Main Building Rear Facade

- 1. Window / Glazed Door assembly to be replaced with new to match historic profiles.
- 2. Concrete curb below windows to be modified to be flush and finished with new stucco.
- 3. Non-compliant single riser to be removed.
- 4. Utility sink + temporary awning to be removed.
- 5. Conduit + Utility piping to be removed.








NOTE: ALL ABANDONED CONDUIT & UTILITY LINES (NOT SHOWN, FOR CLARITY) TO BE DEMOLISHED, TYP THROUGHOUT.

B EXIST. E ELEV - MAIN BLDG

1/8" = 1'-0"





May 11, 2021



- Existing courtyard overview from rear (looking towards Bourbon)

  1. Existing paving to be removed, site regraded for ADA, and new paving installed. Existing drainage channel to left side of photo to be retained.
- 2. Existing brick planting beds, plantings, and tree stump to be removed.
- 3. Select areas of masonry to be repaired, repointed as required. Vegetation to be removed from masonry, and brick / mortar to be cleaned.
- 4. Existing wall sconces and conduit to be removed.
- 5. Non-compliant single riser to rear dependency to be removed.
- 6. Non-historic pendant lights at rear dependency to be replaced. Conduit to new fixtures to be minimized.
- 7. Windows + glazed door at main building rear facade to be removed and replaced.
- 8. Vinyl window at dormer to be replaced with new wood window to match historic profiles. Dormer to be repaired and receive new window surround trim / fascia.







### Existing courtyard overview.

- Existing paving to be removed, site regraded for ADA, and new paving installed. Existing drainage channel to right side of photo to be retained.
- 2. Existing brick planting beds, plantings, and tree stump to be removed.
- 3. Select areas of masonry to be repaired, repointed as required. Vegetation to be removed from masonry, and brick / mortar to be cleaned.
- 4. Existing wall sconces and conduit to be removed.
- 5. Fountain to be removed.
- 6. Non-compliant single riser to rear dependency to be removed.
- Non-historic pendant lights at rear dependency to be replaced. Conduit to new fixtures to be minimized.







### 10 Existing courtyard rear.

- 1. Existing paving to be removed, site regraded for ADA, and new paving installed.
- 2. Existing brick planting beds, plantings, and tree stump to be removed
- 3. Select areas of masonry to be repaired, repointed as required. Vegetation to be removed from masonry, and brick / mortar to be cleaned.
- 4. Metal site fence to be removed
- 5. Ice cooler, ice machine, mech. units, patio heaters to be removed.





### Rear Dependency Main Facade

- 1. Non-compliant single concrete risers to be removed.
- 2. Non-historic interior concrete floor to be removed to original floor level.
- 3. Ground floors doors and shutters to be replaced with new elongated to match historic profiles in same locations. New doors will be single swing to meet current Code.
- 4. Speakers, non-historic lights, to be replaced.
- 5. Existing steel columns at stair landing to remain.
- CMU at existing concrete stair to be parge coated.
- 7. Non-historic iron guardrail at balcony / stairs and iron roof posts at balcony to be replaced with new wood guardrail, handrail, and posts.
- 8. Missing door and window shutters to be replaced with new to match existing.9. Existing windows, doors, shutters to be repaired or replaced in kind to match existing.
- 10. Gutters and downspouts to be replaced. Fascia + Soffit to be repaired as necessary.

### 420 Bourbon



**VCC Architectural Committee** 



### Main Building + Rear Dependency

- 1. Non-compliant single concrete risers to be removed.
- 2. Non-historic interior concrete floor to be removed to original floor level.
- 3. Ground floors doors and shutters to be replaced with new elongated to match historic profiles in same locations. New doors will be single swing to meet current Code.
- 4. Speakers, non-historic lights, to be replaced.
- 5. Existing steel columns at stair landing to remain.
- CMU at existing concrete stair to be parge coated.
- 7. Non-historic iron guardrail at balcony / stairs and iron roof posts at balcony to be replaced with new wood guardrail, handrail, and posts.
- 8. Lattice screen and mechanical equipment to be demolished.
- 9. Non-historic door and transom infill to be removed (trim to be retained.) New glazed transom and new wood door to match existing profiles.
- 10. Existing mortar and masonry to be repaired, cleaned.





# 13

- View of existing stair and rear dependency west elevation.

  1. Repair or replace existing window to match historic profiles at existing 2nd floor dependency.
- Remove spalling stucco from existing historic masonry at rear depedency. Upper level side elevation of rear dependency to receive new stucco.
   Non-compliant metal handrail and gate at stair to be demolished; replace with
- compliant hand- and guardrail.







14

- East Facade of Rear Dependency Building

  1. Existing electrical panel, mechanical, conduit, utility piping to be removed.
- 2. Existing masonry and windows to be repaired.
- 3. Gutters and downspouts to be replaced.
- Non-historic iron guardrail and iron posts at second floor balcony to be removed.
   Non-compliant single riser concrete stair at ground floor to be removed.





- East Facade of Rear Dependency Building

  1. Structural settling of SE corner of rear dependency visible.

  2. Door opening to be reframed plumb for new elongated door and shutters.
- 3. Siding to remain as is.





### 16 Existing Rear Shed

- 1. Existing rear shed to be removed in it's entirety. New shed structure to be built within same footprint (to be reviewed by VCC.)
- 2. Existing electrical panel on Rear Dependency to be removed.
- 3. Mechanical, conduit, utility piping to be removed.








### 17 Existing Party Wall at Courtyard (view from rear shed)


- 1. Existing paving to be removed, site regraded for ADA, and new paving installed. Existing drainage channel to be retained.
- 2. Existing brick planting beds, plantings, to be removed.
- 3. Select areas of masonry to be repaired, repointed as required. Vegetation to be removed from masonry, and brick / mortar to be cleaned.
- 4. Existing wall sconces, exit light, and conduit to be removed.
- 5. Fountain to be removed.
- 6. Structural bracing to alleyway to be evaluated by structural engineer for removal or reconfiguration.
































































WEST OF THE STATE OF THE STATE




























VCC Architectural Committee

May 11, 2021









# 1 EXISTING WEST ELEV - DEPENDENCY 1/8" = 1'-0"






4 PROPOSED WEST ELEV - DEPENDENCY 1/8" = 1'-0"







5b PROPOSED SOUTH ELEV - SHED GATE 1/8" = 1'-0"








1/8" = 1'-0"




EXISTING ELEVATION - COURTYARD WALL 1/8" = 1'-0"













1 EXIST. TRANSVERSE SECTION - MAIN BLDG 1/8" = 1'-0"




1/8" = 1'-0"






2 EXIST LONG. SECTION - ALL BLDGS 1/8" = 1'-0"






2 EXIST LONG. SECTION - ALL BLDGS 1/8" = 1'-0"






1 EXISTING TRANSVERSE SECTION - DEPENDENCY 1/8" = 1'-0"






3 PROPOSED TRANSVERSE SECTION - DEPENDENCY 1/8" = 1'-0"





2 EXISTING TRANSVERSE SECTION - SHED 1/8" = 1'-0"



4 PROPOSED TRANSVERSE SECTION - SHED
1/8" = 1'-0"



## LIGHTING





**FURNISHINGS** 



BAR TRAILER

@ OUTDOOR COURTYARD AS SHOWN PER PLANS REQUIRES PLUMBING, DRAINAGE. + POWER



STAGE @ OUTDOOR COURTYARD, PORTABLE



**BOURBON ELEVATION** (4) SOFFIT RECESSED CANS CENTERED ON (4) DOOR OPENINGS



REAR DEPENDENCY (8) ELECTRIC LANTERNS CENTERED OVER DOORS, GROUND AND SECOND FLOOR



COURTYARD LED FROSTED BULB STRING LIGHTS



COURTYARD LED EDGE LIT CLEAR EXIT SIGNAGE



**PAVING** 

COURTYARD PAVING NATURAL CLEFT VARIEGATED BLUESTONE PAVERS



SPEAKERS @ COURTYARD



CAMERAS THROUGHOUT



@ COURTYARD

# **SIGNAGE**

CATEGORY SIGN ON BOURBON STREET LIMITED TO (1) 40.72 SQ.FT. SIGN

\*PROPOSED SIGNAGE TO BE DOUBLE FACED, ~20 SQ.FT. AREA EACH SIDE, ALL ALUMINUM CABINET W/ NEON, LEXAN FACES W/ LED. UL LABELED.

\*PROPOSED SIGNAGE TO BE PIPE SUSPENDED AT CENTER OF BUILDING FACADE.







April 30, 2021

Office of Business & External Services Vieux Carré Commission 1300 Perdido St, 7th Floor New Orleans, LA 70112 (504) 658-1420

Attn:

Bryan D. Block, Director bdblock@nola.gov

Erin B. Vogt, Senior Building Plans Examiner ebvogt@nola.gov

Tony B. Whitfield, Building Inspector abwhitfield@nola.gov

Subject: Structural Stability Recommendations

420-422 Bourbon Street - Rear Dependency Building

Permit Reference 43KJW1

To Whom It May Concern,

I, a representative of Batture LLC, visited the site on April 29, 2021 to assess the brick masonry condition at a settled corner in a historic structure at the address located above. The structure is a 2-story masonry structure with wood infill framing. A downspout is located at the settlement location. Based on the condition of the interior side of the masonry, the area has been tuckpointed. No large settlement cracks are present, which indicates no new settlement has occurred. We would recommend the masonry at the corner to remain as is in lieu of repair. The stormwater at the downspout exit should be redirected away from the foundation. The interior of the masonry wall should be further tuckpointed to fill all exposed mortar joints.

I hope this letter adequately relates our findings related to the specific items listed. Please bear in mind that it is based upon investigations consisting only of visual observations of those features of the structure that were exposed and accessible. Neither my investigation nor this letter should be considered to warrant or guarantee the structure or its components. Future investigation, observations, or occurrences may reveal other conditions of note or may indicate changes in the conditions mentioned above.

5110 FRERET ST., NEW ORLEANS, LA 70115

PH.504.533.8644





Subject: Structural Stability Recommendations

420-422 Bourbon Street - Rear Dependency Building

Permit Reference 43KJW1

To Whom It May Concern,

I, a representative of Batture LLC, visited the site on April 29, 2021 to assess the brick masonry condition at a settled corner in a historic structure at the address located above. The structure is a 2-story masonry structure with wood infill framing. A downspout is located at the settlement location. Based on the condition of the interior side of the masonry, the area has been tuckpointed. No large settlement cracks are present, which indicates no new settlement has occurred. We would recommend the masonry at the corner to remain as is in lieu of repair. The stormwater at the downspout exit should be redirected away from the foundation. The interior of the masonry wall should be further tuckpointed to fill all exposed mortar joints.

I hope this letter adequately relates our findings related to the specific items listed. Please bear in mind that it is based upon investigations consisting only of visual observations of those features of the structure that were exposed and accessible. Neither my investigation nor this letter should be considered to warrant or guarantee the structure or its components. Future investigation, observations, or occurrences may reveal other conditions of note or may indicate changes in the conditions mentioned above.

If you have any questions, please contact the undersigned at (504) 533-8644 at your convenience.

Thank You,

BATTURE, LLC

Mary Schambeau Johnson, PE Structural Design Manager

420 Bourbon

Enclosures: Photos





Photo 1: View of Settled Corner





Photo 2: Interior View of Settled Corner






Photo 3: View of Settled Corner
























































627 Bourbon






627 Bourbon – Flat Roof







627 Bourbon – 2014 – Before AC Rack



