Vieux Carré Commission Meeting

Wednesday, June 17, 2020








WHAT THIS MEANS FOR NEW ORLEANS

The FCC has granted certain rights to carriers and infrastructure providers allowing them the right to install small cells in your Public ROW. If you don't get ahead of the problem and put into place the designs necessary to mitigate what these installs look like you could find yourself with an onslaught of poles that actively degrade your ROW's aesthetic.



PREVIOUS FRENCH QUARTER SMALL CELL PROPOSAL





Each orange square represents one (1) linear foot.

CURRENT FRENCH QUARTER SMALL CELL PROPOSAL






BEFORE

AFTER


4G OR 5G GAS LAMP SMALL CELL COLOCATION DESIGN



POLE SIZE COMPARISONS




Each orange square represents one (1) linear foot.




20' PROPOSED SMALL CELI

Each orange square represents one (1) linear foot.



































































626 Bourbon




















Appeals & Violations













VCC Architectural Committee







January 10, 2017














January 10, 2017



VCC Architectural Committee






January 10, 2017







January 10, 2017





2 Dumaine St. Entrance - Revised Gallery Details Key


1/2" = 1'-0"

KEYNOTES: existing masonry wall existing metal gate - to remain existing metal column - to be repaired, paint removed & if required, metal prepped for repainting, same color Farrow & Ball Railings' No. 31 [same as outriggers] existing wood trim - replace all existing wood unit - reproce an existing metal outriger - remove up to 8" from masonry wall existing wood & glass entry door new wood trim at entry to rectify existing condition wood casing - match existing in profile & dimensions wood casing - match existing in promie a dimensions existing wood blocking remove existing crown moulding remove extension of gallery fascia - move col. capital up repair capitals in kind, as needed at all column locations - for missing column capital, new to match existing in profile, dimensions 8 matchiel. dimensions & material dimensions & material repair wood paneling in kind, as needed replace T&G wood gallery floor w/ Aeratis Traditions, prime and paint to match existing trim color [BM 'Super White'] and paint to match existing trim color BM 'Super White'] 15. existing wood stringer - remove [to replace w/ new profile as existing wood joist w/ flooring above - to remain existing upright steel bar balcony support [encased in wood] to be removed new 3"x4" beaded wood purlin [stringer], details per VCC Sheet No. 12; 16" max o.c. per Aeratis manufacturer new wood fascia, painted to match exst. trim color [BM 'Super White']

20. remove flat steel plate above column capital
21. existing metal outrigger, projecting approx. 8' from masonry
wall. When new outrigger i[welded to provide even, sloped
platform for new decking] causes locations where the
corners of the cut existing outrigger skewed from the profile
of the new, the exst. outrigger will be grinded down to
remove as much projecting materials from the profile as
possible without compromising structural integrity
21. new metal outriggers to be welded onto exst outrigger
projections, overlapped to allow for strong welded adhesion,
all metal outrigger components painted Farrow&Ball
Railings' No. 31 (match columns)
23. wood blocking within encasement as req'd
24. new steel C-channel, gallery perimeter [encased in wood
trim as shown]







536 Dumaine

536 DUMAINE STREET - GALLERY + WOOD TRIM DETAILING VCC APPLICATION . 04 JUNE 2019 ***REVISED 21 MAY 2020***