

# Vieux Carré Commission Architecture Committee Meeting

Tuesday, August 22nd, 2023













235-41 Bourbon - 1963



235-41 Bourbon - 1965































February 28, 2023





















235-41 Bourbon



February 28, 2023
























VCC Architecture Committee











235-41 Bourbon

























REF. A1.25, A7.1





239 - 241 BOURBON ST. VCC REVIEW | OCT 2022





### ARCHITECT

# WILLIAMS ARCHITECTS Copyright © 2022 John C Williams Architects LLC

824 BARONNE STREET NEW ORLEANS, LA 70113 504-566-0888

SAM LEVISON AIA, NCARB, LEED AP BD+C: PROJECT ARCHITECT SLEVISON@WILLIAMSARCHITECTS.COM

#### STRUCTURAL

PACE GROUP, LLC

400 SOUTH NORMAN C. FRANCIS PKWY NEW ORLEANS, LA 70119 504-206-3834

# WDG ENGINEERS Copyright © 2022

821 BARONNE ST NEW ORLEANS, LA 70113 504-754-5272

KENT A. POYSER, P.E. KAPOYSER@WDGNOLA.COM



PERMIT SET

235, 237, 239, 241 Bourbon St, New Orleans, LA 70112

COVER SHEET

1.1





241 Bourbon St.

From Nick's notes: responses in blue

The ramp has been externalized where previously the ramps had been on the interior sides of the doors to both the rentals and the bar. This change would likely need to return to the Committee. The raised sidewalk has been approved per BBSA, Fire Marshal, and is to be in front of the Encroachments Working Group (EWG) 8/9/23.

One of the doors to the bar (100D) was previously in-swinging French doors but is now shown as an out-swinging single leaf door


The door is an egress door per Fire Marshal and BBSA.

Exterior sprinklers are now shown at the second and third floor on the Bienville side of the building. Likely need some more details on these

These would be dry pipe sprinklers with a cut sheet to be given to VCC and Fire Marshal prior to installation. They will likely be a version of Viking exterior sprinkler heads.

The 2hr rated exhaust shaft running up from the ground floor kitchen – looks like this was previously included but not sure it was noticed or discussed. Would it be possible to shift it over so it is not shortening the balcony at the third floor level? No, there are three different ducts running vertical that would need to be enclosed within the shaft so to not be exposed to the interior courtyard.





We previously wanted to see some revisions to the 104A door and am seeing those and agree it looks more appropriate as now proposed.

The railing extension seen on 5.3. Is that just the existing one redrawn or is that some kind of new/modified extension? N/A existing guardrail per code guardrail height 42".


There were some questions regarding the previously submitted structural work. Here is the section from my last report:

# "Structural Plans

On sheet S201 (page 47), there is a detail showing a typical balcony support. The detail shows the addition of a new L shaped metal brace at each existing balcony support. It appears that the new metal brace is proposed to be welded to every outrigger of the balcony. Staff finds that this proposed work would make a major impact on the appearance of the underside of the balcony and would be highly inappropriate. Staff seeks clarity on this proposed detail and recommends that more traditional methods be used to reinforce the balcony if needed. Instead of an 'L' plate, new flat plate balcony support plates will be added to existing balcony supports, needed for 100 PSI per weight/usage.

Two tie back details are also seen on this same sheet. One detail appears to be completely on the interior of the building while the other shows an exterior 10" x 10" plate. These tie back plates are not shown on the elevation and it is unclear how many are being proposed and their exact location. If exterior tie backs are proposed, staff notes that the Committee has established a preference for circular, rather than square tie back plates." There will be 4 circular 10" plates seen on \$102/\$103.

# 235-41 Bourbon
















RELATIVE OREINTATION & NAMES OF BASIC FIRE SPRINKLERS WITH REQUIRED ESCUTCHEONS




	1001	4 /3/1	INFORMATION - JOB#:	3407200	_	-	_	_	_		_				_		_			_
AN NIT ND	TAG	QTY	FAN UNIT MODEL #	MANUFACTUR	ER CFM	ESF	RPM		TOR ICL	HP	BHP	PHASE	VOLT	FLA		CHARG		(LBS)	SONE	S
1		1	EADU240H	ECON-AIR	5162	2.25	0 1099	DDP,P	REMIUM	5.000	3.8270	3	208	15.8	117	3 FPI	м	307	25	
UA	FAN	INFO	RMATION - JOB#54572	208				,,,,											777	
AN NIT	TAG	QTY	FAN UNIT MODEL #	BLOWER	HOUSING	MIN CFM	DESIGN CFM	ESP	RPM		TDR NCL	HP	BHP	PHASE	VOLT	FLA	MCA	MOCP	WEIGHT (LBS)	SONES
5		1	ETA3-24D	24MF-3-MDD	INLINE.3	3000	4130	0.750	1013	DDP,P	REMIUM	3.000	1.9820	3	208	10.2	12.8A	20A	506	7.7

FAN	OPTI	ONS	
FAN UNIT NO	TAG	QTY	DESCRIPTION
		-1	GREASE BOX
1		1	2 YEAR PARTS WARRANTY
2		1	INLINE3 INDOOR HANGING OPTION - INCLUDES 2 HSA200 HANGING SPRING ISOLATORS PER UNI-STRUT
		1	2 YEAR PARTS WARRANTY

		1 - 1-	TEME PA	IKIZ W	MKKMIVIT						
FAN		SSORI	ES EXHAUST		SUPPLY						
UNIT NO	TAG	GREASE CUP			SIDE DISCHARGE		MOTORIZED DAMPER	WALL			
1		YES									

NO	FAN	WEIGHT	ITEM	SIZE
.1	# 1	48 LBS	CURB	31.500°W X 31.500°L X 20.000°H ALDNG LENGTH, RIGHT VENTED HINGE

#### FAN #1 EADU240H - EXHAUST FAN



## FEATURES:

- TENTUNCAS:

   BIRCT BRIVE CINSTRUCTION OND BELTS/PULLEYS).

   ROOF MOUNTED FANS.

   RESTAIRANT MOBEL.

   UL705 AND UL762 AND UL7-5645

   VARIABLE SPECE CONTROL.

   INTERNAL VIRING.

   INTERNAL VIRING.

   THERMAL DYBRIGATION SOFT (149°C).

   HIGH HEAT DEPEATION 300°F (149°C).

   REGASE CLASSITICATION TESTING.


   NEMA 3R SAFETY DISCONNECT SVITCH.


NORMAL TEMPERATURE TEST
EXHAUST FAN MUST DEPRATE CONTINUOUSLY
WHILE EXHAUSTING AIR AT 300° C49°C)
UNTIL ALL FAN PARTS HAVE REACHED
UNTIL ALL FAN PARTS HAVE REACHED
EXHIBITION OF THE FAIL AND HE FAIL


ABRORMAL FLARE-UP TEST EXHAUST FAN MUST DPERATE CONTINUOUSLY WHILE EXHAUSTING BURNING GREASE VAPORS AT 600°F (3)6°C) FOR A PERIOD OF IS MINUTES WITHOUT THE FAN BECOMING DAMAGED TO ANY EXPENT THAT COULD CAUSE AN UNSAFE CONDITION.

## OPTIONS

GREASE BOX. 2 YEAR PARTS WARRANTY.

































VCC Architectural Committee















VCC Architectural Committee

August 22, 2023



841 Royal






841 Royal























837 & 841 Royal, 1987






















































## 913 Governor Nicholls/ 1215 Dauphine























907-17 Governor Nicholls – 1963


















907-17 Governor Nicholls – c. 1950s/60s









907-17 Governor Nicholls



907-17 Governor Nicholls




1211-15 Dauphine















907-17 Governor Nicholls

































































913 Governor Nicholls, 1215 Dauphine
















































































913 Governor Nicholls, 1215 Dauphine

























































































Principal Historic Preservation Plans Examiner Vieux Carre commission Office of Business & External Services ebvogt@nola.gov

RE: 913 Gov Nicholls VCC Violation Letter Scope of work Timeline

Erin,

Below is a summary of the violations listed on the 7/27/2023 Notice of Violations letter our office received regarding the existing building at 913 Gov Nicholls Street. The letter below outlines the proposed timeline to correct these violations as part of the proposed repair permit and new construction permits for this

Gallery Renovation without Permits-Columns/Post-Balconies/Galleries:

 This will be addressed through the drawings provided int his permit covering repairs conducted on the building without a permit and additional repairs needed based on current conditions.

Fence/Gate - Chain link Fence Without Permits

 Chain link fence has been in existence for many years, current proposed New Construction permit will replace the existing non-compliant chain link fence with a new masonry and cast iron picket fence. This work will be covered under the separate New construction permit for the lot.

Gutters/Downspouts – Gutters not installed as permitted

· Gutter downspouts will be temporarily repaired with aluminum downspout extensions to assist in removing water from foundations, Full replacement of matching in kind downspouts will be conducted in the Full new construction permit.

Trim - Gallery Trim Altered Without permits

 This permit will cover work performed on the gallery trim replacement without permits previously. It also will cover current work to address rotten trim and wood components at the gallery under new work to address this item.

Paint - Gallery Painted without Permits

· This permit will cover additional repairs to the gallery and those repairs will necessitate prime and painting of existing a new wood components to be done with issuance of this repair permit.

 Seek retainment of existing security cameras until new construction work is completed. Additional request will be provided to install permanent security cameras in conjunction with completed new construction work on site.

Lighting - Flood Lights without permits-Wires/conduits

 Seek to paint existing exposed conduit and to retain existing flood lights due to continued security issues at site. Flood lights will be removed once final new construction work is completed and lighting from new construction can help provide site security to rear lot.

Sealant – Bondo on Gallery column w/o Permits

· Bondo at column bases will be removed under work performed with this permit for column repair/splice detail.

Security Bars at rear of structure

Security Bars at rear of structure will be removed under this scope of work.

· Request to ease/remove this item with repairs conducted to gallery under this permit scope of

Hazardous Conditions/Foundation - Listing Gallery Pier

· Request to measure/document gallery pier over the course of several months to determine if active settling is occurring or if gallery pier is remaining in place.

Walls - Weatherboard damage

Weatherboards to be repaired under this scope of work at rear of building

WILLIAMS ARCHITECTS

824 Baronne Street New Orleans, LA 70113 (o) 504.566.0888 williamsarchitects.com

Brick - Deterioration on brick wall on barracks elevation/Deterioration of Stucco

 Brick fence wall at rear of site will be demoed as part of new construction permit for new masonry fence at existing citation location. This item will be handled during new construction permit work/phase.

Floors - Deterioration of porch decking

. Repairs will be conducted under this permit to existing gallery T&G decking to replace with new in kind materials where damaged components existing and are not repairable.

Steps/Stoops - deterioration of front steps

Repairs to be handled under this permit.

Paint

Repairs to any painted areas will be handled under this permit for any repairs, replacement materials covered.

Vegetation

· Removal of all vegetation materials/growth will be performed under this permit


We appreciate your review of these items and our proposals to address the cited violations. Please let us know at your earliest convenience if you have any additional questions on the proposed solutions we have outlined in this letter per your most recent review.

Please reach us at anytime at (504) 566-0888

Regards,


John C Williams Principal & Owner Williams Architects

WILLIAMS ARCHITECTS 824 Baronne Street New Orleans, LA 70113 (a) 504 566 0888 williamsarchitects.com




913 Governor Nicholls, 1215 Dauphine






913 Governor Nicholls, 1215 Dauphine






## 913 Governor Nicholls, 1215 Dauphine






## 913 Governor Nicholls, 1215 Dauphine






913 Governor Nicholls, 1215 Dauphine





913 Governor Nicholls, 1215 Dauphine







030



