Vieux Carré Commission Meeting


Wednesday, July 20, 2022



















440 Bourbon






THE COMMON TO TH
































440 Bourbon





440 Bourbon













440 Bourbon – 1876 Sanborn








440 Bourbon – 1896 Sanborn








LUBRI CATING OILS

440 Bourbon – 1908 Sanborn




440 Bourbon – 1940 Sanborn





440 Bourbon – first floor



440 Bourbon – entresol level




440 Bourbon – entresol level



440 Bourbon



440 Bourbon



440 Bourbon











440 Bourbon





440 Bourbon





440 Bourbon – third floor



440 Bourbon – third floor

PLISHED 3



440 Bourbon – third floor, courtyard side

PARE COMPANY OF THE PARE C



440 Bourbon – third floor




440 Bourbon – third floor, courtyard side

THE COMMON TO TH

July 20, 2022

Vieux Carré Commission



440 Bourbon



440 Bourbon








440 Bourbon









800 N. Rampart






800 N. Rampart














800 N. Rampart – 1863 plan book










800 N. Rampart - 1876





800 N. Rampart - 1885





800 N. Rampart - 1896





800 N. Rampart



800 N. Rampart





800 N. Rampart



800 N. Rampart





800 N. Rampart





800 N. Rampart – 9/2021





800 N. Rampart – 9/2021





800 N. Rampart – 9/2021





800 N. Rampart – 06/2022





800 N. Rampart – 06/2022



MAINTENANCE AGREEMENT AND GALLERY CONSENT

J&R Rental Properties, L.L.C., Half James Properties, L.L.C., Michelle Cahn Wolfson Trust, James Lenard Cahn Trust, and Richard M. Cahn Trust (collectively, "Owner") and the Sewerage and Water Board of New Orleans ("Board") hereby enter into this Maintenance Agreement and Gallery Consent (this "Agreement") under the terms described herein.

WHEREAS, Owner is the owner of the real property located at municipal address 800 N. Rampart Street, New Orleans, LA 70116, Lot 1, Square 103, in the Second Municipal District, City of New Orleans, Louisiana (the "Property");

WHEREAS, the Board has certain water and/or sewer lines (the "Board Lines") under the public right of way sidewalk adjacent to the Property, which said Board Lines are subject to a servitude in favor of Board (the "Servitude");

WHEREAS, Owner desires to renovate the existing, historic structure located upon the Property including the addition of a gallery (the "Gallery") to be attached to the structure, extending over and above the public right of way sidewalk and the Board Lines and Servitude, at a height of approximately twelve feet eight inches (12'8") above the adjacent sidewalk, including over the Board Lines and Servitude, which Gallery is planned by Owner to be constructed at 12'8" generally according to plans (the "Plans") as attached hereto as Exhibit "A"; and

WHEREAS, Board has objected to the addition of the Gallery above and over the Lines and Servitude because it needs the Servitude for access to its Lines and related facilities to maintain water and sewer services, for work to be done and performed by Board, its employees, the City of New Orleans or its employees, their respective officials, agents (including contractors and subcontractors) acting within the scope of their authority; and

WHEREAS, Owner recognizes and is willing to assume and indemnify Board for the risks and complexities due to the addition of the Gallery over and above the Board Lines and the Servitude:

NOW THEREFORE, the parties agree as follows:

- The Board withdraws its objection to the construction of the Gallery over the Board Lines and Servitude at a height of twelve feet eight inches (12'8") generally in accord with the Plans attached as Exhibit A.
- 2. Owner acknowledges that damage to or removal of the Gallery may be necessary to the performance of such Board work and Owner agrees that, so long as the Board Lines and/or Servitude exists beneath the Gallery, Owner, to the fullest extent permitted by law, shall indemnify and hold harmless the Board, its employees, officials, agents (including contractors and subcontractors) acting within the scope of their authority, and the Board's assigns (collectively, the "Indemnified Parties") for any damages to, including the removal of, the Gallery caused by the Board, its employees, officials, contractors, subcontractors or agents in the maintenance, servicing, or replacement of the Board Lines, provided the Board, its contractors, and agents exercise reasonable and standard care and are not negligent in causing such damage.

Maintenance Agreement – 800 N. Rampart Gallery 3/3/2022

- 3. Owner agrees that, so long as the Board Lines and/or Servitude exists beneath the Gallery, Owner, to the fullest extent permitted by law, shall indemnify and hold harmless the Indemnified Parties from and against any and all claims, suits, damages, losses, costs, demands, judgments, and liabilities accrued against the Indemnified Parties, for any and all liability arising from or relating to any act or omission of the Owner, its employees, officials, or agents (including contractors and subcontractors) acting within the scope of their authority while the Owner is engaged in, or in connection with the discharge or performance of, any work or other activity that has an effect on the Board's Lines and/or Servitude; and for any and all claims and/or liens for labor, services, or materials furnished to the Owner in connection with performance of work that has an effect on the Board's Line, including but not limited to damages, losses, claims, costs, demands, and judgments of sums of money suffered or incurred by any or all of the Indemnified Parties, specifically including without limitation, all reasonable attorney's fees and related costs...
- 4. Except in the case of emergency, Board agrees to provide written notice to Owner to the address and contact on record for Board billing of the Property no less than thirty (30) days prior to any maintenance, servicing, or replacement of the Board Lines that may damage, cause the removal of, or otherwise impact the Gallery. Upon receipt of such notice, Owner shall have the opportunity to fully or partially remove, fortify, or otherwise prepare the Gallery for the work planned by Board, within such thirty (30) day period.
- 5. The Owner has an immediate and independent obligation, at the Board's option, to: (a) defend the Board from and/or (b) reimburse the Board for its costs (including but not limited to reasonable attorney fees and related costs) incurred in the assertion or defense of any claim that actually falls within this indemnity (even if the allegations are, or may be groundless or the Owner is ultimately absolved from liability in whole or in part).
- 6. The indemnity provided herein does not extend to the extent of any claims, suits, damages, losses, costs, demands, judgments, and liabilities arising from or relating to the gross negligence or willful misconduct by any of the Indemnified Parties.
- All covenants, stipulations, terms, conditions, and provisions of this Agreement shall extend to and are binding upon the respective successors and assigns of the Appearer and the Board.


[THE REMAINDER OF THIS PAGE IS INTENTIONALLY LEFT BLANK]

[SIGNATURES CONTAINED ON THE NEXT PAGE]





8. This agreement shall run successors. Owner shall record this Agreeme records of Orleans Parish.	nt timely upon its execution in the official land
Executed before the undersigned notary Orleans, Louisiana on the 24+ day	and the undersigned competent witnesses in New y of, 2022.
J&R RENTAL PROPERTIES, L.L.C., HALF JAMES PROPERTIES, L.L.C., MICHELLE CAHN WOLFSON TRUST, JAMES LENARD CAHN TRUST, AND	WITNESSES:
BY: JAMES LENARD CAHN	SIGN: Mm h Andrews PRINT NAME: Michael & Shemur
AS AUTHORIZED SIGNATORY OF EACH	H SIGN: Shella tally PRINT NAME: Shella tahyildari
Miles L. Granderson Orleans Parish, Louisiana Notary Public Commission No. 148722 My Commission Expires at death	Y PUBLIC
	in New Orleans, Louisiana on the day
SEWERAGE & WATER BOARD OF NEW ORLEANS	WITNESSES:
BY:	SIGN:
GHASSAN KORBAN	PRINT NAME:
ITS: EXECUTIVE DIRECTOR	
	SIGN:
	PRINT NAME:
FORM AND LEGALITY APPROVED: Legal Department BY:	
YOLANDA Y. GRINSTEAD, SPECIAL CO	DUNSEL
NOTAR	RY PUBLIC



FOOD PREF

203

205

206

RESINOUS EPOXY

POLISHED CONC.

POLISHED CONC

RUBBER TILE

MOOD

MOOD

MOOD

PTD. GYP. BOARD

CERAMIC TILE

CERAMIC TILE

CERAMIC TILE

HEAD JAMB SILL

1/A34 5/A33 2/A34 SEE ELEVATION 1/A33

5/A3.4 6/A3.5 4/A3.4 SEE ELEVATION 2/A3.5

5/A3.4 9/A3.5 6/A3.4 SEE ELEVATION 4/A3.5

EXIST, 4'-2" X I'-T' FIXED TRANSOM SEE ELEVATIONS 104

1/2 HR. FIRE RATED, HOLD OPEN DEVICE ACTIVATED BY FIRE AL

THE SIGNING OF THIS PLAN BY AN ENGINEER OF THE SEWERAGE AND WATER BOARD SIGNIFIES THAT IT HAS BEEN REVIEWED FOR GENERAL COMPLIANCE WITH THE BOARD'S MINIMUN ACCEPTED STANDARDS AND SHALL NOT BE CONSTRUED AS A WARRANTY OF THIS AND THE ACCOMPANYING PLANS AND SPECIFICATIONS.

IT DOES NOT RELIEVE THE DEVELOPER OF THE RESPONSIBILITY FOR ERRORS, DISCREPANCIES, OMISSIONS, ELEVATIONS, OBSTRUCTIONS, OR OTHER REQUIREMENTS OF A COMPLETE AND WORKABLE DESIGN, NOR DOES IT PROBBIT THE BOARD FROM HAVING THE DEVELOPER MAKE FURTHER MODIFICATIONS TO THE PLANS OR AND JUSTMENTS IN THE FIELD DURING CONSTRUCTION.

SIGNED 9

FOR GENERAL SUPERINTENDENT

DATE \$ 7/97/2622

JOHN C WILLIAMS

ART STREET RLEANS, LA

800 N. Rampart

3'-5 1/2" x 8'-0" x 1 3/4"

103 PR, I'-10" x 8'-0" x 1 3/4"

105 PR, I'-10" x 8'-0" x 1 3/4"

108 2'-0" x 8'-0" x 1 3/4"

3'-6" x 8'-0" x 1 3/4"

3'-0" x 8'-0" x 1 3/8"

205 3'-0" x 8'-0" x 1 3/8"

206 3'-0" x 8'-0" x | 3/8" 207 3'-0" x 8'-0" x | 3/8"

104 PR. 2'-1" x T'-0" x 1 3/4"

Vieux Carré Commission

EXT. 8 LIGHT/2 PANEL RAIL & STILE WOOD DOOR

INT. FLUSH WOOD SOLID CORE DOOR

INT FLUSH WOOD SOLID CORE DOOR

INT, FLUSH WOOD SOLID CORE DOOR INT, FLUSH WOOD SOLID CORE DOOR

INT. FLUSH WOOD SOLID CORE DOOR


INT FLISH WOOD SOLID CORE DOOR W/ VISION PANEL. H. M.

H.M.

H.M.

MOOD






800 N. Rampart









800 N. Rampart













800 N. Rampart












800 N. Rampart














TABLESHED ST



Page 70 of 137 DRAWING RAMPART STREET ELEVATION

- BASE PLATE (SEE DETAIL A/S1.1) - ANCHOR ROD (SEE DETAIL B/S1.1) 1" NON-SHRINK GROUT

PLAN NOTES: 1. FOR ALL NOTES, SEE DRAWINGS \$1.0A - \$1.0B. SYMBOL ON PLAN INDICATES HSS 3x3x1/4" COLUMN.

PRIOR TO CONSTRUCTION, CONTRACTOR TO FILED VERIFY THAT ALL FOUNDATIONS WILL FIT WHERE SHOWN. IF THERE ARE ANY OBSTRUCTIONS, NOTIFY ENGINEER OF RECORD.

1 1/2" (TYP.)

NOTE:

BASE PLATE ANCHOR ROD SCHEDULE

1 1/4

1 1/2

1 3/4

2 1/2

5/16

8'-3 1/2"

FOUNDATION PLAN

1 1/2" CLEAR (TYP.)

HSS COLUMN TO PL


7'-0 1/2"

HEAVY HEX NUT

3/4"¢ ANCHOR ROD


ENGINEER: JAMES B HEASLIP AE PROJECT #:21045 LICENSE NUMBER: 31593


DRAWING BY SCALE JOB No. DATE S1.1



800 N. Rampart











June 27, 2022

City of New Orleans Department of Safety & Permits 1300 Perdido St., Room 7E06 New Orleans, LA 70112

Reference: 800 N Rampart St.

New Orleans, La

On March 15, 2021, this office submitted structural drawings for a gallery addition to an existing building located at the above reference address to Williams Architects. During the plan review stage one structural issues arose concerning the structural integrity of the building and the ability of the building to withstand the added dead and live loading of the gallery.

The issue concerning the building was as follows, 'Extensive time has gone by since initial review, and it has been known that structural repairs will be needed on the N. Rampart masonry wall. Meanwhile, the building has continued to deteriorate due to continuing demolition by neglect. In light of these facts, VCC staff is requesting an updated engineer's report based on a recent inspection confirming that the building can carry the necessary dead and live loads for a gallery.' The new structure was designed with auger cast-in-place concrete piles to support the added 3-inch steel columns and steel plate joists and wood decking similar to typical New Orleans type galleries. Past photos show the building had a gallery at one time therefore the building is able to support the added dead and live loading of the gallery. We originally inspected the building in 2020 and re-inspected the building on Friday June 24, 2022 after the request by Mr. John Williams. The building is structurally sounds as a whole, during construction all damaged or deteriorated wood framing shall be replaced in-kind and all masonry walls tuck pointed as needed to restore the original structural integrity of the building. This office is to be contacted as needed during construction to ensure all repairs are performed as per all city and state building codes.

All new construction was designed in compliance with the 2015 International Building Code, ACI 318-05 Building Code Requirements for Structural Concrete and ASCE 7-10 Minimum Design Loads for Buildings and Other Structures.


Sincerely,

James B. Heaslip II, P.E.

















800 N. Rampart











800 N. Rampart – 06/2022









1222 Decatur











1222 Decatur










1222 Decatur

THE COMMON TO TH





Facade length 26'

WINDLOAD: 140 mph

Signage shall meet requirements of 2015 IBC Appendix H and related chapters.

Signage shall meet requirements of ASCE 7.

These plans and specications have been prepared by or under close personal supervision and, to the best of my knowledge and belief, they comply with all city requirements, and that I am not generally administering the work.



for it purpose the parties solely to the

fabrication processes or to the means,

methods, techniques, sequences and

occdures of construction, and for

coordination of the Work of all trades.

PROJECT MANAGER: Danil Khutorianskii

2545 Banks St., New Orleans, LA 7019 504-434-5543 /// notasignshop «gmall.com www.notasignshop.com

acrylic

·HDU

COMPANY: Tru Barber Tattoo

NAME: Doe Williams

EMAIL: doryon60@gmail.com

PHONE NUMBER: (985) 855-3044

PRODUCT: Double-sided sign

MATERIALS: HDU MOUNT: Hardware

REVISION LOG: 04.25.2022













Appeals and Violations





815 St. Ann





815 St. Ann






815 St. Ann





815 St. Ann - 1974

ALISHED STATES









815 St. Ann





















815 St. Ann






815 St. Ann – 1st Floor Interior












815 St. Ann – 1st Floor Interior






815 St. Ann – 1st Floor Interior






815 St. Ann – 1st Floor Interior







815 St. Ann – 1st Floor Interior


CARRE COMMO















815 St. Ann – 1st Floor Interior

TAMESHED ST



815 St. Ann – 1st Floor Interior





815 St. Ann – 1st Floor Interior





815 St. Ann – 1st Floor Interior







815 St. Ann – 1st Floor Interior









815 St. Ann – 1st Floor Interior





815 St. Ann – 1st Floor Interior






815 St. Ann – 1st Floor Interior





815 St. Ann – 1st Floor Interior





815 St. Ann – 2nd Floor Interior





815 St. Ann – 2nd Floor Interior






815 St. Ann – 2nd Floor Interior







815 St. Ann – 2nd Floor Interior

TAPLISHED **








815 St. Ann – 2nd Floor Exterior






815 St. Ann – 2nd Floor Exterior





815 St. Ann – 2nd Floor Exterior





815 St. Ann – 2nd Floor Exterior













Established 1840 PHONE 504-488-2671 * FAX 504-482-2862 3319 ORLEANS AVENUE * P.O. BOX 19737 NEW ORLEANS, LA 70179-0737

www.abrybrothers.com
LA CONTRACTORS LICENSE NO. 26319

May 18, 2021

William Wolf Yazoo Restorations, LLC 7611 Maple St New Orleans, LA 70118

An initial inspection was conducted at:

815 St. Ann Street NOLA 70116

As per your request, a visual inspection was conducted at the above address. The purpose of the inspection was to develop a cost estimate for structural shoring at the site.

We are pleased to quote a cost range of \$65,000.00 to \$68,000.00.

The price is based on the following scope of work:

- Shoring the interior framing from the ground up to the roof, the balcony and the balcony roof to allow removal of the front masonry wall. The removal is to be done by others.
- Installing a new foundation under the removed wall.

The quote **does not include** the demo or removal of the wall or any finishes that need to be replaced. It **does not include** rebuilding of the wall.

If you should require further information and/or a contract to make the necessary repairs, please let us know.


Thank you for contacting **ABRY BROTHERS**, **INC.** for your raising/shoring/leveling requirements.

Sincerely,

815 St. Ann







July 20, 2022 Vieux Carré Commission

815 St. Ann


Page 130 of 137

AKOFSKY I œ 0

815 ST ANN ST MASONRY WALL REPAIRS NEW ORLEANS, LA 70130


JLS DATE 08-18-21 ISSUE JOB NO. 20167 SHEET

S1.1



Vieux Carré Commission

July 20, 2022



Vieux Carré Commission

July 20, 2022

MORPHY, MAKOFSKY, INC.

CONSULTING ENGINEERS 336 N. Norman C. Francis Parkway New Orleans, LA 70119 P:504/488-1317 F:504/488-0924 www.mmi-eng.com Jamie L. Saxon Jonathan A. Sofranko H. Stephan Bernick

June 27, 2022

John Williams Williams Architects 824 Baronne Street New Orleans, LA 70113

RE: 815 St Ann Street New Orleans, La.

Dear Mr. Williams.

We are writing this is letter to explain that the front façade wall will need to be rebuilt. The existing building is two stories tall with wood framing at the 1st, 2nd and roof levels. The exterior walls are multiwythe, load bearing, clay masonry brick walls. The front of the building abuts onto St. Ann Street. The floor joists appear to span in the direction parallel with the street.

At the time of our inspection, Tuesday, October 27, 2020, we could see displacement of the front façade wall and cracking in the masonry wall. The footing was damaged due to the ongoing construction. See attached photos. The lower section of the wall has the outer wythe of masonry tilting outwards, the inner wythes tilt inwards and the masonry towards the Dauphine Street side has cracked and begun to separate. The front wall has actually buckled which occurred when the footing under the front wall was undermined and likely rotated. Above the second floor we can also see significant horizontal movement across the wall resulting in large cracks above and adjacent to the windows. In addition, the front wall is separating from the side and central walls.

In consideration that the lower half of the wall needs to be removed to allow for the total replacement of the footing and rebuilding of the lower section of the wall. To shore the front wall needle beams need to be placed thru the wall above the windows of the first level. This will remove a significant portion of the wall. All the masonry below these needle beam will need to be replaced as it has suffered damage and the wythes have separated. The upper wall also has significant issues. The sections at each end have significant cracks above the second level windows and thru the outer jambs each side. These sections of masonry have moved outwards. These sections cannot be safely shored and need to be rebuilt. See attached elevation with notes.

When considering that wall sections are removed to allow for needle beam installation, the lower half of the wall below the needle beams has to be rebuilt, the two outer masonry piers at the second level and corresponding section of masonry above this outer windows will also be replaced, then only the upper interior piers and masonry above the two second level windows is left in place. This is an insignificant portion of the wall that would remain. Also the shoring for this small section would be above the area of footing and wall replacement, making it a very dangerous area to work.



In view of this extent of work, the entire front façade will need to be removed and rebuilt. This also provides the safest means of restoration of the front façade when you consider that this wall is on the property line and close to a very busy part of the French Quarter.

Morphy Makofsky, Inc.

Yours truly

Jamie Saxon, P.E







Photo 1: DAMAGED FOOTING



Photo 2: DAMAGED/MISSING FOOTING.



Photo 3: DAMAGED/MISSING FOOTING



Photo 4: DAMAGED FOOTING.





Photo 5: CLOSE UP OF DAMAGED BRICK OF FORMER FOOTING.



Photo 6: CLOSE UP OF DMAGED BRICK IN FORMER FOOTING.



Photo 7: CLOSE UP OF DAMAGED AND DISPLACED BRCIK IN FOOTING.







