
Vieux Carré Commission Architecture Committee Meeting

Tuesday, February 9, 2021







501 Decatur






501 Decatur



































February 9, 2021



DECATUR STREET DOWNRIVER EDGE
NO DOWNSPOUT. BIRDS
MOUTH SCUPPERS AT END,
MIDDLE, AND AT CENTER OF
RADIUS AT CORNER



REWORK DOWNSPOUT
TO BE OUTSIDE OF
BALCONY

OPTIONAL LEADER
FROM GUTTER TO
DOWNSPOUT HEADER
/ COLLECTOR

If Option 1 is used (birds mouth scuppers), this header collector can be deleted, as well as leader from gutter to wall.

ONLY REAL OPTION (OTHER THAN BIRD MOUTHS) IS TO LNK TO NEIGHBORING DOWNSPOUT AND ADD HEADER COLLECTOR.

OR ANGLE BACK TO WALL, EBLOW TOWARD THE RIVER, AND THEN PENETRATE THE BALCONIES.



ST. LOUIS STREET - GAP BETWEEN BALCONIES

OPTION 1 (NOT SHOWN) -BIRDS MOUTH SCUPPERS AT EACH END OF LAKESIDE GUTTER; END AND MIDDLE (AND CORNER AT RADIUS) OF RIVERSIDE GUTTER. ST. LOUIS STREET, LAKESIDE

OPTION 1 (NOT SHOWN) -BIRDS MOUTH SCUPPERS AT EACH END OF LAKESIDE GUTTER; END AND MIDDLE (AND CORNER AT RADIUS) OF RIVERSIDE GUTTER.




NO ROOM FOR

DOWNSPOUT HERE























1014 N Rampart







1014 N Rampart




1014 N Rampart






5 PROPOSED GATES
1/2" = 1'-0"





524 Esplanade











524 Esplanade - 1939


















524 Esplanade - 2005


















524 Esplanade





524 Esplanade





524 Esplanade






524 Esplanade





524 Esplanade





















524 Esplanade – Conceptually Approved Plans








524 Esplanade – Conceptually Approved Plans

















Chapter 1: a good beginning

I hire an architect with interest in classical revival architecture for my Palladian inspired house, Lewis Robinson. We have similar taste. He is a very reassuring since he stated that he's never had a project turned down by the commission. He does his research and shows me several fancy designs from a catalog that was printed in the 1840s. My home was constructed in 1845.

Lewis consults with a senior member of the staff and reports to me that since the staircase was a later addition, that there would be no problem in removing the railing or the entire staircase.

Since the 1879 survey showed a semi circular staircase, I asked him to design an iron staircase similar to the one in my home. Unfortunately, after doing measurements, he concluded that a new staircase would not meet current code standards of width and rise. I find this baffling that I am not allowed to construct a staircase that would be far safer then the current staircase which has irregular, variable rises. Certainly, a new staircase with the same riser heights would be safer. He advised me to only remove the railing and leave the steps.

Chapter 2: rejection

The historic design is brought to the architectural committee. The staff historian objects to the removal of the railing since it has been there over 50 years. She states that the commission is following the recommendations of the national park service.

The chairman of the commission was encouraging when he stated:(This is not an exact quote) since 524 Esplanade already has an historic design railing on the gallery and along the sidewalk, it would be reasonable to have a railing of similar design.

I read the national parks service manifesto. I would like to stress that this is not a mandate or a law. It is a guideline, which they say can be modified by local historic districts. Saving something that is 50 years old in a newer city might be appropriate, but I disagree that it is appropriate in one of the oldest cities in the United States.

When I was restoring 915 Bourbon St., I saved the two 1950s expensive bathrooms. One of the bathrooms was blue, the other was pink, a color I don't like! Nevertheless, I had the pitted chrome, re-chromed. I had a row of cracked pink tiles replaced. Finding the same discontinued tile was very time-consuming. Fortunately, when I sold the house, the new owners did not replace the bathrooms with modern ones.

The architectural committee rejected the removal of the concrete railing unanimously. I was advised to appeal it to the full commission .

Chapter 3: reversal

The issue of removing the concrete railing was appealed to the full commission. Fortunately, one of the members asked what was the height of the railing. This was a issue not addressed by my architect or the three architects on the commission approved unanimously the removal of the concrete railing.

I would like to bring up the issue that the architects sit on both the architectural committee and the full commission. So, appeals are voted on by members that have already rejected the design. This does not seem right to me.



Chapter 4: back to the drawing board

The staff negotiates with my architect on simpler and simpler designs. This is beginning to look to me like something from Levittown, NY! But then, the staff is wearing me down, I'm willing to agree to anything. Unfortunately, due to the length of this process, the decorative element that was agreed to by the staff, has now been discontinued! My architect who never considers cost, tells me to have it replicated from the last three pieces that he bought. He also states that it should be one and a half inches thick.

My Iron man made up one sample, the cost is \$200 each . At this point, I've already spent over \$10,000 on one set after another of simpler drawings demanded by the staff. The staff has now made this project so expensive, that it is unaffordable.

I would like to point out that I have been actively involved in restoring buildings in the French quarter since 1975. This is the third building. I have always maintained using the buildings according to their original use as a private home. My first renovation at 1012 Royal St., I turned four apartments in the main building back to a single residence.

At 524 Esplanade Ave., I have, by myself, repaired the plaster, painted all the rooms, sanded and varnished the floors, stripped off over 10 coats of paint off the wood risking lead poisoning, repaired the roof multiple times risking cancer from asbestos tiles, replaced termite eaten wood. Instead of playing golf or tennis, my physical exercise is working on my home.

Chapter 5: desertion

I discuss cost with my architect and tell him we need a more affordable design. He understands my concerns, but is unwilling to submit any appeals to the full commission and the city Council. He is unwilling to risk his relationship with the staff members. This might make it difficult for him to get future projects approved in the French Quarter, or even in another part of the city.

This is a complaint that I've heard multiple times in the past from architects who are unwilling to work in the French quarter. They have explained to me that they receive little guidance, rules are not clear, the rules continually change with changes in the staff or the changing members on the architectural committee.

Chapter 6: Bauhaus Humbug

This change to modernism reverses 70 years of the policies of the commission. For 70 years, historical designs have not only been approved but were required. This staff is, in effect, saying that for 70 years the citizens that served on the architectural committee's and the commission were wrong. Also, the architects and the commission members who approved my balcony railing and my sidewalk fence were wrong. Bauhaus humbug!!

Many of these volunteers were my friends, for example, Mary Morrison who lived in and who fought for the French Quarter from the 1930s and helped Save it along with her husband Jake. I was also friends with the previous owners of the house, the Ronstroms, who bought the house in the 1930s. I had been entertained more than 50 times by this couple with their stories of the French quarter and our house. They had seen my renovation at 1012 Royal St. through the many stages. Dr.Ronstrom was very pleased that I was buying his precious home.

Please approve the affordable and historic design.

Please include this letter in my application.



From: Robert Kenny < drrobertkenny@yahoo.com > Page 46 of 221

Sent: Tuesday, February 2, 2021 12:07 AM

To: Bryan D. Block < bdblock@nola.gov>; Erin Holmes < erinholmes@vcpora.org>

Subject: Response to staff analysis January 26, 2021

EMAIL FROM EXTERNAL SENDER: DO NOT click links, or open attachments, if sender is unknown, or the message seems suspicious in any way. DO NOT provide your user ID or password. If you believe that this is a phishing attempt please forward this message to phishing@nola.gov

"Following the conceptual approval of a simplified railing design at the 11/10/2020 meeting, the owner stated that the cost of the cast iron center decorative element would be over \$200 each."

This sentence seems to imply that all of the above occurred shortly after November 10, 2020. The sequence of events is the following.

I, Dr. Kenny, called 2 ironworkers that I had used previously: Iron work services, and Gutierrez iron. I left detailed messages about reproducing from a casting, a thicker two sided casting. I also call the "Premier ironworker in New Orleans" recommended by my architect. After leaving messages weekly for over a month at these three businesses, I only had one reply.

I have worked with Mr. Gutierrez on several projects at my home and rental properties. Some of the iron ornamental iron jobs were missing pieces and Mr. Gutierrez was able to reproduce them. Finally, in January Mr. G brought me the finished sample. He said the thickness was very difficult to make and would cost at least \$200 each. It was at this time that I asked him to bring me the catalog so I could look for ready-made pieces. These pieces would cost less than \$50 each and would greatly decrease the total cost of the project. This was not just one decorative element, but an entire section.

"No revised drawings have been submitted."

This is true, after over \$10,000 in architectural fees because of continual staff demands for simpler drawings, without any guidance, I do not want to waste more money until the ready-made iron piece is approved.

It is unclear how these rectangular elements would rise and the curve around the stairs.

This is true for the piece which has straight lines. The rising curve that the staff is mentioning is the railing being convex. Otherwise, the railings are a stretch straight, making a 90° turn with the inner railing. This is also a problem with the previously conceptually approved Design with the parallelograms. You have straight lines with the parallelograms, yet the railing is not straight, it is convex, gradually turning upward and then downward. The ready-made piece will have to be made higher in order to meet they 34 inch to 38 inch rule.

My idea would be to add 3 inch rosettes previously conceptually approved above ready-made piece.

However, this criticism does not apply to the fancier ready-made piece. This design it's very curvy and not linear. The bottom section of this design could easily be cut to compensate for the Convex railing. However, the staff chose to comment only on the rectangular Design ready-made piece.

More Analysis Of staff analysis to follow.

Cheers, Dr. Kenny

524 Esplanade – Letter from Owner/Applicant



Page 47 of 221

From: Robert Kenny < drrobertkenny@yahoo.com>

Sent: Tuesday, February 2, 2021 2:06 AM

To: Bryan D. Block < bdblock@nola.gov >; Erin Holmes < erinholmes@vcpora.org >

Subject: Staff analysis January 26, 2021

EMAIL FROM EXTERNAL SENDER: DO NOT click links, or open attachments, if sender is unknown, or the message seems suspicious in any way. DO NOT provide your user ID or password. If you believe that this is a phishing attempt please forward this message to phishing@nola.gov

Staff quotes department of interior guidelines.

I have already commented on my disagreement with reversing 70 years of policies followed by the Vieux Carré Commission.

Staff reminds the committee that I have already significantly altered the front of the building twice.

It would have been nicer and kinder if this criticism was tempered by the acknowledgment that this was all done with Vieux Carré Commission approval. For years, I thought I was doing right by following the guidelines of the commission. Now, I am the bad guy, the ignorant owner, a destroyer of the French quarter.

The contemporary addition in 2017.

Well at least this should suit staff's taste, but The staff doesn't say so. The Commission staff fought this project for years. I finally had to go to the city Council, And they overrode the commission. The design that was approved by the city Council, the staff decided to try to block it. So, after requiring me to get a structural engineer report for the city Council Design, the director changed his mind, and thought that he should be able to change the design. He rejected one design after another, and advised me to get another architect that was more sensitive to the quarter. This meant someone who agreed with the director. So I was directed to new architect by an architectural committee member. This new architect said that this was a very difficult project and he had to think on it a lot, think and bill, think and bill. When the bills got to \$20,000 with this new architect, I had to get my old architect involved to help him think clearly and quickly.

The design approved by city Council went between my building and the building next-door Riverside. The city Council Design wars much shorter and would've cost a lot less. I believe the director was trying to wear me down and increase the cost to prevent this project.

There are similarities between the simpler ready-made Design and the conceptually improved Design. Both are angular and have anthemion. However, the fancier design would be easier to use with the convex railing.

The anthemion is above my front door which is the reason why I used it on the sidewalk fence. The angular piece has a SIMPLIFIED Greek key type Design which are in my gallery railing and the front fence. Again, both the gallery railing and sidewalk fence were approved by the Vieux Carré Commission. Does the angular ready made piece meet the interior department recommendation for a simplified design? It does.. It is much simpler then the design on the Beauregard house, or the house on Dauphine Street.

The 1876 survey showed semi circular railing and staircases. The 1896 survey showed that there was no staircase. The staff seems to think that they railing should be a wood railing from a picture that was taken after 1915. How do we know this? Because the picture also shows a building that was built in 1915 on the lake side of my home.

524 Esplanade – Letter from Owner/Applicant



A wood railing and staircase was part of the specifications printed in the Esplanade Avenue book. The book also specified an iron gallery railing which the staff analysis never mentioned. The staff seems to leave out anything that would not support their opinion and taste. It seems reasonable to assume that the original gallery railing rusted and was thrown out with modernization in the 20th century. I did try to find an older picture that would show the original iron gallery railing, but was unsuccessful.

Since the first owner quickly lost the house in a sheriff's sale, it is reasonable to assume they would have built a more expensive staircase like the Beauregard house which they were copying, but they ran out of money.

Is my house original, no.

Is my home copying two previously built homes in the French quarter, yes.


Are the two previously built homes original architecture, no.


There are no Frank Loyd Wright houses in the French quarter.

Could the original wood staircase have rotted quickly and replaced within a few years, possible. Could there have been a metal staircase and metal railing install in the 19 century, possible. Could the second owner have torn down they original cheap wooden staircase and replace it with an expensive metal staircase, very likely.

Cheers, Robert Kenny







932 Bourbon







































































































932 Bourbon Street Restoration New Orleans, Louisiana 70116

OWNER: 932 BOURBON STREET LLC DBSASSONE@AOL.COM

(P) 504-252-2931

ARCHITECT: ARCHETYPE, LLC

ATTN: LACEY WOTRING

LACEY@STUDIO-ARCHETYPE.COM

(P) 337-280-1089

SHEET INDEX:

G0.0 TITLE PAGE & SHEET INDEX

A1.0 SITE/ROOF PLAN & EXTERIOR FACADE MODIFICATIONS

A2.0 PROPOSED SIDE MODIFICATIONS & DETAILS

BUILDING INFORMATION:

BUILDLING ADDRESS

NEW ORLEANS, LA 7011

PROJECT DESCRIPTION: SCOPE IS FOR EXTERIOR WORK ONLY OF EXISTING MULTI-FAMILY RESIDENCE. NO INTERIOR WORK OR MODIFICATIONS TO MECHANICAL, ELECTRICAL OR PLUMBING

LOT: SQ. 57 LOT 4 23X101 = 2,323 SF

BUILDING AREA EXISTING CONDITIONED SPACE: 4,000 SF

FLOOD ZONE/FIRE DISTRICT FLOOD ZONE: X

FIRE DISTRICT: YES

FOUNDATION: EXISTING PIER FOUNDATION TO REMAIN

ZONING - CITY OF NEW ORLEANS

ZONING DISTRICT: VCR-1

ZONING DESCRIPTION: VIEUX CARRE RESIDENTIAL DISTRICT

APPLICABLE CODES AND REGULATIONS:

INTERNATIONAL RESIDENTIAL CODE, 2015 EDITION W/ NEW

RLEANS AMENDMENTS

NO AUTOMATIC SPRINKLER SYSTEM

IBC TYPE IIIA

NFPA TYPE III (211)

LEGEND: SYMBOLS HATCH PATTERNS BRICK EARTH and di STUCCO WOOD BLOCKING GYP, BOARD 8 3 FINISHED WOOD ROOM NAME / NUMBER ELEVATIONS 1.110113 WDCD GRAP KEYNUTES / GENERAL NOTES ACOUSTIC TILE CEILING A.F.F. ABOVE FINISHED FLOOR ALUM. /TEMP. GLASS ALUMINUM TEMPERED GLASS ANODIZED ALUMINUM BOARD B.E.E BELOW FINISHED FLOOR CPT CARPET CONC CONCRETE DIA. DIAMETER F.O.B FACE OF BOARD GYP GYPSUM H.M. HOLLOW METAL ON CENTER PTD PAINTED PTD. GYP. PAINTED GYPSUM BOARD PAINTED MOISTURE RESISTANT PTD, MR, GYP SOLID CORE WOOD S.C. WOOD T&G TONGUE AND GROOVE TYP. TYPICAL VCT VINYL COMPOSITE TILE

GENERAL NOTE

- SEE OTHER SHEETS FOR ADDITIONAL NOTES & SPECIFIC CONSTRUCTION NOTES
- THE GENERAL CONTRACTOR AND SUBCONTRACTORS SHALL VISIT THE PROJECT SITE AND DECOME GENERALY FAMILIAR WITH THE PROJECT AND WITH THE MANCT OF THE REW WORK ON EXISTING CONDITIONS, ANY NEADS OF CONCIONS SHALL BE ROUGHT TO THE ATTENTION OF THE ARCHITECT PROPE TO SUBMITTION A PROPOSAL. NO ADDITIONAL CHARGE TO THE OWNER WILL BE APPROVED WHICH IS ATTRIBUTABLE TO THE CONTRACTOR'S FAILURE TO MEET THIS REQUIREMENT.
- SURVEY EXISTING ARCHITECTURAL IMEDIANICAL ELECTRICAL, AND STRUCTURAL SYSTEM LOCATIONS AND COORDINATE WITH THE DOCUMENTS PRIOR
 TO SUBMITTING A PROPOSAL FOR THE WORK VERIFY THAT ALL NEW CONSTRUCTION AND COUPPIENT INSTALLATIONS ARE COMPATIBLE WITH BOTH THE
 CONTRACT DOCUMENTS AND FIELD CONSTITUENT. ALL COST OF RELOCATING OR MODIFYING EQUIPMENT SHALL BE REPLICATED IN THE CONTRACTORS
 PROPOSAL, CHARGE ORDINGS OR JOS EXTRAS FOR WORK SHALL NOT BE CONSIDERED IF VERIFICATION OF JOB CONDITIONS COULD HAVE BEEN IMPORTANT.
- 4. PROVIDE POSITIVE SEPARATION OF DIS-SIMILAR MATERIALS.
- WORK OALY FROM THE WRITTEN DIMERSIONS SHOWN DO NOT SCALE DRAWNINGS, DETAIL DIMERSIONS TAKE PRECEDENCE OVER PLAN DIMERSIONS. LOCATION AND DIMERSIONS SHALL BE PER ARCHITECTURAL DRAWNINGS. EXISTING CONDITIONS INDICATED ARE APPROXIMENT AND SHALL BE RELEASED. VERFIELD BY THE CONTRACTOR PRIOR TO PROCEEDING WITH ANY WORK. DISCREPANCIES MUST BE BROUGHT TO THE ATTENTION OF THE ARCHITECT BEFORE THE STRAT OF WORK OR MUMERIALLY UPON DISCOVERY.
- THE GENERAL CONTRACTOR SHALL KEEP THE CONSTRUCTION AREA CLEAN AND SAFE AND PROTECT ADJACENT AREAS OUTSIDE THE WORK AREA FROM THE WORK OF THIS CONTRACT.
- 7. REMOVE AND LEGALLY DISPOSE OF DEBRIS, RUBBISH AND OTHER MATERIALS RESULTING FROM CONSTRUCTION OPERATIONS
- THE GENERAL CONTRACTOR IS FULLY RESPONSIBLE FOR THE CONSTRUCTION, MATERIALS AND WORKMANSHIP OF THE PROJECT DESCRIBED IN THE DRAWINGS AND NOTES. AND IS TO COMPLY WITH THE INTENT AS WELL AS THE LETTER IN WHICH THEY WERE WRITTEN.
- 9. THE GENERAL CONTRACTOR SHALL PROVIDE ALL NECESSARY PROTECTION FOR HIS WORK UNTIL TURNED OVER TO THE OWN
- THE GENERAL CONTRACTOR IS RESPONSIBLE FOR COORDINATION WITH HIS SUBCONTRACTORS. ANY CONFLICTS WITH THEIR WORK, EQUIPMENT PLACEMENT, ETC. ARE TO BE RESOLVED PRIOR TO INSTALLATION OF THE WORK.
 - A) THE CONTRACTOR SHALL COORDINATE AND LOCATE ELECTRICAL DEVICES, DATA AND PHONE RECEPTACLES, SWITCHES, ETC. TO AVOID CONFLICTS. WITH CASEWORK, DOORS AND OTHER TRADES.
 - 8) THE CONTRACTOR SHALL VERIFY & COORDINATE, WITH ALL TRADES, THE SIZES AND LOCATIONS OF ALL OPENINGS FOR MECHANICAL PULMBINS AND ELECTRICAL EQUIPMENT, EQUIPMENT PADS, OR BASES AS WELL AS POWER, WATER AND DRAIN INSTALLATIONS BEFORE PROCEEDING WITH THE WORK.
 - C) THE CONTRACTOR SHALL PROVIDE COORDINATION DRAWINGS FOR PROPER PLACEMENT OF ALL TRADES WORK ALL CONCERNS, SPACE LIMITATIONS OR STRUCTURAL CONFLICTS SHALL BE BROUGHT TO THE IMMEDIATE ATTENTION OF THE ARCHITECT.
- CONTRACTOR SHALL SUBMIT SHOP DRAWINGS AND FINISH SAMPLES FOR ALL CASEWORK, MILLWORK, HARDWARE, FINISHES, AND SPECIALTY ITEMS TO ARCHITECT FOR REVIEW PRIOR TO FABRICATION.
- INSTALL ALL MANUFACTURED ITEMS, MATERIALS AND EQUIPMENT IN STRICT ACCORDANCE WITH MANUFACTURER'S RECOMMENDED SPECIFICATIONS.
- 13. VARIATIONS FROM WORK SPECIFIED DUE TO AVAILABILITY OF MATERIALS, FIELD CONDITIONS, VARIATIONS IN EQUIPMENT SPECS, ETC. SHALL BE MADE
- 14. ALL WORK SHALL BE PERFORMED IN COMPLETE COMPUSINGE WITH ALL NATIONAL, STATE AND LOCAL CODES AND ORDINANCES AND IN ACCORDANCE WITH THE AGENCIES HAVING JURISDICTION. THE CONTRACTOR SHALL OBTAIN ALL NECESSARY PERMITS AND INSPECTIONS FOR THE WORK.
- 15. IT IS THE INTENT OF THE DOCUMENTS TO PROVIDE FOR COMPLETE FINISHED WORK, ALL MISCELLANEOUS COMPONENTS, PARTS, ANCHORS, AND OTHER INCIDENTAL ITEMS REQUIRED FOR COMPLETE ASSEMBLY, PUNCTIONING AND OPERATION OF AN ITEM OR SYSTEM SHALL BE PROVIDED. THE COMPRISED SHALL BUILDED ALL COMPONENTS THAT ARE INCIDENTAL. TO THE WORK, THOSE COMPONENTS WHICH ARE NOT SHOWN ON THE DRAWNOS OR CALLED FOR IN THE SPECIFICATION, BUT WHICH ARE REQUIRED AS ESSENTIAL ABSTHETICS OR FUNCTIONAL COMPONENT OF THE WORK, SHALL BE INCLUDED AS IF IT WERE DRAWN OR SPECIFICATION.
- 16. IT IS THE RESPONSIBILITY OF THE GENERAL CONTRACTOR TO PROVIDE IN A TIMELY MANNER, AT NO ADDITIONAL COST TO THE OWNER, ACCURATE AND COMPLETE DRAWNINGS, SKETCHES, AND PHOTOGRAPHS SUPPICIENT TO CLEARLY CESCRIBE DISCREPANCIES, CONFLICTS AND CONCEALED OR OTHERWASS UNANTICEPATED DISTRING CONTRICIONS ENCOUNTEED THAT AFFECTS THE NEW CONSTRUCTION.
- SECURE ALL PERMITS AND COMPLY WITH ALL APPLICABLE CODES AND REGULATIONS FOR SAFETY AND PROTECTION OF ADJACENT BUILDINGS AND
 DOCUMED AREAS, DUST CONTROL JUILTY DISCOVERED HAZARDS AND BISPOSAL, CONTACT APPROPRIATE AGENCIES PRIOR TO ANY BELOW GRADE
 EXCAVATIONS NOTIFY OWNER AND PROTECT FROM DISTURBANCE ANY DISCOVERY OF SUSPECTED HAZARDOUS MATERIALS.
- FURNITURE INDICATED ON PLANS IS FOR REFERENCE AND COORDINATION PURPOSES.
- PROTECT ADJACENT PROPERTY AND PERSONS FROM THE WORK. WORKING CUTSIDE THE DESIGNATED LIMITS IS PROHIBITED UNLESS APPROVED BY 1 CLIENTIUSER.
- LIMIT NOISE TO NORMAL CONSTRUCTION OPERATIONS AND REGULATIONS.
- TO ESTABLISH THE COMPLETE SCOPE OF ITS WORK AND TO AFFECT CLOSE COORDINATION WITH THE OTHER TRADES, EACH TRADE SHALL VISIT THE SITE AND COMPLETELY REVIEW THE DRAWINGS NOT ONLY FOR ITS RESPECTIVE TRADE, BUT THE WORK OF OTHER RELATED TRADES AS WELL.
- 22. IT IS THE RESPONSIBILITY OF THE CONTRACTOR TO IDENTIFY POINTS OF ACCESS TO THE SITE AND BUILDING AND TO VERIFY MINIMUM CLEARANCES AVAILABLE FOR USE IN TRANSPORTING NECESSARY CONSTRUCTION MACHINERY, EQUIPMENT, MATERIALS AND COMPONENTS INTO THE BUILDING AND ON THE SITE.
- THE CONTRACTOR SHALL PROTECT EXISTING UTILITIES AND SERVICES AGAINST INTERRUPTION DUE TO THIS WORK. NECESSARY DISRUPTIONS MUST BE COORDINATED IN ADVANCE OF NEED.
- 4. VERIFY PROPERTY LINES, CONDITIONS, SERVICES AND DIMENSIONS BEFORE COMMENCING THE WOR
- 65. CONTRACTOR SHALL PROVIDE ALL SHORING AND STABLIZING BRACING AS REQUIRED TO PROTECT FROM STRUCTURAL FALLINE OR COLLAPSE. PROVIDE INTERIOR AND EXTERIOR BRACING OR SUPPORT TO PREVENT HOVEMENT, SETULABRIC, OR CALLAPSE OF AREA BRACINGED IN AND ASSISTANT AREAS, CLASE OPERATIONS AND NOTIFY ARCHITECT IMMEDIATELY IS SAFETY OF STRUCTURE APPEARS TO BE ENDANGERED. TAKE PRECAUTIONS TO SUPPORT STRUCTURE UNIT. DETERMINATION IS MADE TO CONTINUE OPERATIONS.
- PROVIDE SECURITY AND FACILITIES TO PROTECT SITE AREA, EXISTING FACILITY AND EQUIPMENT FROM UNAUTHORIZED ENTRY, VANDALISM OR THEFT DURING THE WORK, CONTRACTOR SHALL BE SOLELY RESPONSIBLE FOR THE SECURITY OF HISHER OWN EQUIPMENT AND TOOLS.
- 7. THE COST FOR CONNECTION TO AND POWER LINES FROM AVAILABLE POWER SOURCE SHALL BE AT CONTRACTOR'S SOLE EXPENSE.
- 28. PROVIDE TEMPORARY LIGHTING AS REQUIRED; CONNECT TO TEMPORARY ELECTRIC SERVICE
- 29 PROVIDE TEMPORARY VENTILATION TO PROTECT WORKERS AS REQUIRED.
- 30, CONNECT TO EXISTING WATER SOURCE FOR TEMPORARY WATER SERVICE. IF UTILITY IS CAPPED, COORDINATE WITH OWNER,
- PROVIDE TEMPORARY SANITARY FACILITIES.
- MAINTAIN FIRE SAFETY/CONTROL AT ALL TIMES.

м

Page 70 of 221

O+∞ _ o _ Φ0 ` _ ' <u>ш</u>+ р $^{\rm H}$ $^{\rm C}$ α S 0 z_{Ω} В ⊃ ⊆ α Ω 0 \supset OwI 0 Ω 7 2 e e

DE SENE


66Z


ISSUEDATE: JANUARY 18, 2021

DRAWING TIL:
TITLE PAGE &
SHEET INDEX
DRAWING NUMBER


G0.0

VERIFY ON JOB






O 1 DUMAINE STREET (SIDE) ELEVATION SCALE: 1/4" = 1'-0"



02 BALCONY SECTION SCALE: 1" = 1'-0"



Full Meeting Materials - 932 Bourbon

932 Bourbon


VCC Architectural Committee


GC TO INVESTIGATE CONDITION AND LOCATION OF EXISTING STEEL OUTRIGGERS & SUPPORT BARS

REINSTALL DECORATIVE WOOD BRACKETS @ EXIST. LOCATIONS (NOT SHOWN)

02 BALCONY SECTION SCALE: 1" = 1'-0"


















CONSTRUCTION SEQUENCE SCHEDULE
















937 Dumaine



937 Dumaine





NOTES (UNLESS NOTED OTHERWISE):

- IN EXTERIOR WALLS WHERE CRACKING OCCURS IN STUCCO FINISH, DETERMINE JOINT LOCATIONS USING HAND TOOLS. USE CAUTION NOT TO DAMAGE ADJACENT FINISHES.
- WHERE REQUIRED, PATCH FINISH IN LIKE KIND AND WORKMANSHIP AS ORIGINAL, ADJACENT FINISHES.
- AFTER INSTALLATION OF TIES AND PRIOR TO INSTALLATION OF STUCCO FINISH (WHERE REQUIRED). GROUT INJECT C.I.F. INTO CRACK TO FILL CRACK AND VOIDS COMPLETELY.









937 Dumaine St. Existing
Existing outward swing iron security gate. The opening is approx 10' 6" high and 43" wide to the masonry. The wood framing creates about a 2 to 3" border.




Proposed Gate Design

Solid iron gate and transom concept common to the French Quarter. 5/8" bar set on diamond pattern in 3/8" flatiron with classic lockset with matching transom. All solid material to be built by Darryl Reeves of Andrew's Blacksmith Shop in NO.

It will be heavy gauged to match other iron generally found in the FQ with heavy hinges and hardware. To avoid the use of expanded metal around the lockset to prevent unauthorized access from the exterior, we plan to use an additional picket between each main bar up to 58" with pointed tops.

Please note the address numbers cut out of plate to create a silhouette of the address (example above)

Classic large gauge brass knob hardware and iron plated mortice latch around knob area have been suggested to prevent access to the internal knob from the exterior and will be added. Per Fire Marshall requirements, the interior knob will be practical to unlock gate from interior.





































































937 Dumaine St. Existing
Existing outward swing iron security gate. The opening is approx 10' 6" high and 43" wide to the masonry. The wood framing creates about a 2 to 3" border.




Proposed Gate Design

Solid iron gate and transom concept common to the French Quarter. 5/8" bar set on diamond pattern in 3/8" flatiron with classic lockset with matching transom. All solid material to be built by Darryl Reeves of Andrew's Blacksmith Shop in NO.

It will be heavy gauged to match other iron generally found in the FQ with heavy hinges and hardware. To avoid the use of expanded metal around the lockset to prevent unauthorized access from the exterior, we plan to use an additional picket between each main bar up to 58" with pointed tops.

Please note the address numbers cut out of plate to create a silhouette of the address (example above)

Classic large gauge brass knob hardware and iron plated mortice latch around knob area have been suggested to prevent access to the internal knob from the exterior and will be added. Per Fire Marshall requirements, the interior knob will be practical to unlock gate from interior.














DEPARTMENT OF SAFETY & PERMITS ZONING ADMINISTRATION DIVISION

CITY OF NEW ORLEANS

LaToya Cantrell Mayor TAMMIE JACKSON INTERIM DIRECTOR

ZONING VERIFICATION

The City's Official Zoning Map and the full and complete text of the Comprehensive Zoning Ordinance (Ordinance 4,264 MCS, as amended) can be found online. The City's Official Zoning Map is located at property.nola.gov; the text of the Comprehensive Zoning Ordinance is available online at czo.nola.gov.

Date: 10/6/2020 Case Number: 20-1237

To: Emily Flagler, Architect, LLC

This letter is to verify the zoning classification of the following property:

Address: 937 Dumaine St

 Tax Bill Number: 207102926
 Flood Zone:

 Lot Number(s): A of 24
 Square(s): 85

Legal Description: SO 85 LOT A 21X68 (Per Orleans Parish Assessor)

Zoning Designation: VCR-1 Vieux Carré Residential District

Historic District: Vieux Carré Local Historic District

Comments:

This is a Zoning Verification for a 6-unit Multi-Family Dwelling in a VCR-1 District. This property is also located in the Vieux Carré Height Interim Zoning District. A Multi-Family Dwelling is a permitted use at this location.

The 6-unit structure does not comply with the lot area per dwelling unit requirement of 900 sq ft/du with a lot size of approximately 1,428 sq ft. The use of the property is a permitted use, but with more units than allowed, this is treated as a non-conforming structure and can be renovated subject to the regulations in Section 25.4 of the CZO: http://czo.nola.gov/Article-25#25-4

Inspector Signature: _



Nicholas Kindel, Zoning Administrator

1300 PERDIDO STREET | ROOM 7E05 | NEW ORLEANS, LOUISIANA 70112 TELEPHONE: 504.658.7125 | FACSIMILE: 504.658.7210







To: Erin B. Vogt

That is all good. They can decrease units without a problem.


The 180 day vacancy is only an issue with non-conforming uses (which this is not). For non-conforming structures, it can be vacant for any amount of time and it will still be able to be renovated without a problem.


Nick <mark>Kindel</mark>

Zoning Administrator
Department of Safety and Permits
Office of Business and External Services | City of New Orleans
1300 Perdido Street | 7th Floor | New Orleans, LA 70112
(504) 658-7200 Office | (504) 658-7125 Zoning | (504) 915-6489 Cell | njkindel@nola.gov



740 Esplanade/ 1350 Bourbon St.










740 Esplanade/1350 Bourbon St. – Approximate Location of Proposed Work












740 Esplanade/






740 Esplanade/1350 Bourbon St. – Orange-Rated Rear Buildings





 $3_{\frac{\text{SCALE: NTS}}{\text{SCALE: NTS}}}$




 $3_{\frac{\text{SCALE: NTS}}{\text{SCALE: NTS}}}$








740 Esplanade/1350 Bourbon St.



740 Esplanade/1350 Bourbon St.




Page 114 of 221



1 DOOR ELEVATION
SCALE: 1" = 1'-0"





c/o Carriage House Realty, 640 Congress Street, New Orleans, LA 70117 (504) 941-7751 FAX: (504) 947-6325

January 11, 2021

Via E-Mail

Mr. Bryan Block, Director Vieux Carré Commission 1300 Perdido St, 7th Floor New Orleans, LA 70112

Re: 1350 Bourbon Street, Unit 20 Reference Code W0H44R

Dear Mr. Block:

Beauregard House Homeowner's Association, through its Board of Directors, hereby approves and supports the application of Nofio Pecoraro to remove fixed-glass windows on the south-facing wall of the property and install French doors and transom in both openings. The members of the Board of Directors have reviewed the plans and believe that the proposed replacement of the plate-glass windows with French doors and transoms is an improvement to the property and is in keeping not only with its architecture but also with the tout ensemble of the French Quarter.

If you have any questions, please contact me.

Yours very truly,

Mary Ann Hammett

Manager


Carriage House Realty 640 Congress Street

New Orleans, Louisiana 70117

Mobile: (504) 421-8096 maryannhammett@cox.net

cc:


Linda Neal, President Will Lyman, Treasurer Maria de Lourdes, Secretary Mark Rivero, At-large Angie Tocco, At-large








































618 Conti






618 Conti






























532 N Rampart















February 9, 2021



February 9, 2021







February 9, 2021









February 9, 2021





February 9, 2021

LEGEND (12) X X X X X HMSH KEY (X) DOOR TAG (1) PARTITION ROOF ASSEMBLY ARCHITECTURAL AW3X WOODWORK KEYNOTE (PXX) MECHANICAL KEYNOTE EXISTING PARTITION TO BE DEWOUSHED NEW PARTITION OR MODIFIED - REFER TO FRAMING NOTES AND PARTITION DETAILS ERSTING DOOR & FRAME TO REMAIN EXISTING DOOR & FRAME TO BE ELEVATION MADDES EXTERIOR ELEVATION HP HIGH POINT LP. LOW FOINT SUSP. SUSPENDED GYP. BD. GYPSUM BOARD CONC. CONCRETE H.M. HOLLOW METAL FIXT. FIXTURE LT. UGHT GALV. GALVANIZED ALUM. ALUMINUM. ADJ. ADJUSTABLE HWH HOT WATER HEATER MECH. MECHANICAL STRUCT STRUCTURAL ELEC. ELECTRICAL F.O. FACE OF T.O. TOF OF US UNDERSIDE OF EXIST. DISTING WD. CLG. CEUNG STL. STEEL MTL METAL THIS JECEND CONTAINS SYMBOLS AND ARRESTIATIONS LISED IN PTD PAINTED THE ARCHITECTURAL DRAWINGS. SOME SYMBOLS AND ARRESTATIONS SHOWN ARE NOT LISED IN THIS PROJECT. REFER PTN. PARTITION ALSO TO LEGENDS PROVIDED IN EACH SHEET FOR SYMBOLS AND SPKLR. SPRINKLER ABBREVIATIONS USED TO FURTHER DESCRIBE THE WORK CMU CONCRETE MASONEY UNIT

INDEX OF DRAWINGS

DIRECTORY

ARCHITECTURAL

A-COS SITE, SCOPE LEGEND A-101 ROOF PLAN & DETAILS A-201 EXTERIOR ELEVATIONS

MERCIER REALTY & INVESTMENT CO. 306 DAUPHINE STREET


NEW ORIEANS, IA 70112 (504) 523-1191 mercierrolty@bellsouth.ne

ARCHITECT:

BENDERNAGEL ARCHITECTS, L.L.C. 5530 ATLANTA STREET (504) 891-4700 X52

JOHN E. BENDERNAGE johnbendernogel@gmail.com

TOULOUSE (SIDE)



ST LOUIS STREET (SIDE)





SITE PLAN NOTES

1. THE CONTRACTOR SHALL BE RESPONSIBLE FOR DAMAGE DONE AS A RESULT OF HIS OPERATIONS, INCLUDING DAMAGE TO ADJACENT STRUCTURES, PAVING, VEHICLES, AND PERSONAL PROPERTY OF OTHERS IN THE IMMEDIATE VICINITY OF THE SITE.

3. NOTIFY THE ARCHITECT IN ADVANCE IF ANY SPECIFIED DIMENSIONS CANNOT BE ACHIEVED

NOTES

SUMMARY DESCRIPTION OF WORK

THE PROJECT CONSIST OF THE PHASED RESCOUNG AT THE 4STORY MURTEAWLY STRUCTURE.
THE WORK SHALL INCLUDE WITHOUT LIMITATION:

REMOVAL, STORAGE AND REINSTALLATION OF EQUIPMENT, AND ROOF DECK MATERIALS TO BE REUSED (STORAGE WILL BE ON THE AREA THAT IS OPPOSITE OF THE PHASED WORK AREA).

OPPOSITE OF THE PHOSED WIDEL AREA.

2. PROTECTION OF EXISTING CONSTRUCTION AND ASSEMBLES TO REMAIN.

3. EEMOVAL AND LEGAL DISPOSAL OF ALL EXISTING DECK MATERIALS.

3. EM/ONIA AND ESAS, DEFOCAS, OF ALL DESTING DOCK MATERIALS PROVINCING INCIDENT CASE DEFOCAS, OF ALL DOSTING MATERIALS TO THE OWNERS AND RELIGIOUS OF ALL DESCOUND ASSESSMENT OF THE OCCUPANT ARRESTS AND DESIGNATION OF NEW OCCUPANTIALS AND DESIGNATION OF THE OCCUPANTIAL DESCRIPTION AND THE OCCUPANTIAL DESCRIPTION AND DESIGNATION OF THE OCCUPANTIAL DESCRIPTION AND DESIGNATION OF THE OCCUPANTIAL DESCRIPTION AND MATERIALS FILLY ACCUPANTIAL OF THE OWNERS AND MISTINGS.

CONTINUED AND DESCRIPTIONS OF THE OWNERS AND DESCRIPTION OF THE OWNERS AND DES

GENERAL CONSTRUCTION NOTES

CONTRACTOR IS TO READ ALL PORTIONS AND SECTIONS OF THE CONTRACT DOCUMENTS AND SHALL BE FAMILIAR WITH ERISTING CONSTITUTE.

2. THE CONTRACTOR SHALL REPORT FOR COMMUNICE WITH THE CONTRACT DOCUMENTS, WIRECUT AND SHAPE TO THE ASCRIPTOR SHAPE TO DRAWNING, ROBERT AND SHAPE TO SHAPE AND SHAPE AND SHAPE AND SHAPE AND SHAPE AND SHAPE SHAPE CONTRACT OF THE CONTRACT OF

2. THESE DRAWINGS ARE INTENDED TO CUTTIVE THE SCOPE OF WORK REQUISED TO PROVIDE A CONVINCE IN CHESTAGE PROJECT CONCUSION. ALL MCKELLANDED, COMPONENDED PARTS, FASTERERS, SOSS, AND OTHER INCIDENTAL TRANS PRESENT TO PROVIDE A COMPLETED PROJECT SHALL BE ROCKED WHERE OR BOTS SHORT-CLIVE FOR THE CONTROL WHERE THE CONTROL W

4. WORKING DIMENSIONS SHALL NOT BE SCALED FROM PLANS, SECTIONS, OR DETAILS, CONTRACTOR TO VERBY OUR MEASUREMENTS IN THE FIELD FROM TO ORDERING MATERIAL.

S. COLONACIDED NOT TO BOTHAT BEAUTH CONTRACT EXCLUSIONS NOWSFUL TO COMPACT OR DESCRIPTION FOR CONTRACT OR CONTRACT

6. CONTRACTOR IS TO NOTIFY THE ARCHITECT AND/OR ENGINEER TO ALL 6. CONTRACTOR IS TO NOTIFY THE ARKINETT AND/OR ENGINEER TO ALL SIGNIFICANT WORK TO BE CONCLEARED AT LESS 72 HOUSE PRIOR TO THE ENEN. IN THE PERMIT THAT NEED THE ARCITECT AND/OR ENGINEER CAN DESIRED. THE WORK FRORS CONTAMINAT, THE CONTRACTOR IS TO TAKE CONTRIBUTION PROTOS OF THE WORK WHICH WOUND RECLUDE ACCESS. ACCESS TO MICTIOS ARE TO 18 CRAINTED TO THE ARCHITECT AND CO. ENGINEER UPON REQUEST

CONCLUSION OF EACH WORKDAY.

8. CONTRACTOR TO NOTIFY THE ARCHITECT IMMEDIATELY OF ANY CONFLICTS ARISING FROM DISCOVERED HIDDEN CONDITIONS AT ANY PHASE OF THE

ANY DEVIATION TO THE CONTRACT DOCUMENTS NOT AFFROWED IN WINTING BY THE AND-ITECT/EVIGINEES SHALL BE THE RESPONSIBILITY OF THE CONTRACTOR TO CORRECT AT HIS/HER OWN EIGENSE.

10. DURING AND UPON COMPLETION OF THE WORK, ALL SERVICES, FILTURES, AND EQUIPMENT SHALL BE KEPT CLEAN AND FREE OF EXCESS MATERIALS, STAINS, OR DUST,

11. CONTRACTOR TO PROVIDE REPROOFING FOR ANY PENETRATIONS THROUGH ANY FIRE RATED ROOF ASSEMBLES.

12. CONTRACTOR TO DOCUMENT EXISTING CONDITIONS AT THE PROJECT SITE AND ADJACENT PROPERTIES PRIOR TO START CONSTRUCTION.

OF THE INTERIOR STANDARDS FOR THE TREATMENT HISTORIC PROPERTIES WITH GUIDELINES FOR RESTORING HISTORIC BUILDINGS.

14 CONTRACTOR TO PROVIDE TESTING AND ANALYSIS FOR THE EXISTING BRICK/MASONEY, MORIAR, PAINTING AND COATINGS AND METALS IN ACCORDANCE WITH THE SECRETARY OF THE INTERIORS STANDARDS.

15. CONTRACTOR TO COORDINATE WITH THE OWNER PRIOR TO THE STAT' OF CONSTRUCTION DUE TO THE BUILDING SEMANING OCCUPIED DURING CONSTRUCTION CONTRACTOR TO PROTECT BUILDING OCCUPIENT WISTORS AND RESIDE FROM CONSTRUCTION AND AUCW ENTRY TO THE BUILDING DURING BUILDING OF ORESINON.

Page 150 of 221

 \simeq S

RIOR REPAIRS

RAMPART

LEANS, LOUISIANA
SILA RECHITECTES,

EWORLINGLANIS 1 GOOGEL

R / R / VORLEA

4 3 S

10


THESE ARCHITECTURAL DESIGNAS AND DECOMAINS ARE SHARED TO THE ARCHITECTURAL ANGUES COPYRIGHT RECIFICION AND AND THE ARCHITECTURAL THROUGH STATE AND THE ARCHITECTURAL ARCHI ENDERHADE, ACHTECTE, UC AND MOSE CEBUIS NO US IN CONSE WITH THE SPECIALS MODEL, THE CONTENT SHALL NOT SE USED SF OF ENDERHADES OF MY PREPOSE AND ANY PREPOSE ANY PREPOSE AND ANY PREPOSE A PADERNADE ACTIFICID, ISC. THE OCUMENTS AND THE PROPERTY OF ENDERNADE, AVCHISCIS, ISC.


PROJECT # 2020-15

PROGRESS DRAF


1/8/2021

A-00S



































































































625 Chartres



January 26, 2021







625 Chartres





















625 Chartres

























415 Burgundy






415 Burgundy













415 Burgundy – Wall Location

















February 9, 2021












415 Burgundy - Rear Wall







415 Burgundy





415 Burgundy – 1963 Photograph






415 Burgundy – 1963 Photograph (Detail)

VCC Architectural Committee

February 9, 2021






415 Burgundy – 1963 Photograph (Detail)

VCC Architectural Committee

February 9, 2021












415 Burgundy – 1987 Photograph (Details)
































amazon.com/dp/8088RSL9PF/ref=emc_b_5_i7th=1

Roll over image to zoom in

Antennas Direct 8-Element Bowtie TV
Antenna, 70 Miles Range & ClearStream Juice
VHF/UHF Low-Noise Preamplifier System,
Low-Loss Power Inserter, Two 36%22 HighPerformance Coaxial Cables

Visit the Antennas Direct Store

★★★★☆ ~ 2,105 ratings | 349 answered questions


Bundle Price: \$207.93


Style: 70 Mile w/ Preamplifier System


45 Mile \$44.99 70 Mile	60 Mile
	\$71.14 70 Mile w/ 30° Mount
70 Mile w/ 4-Port TV Amplifier	70 Mile w/ HDTV Preamplifier
\$170.38	\$168.35
70 Mile w/ Preamplifier	70 Mile w/ VHF Kit
System \$207.93	140

. Benchust 1: The Most Boundary 9 Clamont Bourie Antoney Available 70 Mile























U U U U

Schlage Touch Keyless Touchscreen Lever with Camelot trim and Accent Lever

FE695 CAM 716 ACC
READ REVIEWS

Finish: Aged Bronze



Find a Retailer

TAP TO ENLARGE







TAP TO ENLARGE

FEATURES

SPECIFICATIONS

- · Applications: Residential single- and multi-family doors
- · Backset: Universal latch standard, fits either 2-3/8 in. (60mm) or 2-3/4 in. (70mm) backsets
- Battery: Uses 1 9V battery
- · Certifications:
 - Commercial Standard Certification: ANSI/BHMA A156.2-2011 Grade 2
 - Residential Standard Certification: ANSI/BHMA A156.39-2015 Grade AAA in Security, Durability and Finish
- Door thickness range: 1-3/8 in. to 1-3/4 in. (35mm-44mm)
- Exterior Dimensions: 3" x 5.4" x 7.9"
- · Operating Temperatures: Outside escutcheon: -35C to 66C,Inside escutcheon: -10C to 49C
- · Warranty: 3-Year Electronics Warranty; Limited Lifetime Mechanical and Finish Warranty
- Codes: 2 pre-set unique 4-digit access codes, storage of up to 19

Schlage Touch Keyless Touchscreen Lever with Camelot trim and Accent Lever

FE695 CAM 716 ACC



Finish: Aged Bronze



Find a Retailer

Related Products









Camelot Trim Connected Keypad Deadbolt

Accent Lever with Camelot trim Hall & Closet Lock

Accent Lever with Camelot trim Bed & Bath Lock

407 Burgundy – Proposed Keyless Hardware

