
# Vieux Carré Commission Architecture Committee Meeting


Tuesday, July 11, 2023







730-732 St Peter



730-732 St Peter



730-732 St Peter – 1860 plan book



Vieux Carre Commission



730-732 St Peter – 1930s – 40s?



February 16, 2022
























































































































730-732 St Peter















# **H40**

Sure Klean<sup>®</sup> Weather Seal H40 is a deep-penetrating water repellent and consolidation treatment for brick, most natural stone, unglazed terra cotta, historic concrete, stucco and cast stone surfaces. H40 protects against deterioration caused by water and waterborne contaminants while strengthening weathered surfaces and soft mortar joints.

Weather Seal H40 also reduces the severity of biological staining common to regions with high relative humidity. It helps prevent the rapid recolonization of biological species such as mold, mildew and lichens that normally thrive on masonry and natural stone architecture.

#### TYPICAL TECHNICAL DATA

| TITICAL ILCIINICAL DAIA |  |  |  |  |
|-------------------------|--|--|--|--|
| FORM                    | Clear, slightly yellow liquid<br>Mild petroleum odor |  |  |  |
| SPECIFIC GRAVITY        | 0.882  |  |  |  |
| pH                      | not applicable                                       |  |  |  |
| WT/GAL                  | 7.34 lbs   |  |  |  |
| ACTIVE CONTENT          | 23%  |  |  |  |
| TOTAL SOLIDS            | 21% ASTM D 2369                                      |  |  |  |
| VOC CONTENT             | >600 g/L   |  |  |  |
| FLASH POINT             | 108° F (42° C)<br>ASTM D3278                         |  |  |  |
| FREEZE POINT            | <-22° F (<-30° C)                                    |  |  |  |
| SHELF LIFE              | 2 years in tightly sealed,<br>unopened container     |  |  |  |

# SAFETY INFORMATION

Always read full label and SDS for precautionary instructions before use. Use appropriate safety equipment and job site controls during application and handling.

24-Hour Emergency Information: INFOTRAC at 800-535-5053

# **ADVANTAGES**

- Deep penetration provides long-lasting protection.
- Strengthens and protects deteriorating surfaces.
- Strengthens soft mortar reduces need for repointing.
- Treated surfaces "breathe" does not trap moisture.
- · H40 helps prevent rapid recolonization by biological species such as mold, mildew and lichens.
- · Low odor.
- · Resists water penetration when applied over existing shrinkage cracks of 0.02 inches or less

- · May damage glass or be difficult to remove. Always protect.
- · May cause slight or moderate darkening on some surfaces. Always test for desired results.
- Surface and air temperatures should be above 40°F (4°C) and below 95°F (35°C). Avoid application on extremely windy days to avoid rapid evaporation of the solvent carrier.
- · Not recommended for application to new concrete or below-grade application.
- · Will not prevent water penetration through structural cracks, defects or open joints.


## REGULATORY COMPLIANCE

## **VOC Compliance**

Sure Klean® Weather Seal H40 is compliant with the US Environmental Protection Agency's AIM VOC regulations. Manufactured and marketed in compliance with US EPA AIM VOC regulations (40 CFR 59.403).

Visit www.prosoco.com/voccompliance to confirm compliance with individual district or state regulations.

# EXTERIOR WALL TREATMENT LEGEND PROSOCO H40 - OPTION 1 PROSOCO BLOK-GUARD - OPTION 2 NON-PAINTED BRICK MASONRY PROSOCO BMC 2 TREATMENT PAINTED PLASTER OR PAINTED MASONRY COLOR TO BE APPROVED BY VCC



#### Product Data Sheet Weather Seal H40

#### **PREPARATION**

Protect people, property, vehicles, plants and all non masonry surfaces from contact with the product, fumes and wind drift. Protect and/or divert pedestrian and auto traffic. H40 may damage some metal finishes and glass. Test and protect as necessary. PROSOCO's Strippable Masking is not effective protection for use with H40.

Ensure fresh air entry and cross ventilation during application and drying. Extinguish all flames, pilot lights and other potential sources of ignition during use and until all vapors are gone.

When applying to exteriors of occupied buildings make sure all windows, exterior intakes and air conditioning vents are covered and air handling equipment is shut down during application and until all vapors have dissipated. Fill all cracks and voids to keep fumes out of buildings.

| Substrate                            | Type  | Use?                     | Coverage                      |
|--------------------------------------|---|--------------------------|-------------------------------|
| Architectural<br>Concrete<br>Block   | Burnished<br>Smooth<br>Split-faced<br>Ribbed      | yes<br>yes<br>yes<br>yes | 50–100 sq.ft.<br>5–9 sq.m.    |
| Concrete*                            | Brick Tile Precast Panels Pavers Cast-in-place    | yes<br>yes<br>yes<br>yes | 75–175 sq.ft.<br>7–16 sq.m.   |
| Fired Clay                           | Brick<br>Tile<br>Terra Cotta (unglazed)<br>Pavers | yes<br>yes<br>yes        | 50–175 sq.ft.<br>5–16 sq.m.   |
| Marble*,<br>Travertine,<br>Limestone | Polished  | no                       | N/A                           |
|                                      | Unpolished  | yes                      | 100–175sq.ft.<br>9–16 sq.m.   |
| Granite•                             | Polished  | no                       | N/A                           |
|                                      | Unpolished  | yes                      | 150–400 sq.ft.<br>14–37 sq.m. |
| Sandstone                            | Unpolished  | yes                      | 75–200 sq.ft.<br>7–19 sq.m.   |
| Slate•                               | Unpolished  | yes                      | 200-600 sq.ft.<br>19-56 sq.m. |

Always test to ensure desired results.

Coverage estimates depend on surface texture and porosity.

Surface should be clean and free of dirt, dust, oils and other contaminants. If necessary, clean with the appropriate PROSOCO cleaner. Surface must be thoroughly dry and absorbent before application.

All caulks and sealants should be in place and thoroughly cured before application. The top of walls should be capped and made watertight prior to application.

NOTE: Some floor and wall systems incorporate asphaltic or other crack-suppression membranes. This deeply penetrating protective treatment may penetrate through exposed stone, tile, grout or paver surfaces and react with the membrane to mobilize objectionable staining. Always pretest to ensure desired results.

#### **Surface and Air Temperatures**

For maximum effectiveness, surface and air temperatures should be above 40°F (4°C) and below 95°F (35°C). Application on windy days may cause rapid evaporation of the solvent carrier and should be avoided.

#### Equipmen

Recommended application is by high volume, low-pressure (<50 psi) spray. Fit sprayers with solvent-resistant gaskets and hoses to avoid discoloration. Fan spray tips are recommended to avoid atomization. Do not atomize or vaporize the material.

For small scale application, or when spray application is not appropriate, product may be applied using brush or roller. Contact Customer Care or your local PROSOCO representative for more information. Brushes and rollers should be nylon or other synthetic material resistant to solvent solutions.

#### Storage and Handling

Store in a cool, dry place away from potential ignition sources. Keep tightly closed when not dispensing. Published shelf life assumes upright storage of factory-sealed containers in a dry place. Maintain temperature of 45–100°F (7–38°C). Do not double stack pallets. Dispose of unused product and container in accordance with local, state and federal regulations.

## **APPLICATION**

Read "Preparation" and the Safety Data Sheet before use. ALWAYS TEST a small area of each surface to confirm suitability, coverage rates and desired results before starting overall application. Include in the test area any previous repairs and patches,

## Product Data Sheet Weather Seal H40

including aesthetic cementitious finishes. Different surface compositions may result in absorption and/or appearance differences. Test with the same equipment, recommended surface preparation and application procedures planned for general application.

#### Dilution & Mixing

Apply as packaged. Do not dilute or alter.

#### Application Instructions

#### **Vertical Surfaces**

Spray Application

- For best results, apply "wet-on-wet." Spray from the bottom up, saturating with enough material for a 6 to 8 inch rundown below the spray contact point.
- 2. Let the first application penetrate for 5–10 minutes.
- Reapply in the same saturating manner.
   Less material will be required on the second application.

#### Brush or Roller Application

Recommended for small scale application or when spray application is not appropriate. Contact PROSOCO for more information. Take extra care to saturate the surface. Brush out heavy runs and drips that do not penetrate the surface after a few minutes.

Horizontal Surfaces Application: Saturate so the surface stays wet for a few minutes. Thoroughly broom out any pools or puddles that don't completely penetrate.

**Dense Surfaces Application**: Apply a single coat. Use enough to completely wet the surface without creating drips, puddles or rundown. Do not over apply, Always test for proper rate of application.

Strengthening Deteriorated Surfaces: For maximum strengthening benefits, apply H40 in as few as 1 and as many as 3 "cycles." Each cycle consists of 3 consecutive saturating applications applied at 5 to 10 minute intervals. Allow enough time between cycles (30–60 minutes) for penetration of the previous application.

#### **Drying Time**

Protect the treated surface from rain and traffic for 4-6 hours after application. Highly absorbent horizontal surfaces may take several days before the damp appearance is gone. Weather Seal H40 gains its water-repellency properties in 72 hours.

#### Cleanup

Clean tools and equipment immediately with mineral spirits or an equivalent cleaning solvent. Remove over spray and spills as soon as possible.

#### **Painting Treated Surfaces**

Surfaces treated with Weather Seal H40 can be painted over with most high quality, oil-base and acrylic emulsion paints. Testing is always necessary to ensure adhesion.

#### WARRANTY

The information and recommendations made are based on our own research and the research of others, and are believed to be accurate. However, no guarantee of their accuracy is made because we cannot cover every possible application of our products, nor anticipate every variation encountered in masonry surfaces, job conditions and methods used. The purchasers shall make their own tests to determine the suitability of such products for a particular purpose.

PROSOCO, Inc. warrants this product to be free from defects. Where permitted by law, PROSOCO makes no other warranties with respect to this product, express or implied, including without limitation the implied warranties of merchantability or fitness for particular purpose. The purchaser shall be responsible to make his own tests to determine the suitability of this product for his particular purpose. PROSOCO's liability shall be limited in all events to supplying sufficient product to re-treat the specific areas to which defective product has been applied. Acceptance and use of this product absolves PROSOCO from any other liability, from whatever source, including liability for incidental, consequential or resultant damages whether due to breach of warranty, negligence or strict liability. This warranty may not be modified or extended by representatives of PROSOCO, its distributors or dealers.

## CUSTOMER CARE

Factory personnel are available for product, environment and job-safety assistance with no obligation. Call 800-255-4255 and ask for Customer Care – technical support.

Factory-trained representatives are established in principal cities throughout the continental United States. Call Customer Care at 800-255-4255, or visit our website at prosoco.com, for the name of the PROSOCO representative in your area.







# **Blok-Guard® & Graffiti Control WB 6**

Sure Klean® Weather Seal Blok-Guard® & Graffiti Control WB 6 is a clear-drying, water-based silicone emulsion for weather-proofing concrete block and other porous masonry materials, like brick, unglazed terra cotta, porous tile, concrete and some natural stones. Blok-Guard® & Graffiti Control WB 6 protects interior and exterior masonry surfaces from graffiti attacks without altering the natural appearance.

Blok-Guard® & Graffiti Control WB 6 also protects exterior walls exposed to normal weathering. Graffiti removal from treated surfaces is fast and easy using PROSOCO's Graffiti Remover. Blok-Guard® & Graffiti Control WB 6 is easy to apply with low-pressure spray.

# TYPICAL TECHNICAL DATA

| FORM             | White liquid, slight odor                       |  |  |  |
|------------------|---|--|--|--|
| SPECIFIC GRAVITY | 1.00  |  |  |  |
| pН               | 5.4   |  |  |  |
| WT/GAL           | 8.32 lbs  |  |  |  |
| ACTIVE CONTENT   | 6%  |  |  |  |
| TOTAL SOLIDS     | 6% ASTM D 2369                                  |  |  |  |
| VOC CONTENT      | <20 g/L Low Solids Coating                      |  |  |  |
| FLASH POINT      | >212° F (>100° C)<br>ASTM D 3278                |  |  |  |
| FREEZE POINT     | 32° F (0° C)                                    |  |  |  |
| SHELF LIFE       | 1 year in tightly sealed,<br>unopened container |  |  |  |

#### **ADVANTAGES**

- Treated surfaces resist penetration of most types of graffiti.
- Low odor. Excellent UV stability.
- Simplifies graffiti removal.
- Effectively protects hard-to-seal surfaces.
- · Suitable for exterior and interior use.

- Controls rainwater penetration through exterior block walls.
- Resists water penetration when applied over existing shrinkage cracks of 0.02 inches or less.
- Helps control efflorescence, mildew and other moisture-related stains.
- Treated surfaces exhibit excellent surface beading.
- Treated surfaces "breathe" does not trap moisture.

#### Limitations

- May darken or enhance the natural color of some surfaces. Always test to ensure desired results.
- Not appropriate for use on limestone, marble, travertine or other calcareous stones. Always test other natural stone to ensure desired results.
- Not suitable for extremely dense or polished surfaces.
- Not appropriate for application to asphaltic or painted surfaces.
- Not suitable for application to synthetic resin paints, gypsum, plaster or other non-masonry surfaces.
- Not recommended for below-grade applications.
- Will not prevent water penetration through structural cracks, defects or open joints.
- May be difficult to remove from adjacent surfaces. Always protect.
- Not recommended for horizontal surfaces.

# **REGULATORY COMPLIANCE**

#### **VOC Compliance**

Sure Klean® Weather Seal Blok-Guard® & Graffiti Control WB 6 is compliant with the US Environmental Protection Agency's AIM VOC regulations.

Visit www.prosoco.com/voccompliance to confirm compliance with individual district or state regulations.

# Product Data Sheet Weather Seal Blok-Guard® & Graffiti Control WB 6

## **SAFETY INFORMATION**

Always read full label and SDS for precautionary instructions before use. Use appropriate safety equipment and job site controls during application and handling.

24-Hour Emergency Information: INFOTRAC at 800-535-5053

#### **PREPARATION**

Protect people, vehicles, property, plants, windows and all non-masonry surfaces from product, splash, residue, fumes and wind drift. Protect and/ or divert foot and auto traffic.

Surface should be clean, dry and absorbent. If cleaning is necessary, use the appropriate PROSOCO cleaner. Do not use raw acids. Let cleaned surfaces dry completely.

#### Recommended for these substrates. Always test. Coverage is in sq.ft./m. per gallon. Substrate Type Use?Coverage Burnished Architectural Smooth yes 30-100 sq.ft Concrete 3-9 sq.m. Split-faced yes Block Ribbed yes Brick yes Tile yes 75-175 sq.ft. Concrete Precast Panels yes 7-16 sq.m. no Pavers yes Cast-in-place Brick yes yes 50-125 sq.ft Fired Clay Terra Cotta (unglazed) yes 5-12 sq.m. Pavers no Polished no N/A Marble. Travertine. Limestone Unpolished\* no N/A Polished N/A no Granite Unpolished no N/A 100-150 sq.ft. Sandstone Unpolished yes 9-14 sq.m. N/A Unpolished

May darken or enhance the natural color of some surfaces.

\*Weather Seal Blok-Guard\* & Graffiti Control VOC 9 or
Natural Stone Treatment WB Plus may be more suitable
products.

Always test to ensure desired results. Coverage estimates depend on surface texture and porosity. Newly constructed surfaces and re-pointed surfaces should cure for 28 days before application. Sealant and caulking compounds should be in place and cured before application.

The top of walls should be capped and made watertight prior to application.

#### **Surface and Air Temperatures**

Best surface and air temperatures are  $40-95^{\circ}F$  (4-35°C) during use and for 8 hours after. If freezing conditions exist before application, let masonry thaw.

Blok-Guard® & Graffiti Control WB 6's water carrier may freeze at low temperatures or evaporate in high temperatures. Both conditions impair penetration and results.

#### Eauipment

Recommended application is by high volume, low-pressure (<50 psi) spray. Fan spray tips are recommended to avoid atomization of the material.

For small scale application, or when spray application is not appropriate, product may be applied using brush or roller. Contact Customer Care or your local PROSOCO representative for more information.

#### **Storage and Handling**

Store in a cool, dry place. Always seal container after dispensing. Do not alter or mix with other chemicals. Published shelf life assumes upright storage of factory-sealed containers in a dry place. Maintain temperature of  $45\text{--}100^\circ\mathrm{F}$  (7–38°C). Do not double stack pallets. Dispose of unused product and container in accordance with local, state and federal regulations.

#### **APPLICATION**

Read "Preparation" and the Safety Data Sheet before use.

ALWAYS TEST a small area of each surface to confirm suitability, coverage rates and desired results before starting overall application. Test with the same equipment, recommended surface preparation and application procedures planned for general application. Include any previous repairs and patches, including aesthetic cementitious finishes, in the test area. Different surface compositions may result in absorption and/or appearance differences.



# Product Data Sheet Weather Seal Blok-Guard® & Graffiti Control WB 6

#### **Dilution & Mixing**

Do not dilute or alter. Apply as packaged.

#### **Application Instructions**

Lightweight block and porous masonry will need 2 coats. See "Second Coat Application."

#### SprayER Application

- 1. Saturate, "wet-on-wet" spraying from the bottom up. Avoid excessive overlapping. For textured and porous surfaces, apply enough material to create 6–8 inch rundown below the contact point. NOTE: When spray applying to fluted architectural block, spray in an "overlapping X pattern" for complete coverage of recessed surfaces.
- Let first application penetrate masonry surface for 2 to 3 minutes. For textured and porous surfaces, reapply in same saturating manner to ensure complete coverage of recessed surfaces.
- Immediately brush out runs and drips to prevent build up.

#### **Brush or Roller Application**

Recommended for small scale application or when spray application is not appropriate. Contact PROSOCO for more information. Saturate uniformly. Let product penetrate for 2–3 minutes. Re-saturate. Brush out heavy runs and drips that don't penetrate.

#### Dense, Smooth Surface Application

Apply in a single coat using enough to completely wet the surface without creating drips, puddles or rundown. Brush out or back roll all runs and drips for uniform appearance. Do not over apply. Over application may cause unacceptable color change. One application is normally enough. Always test for application rate.

#### **Second Coat/Porous Surfaces Application**

Some surfaces will need an additional coat of Blok-Guard® & Graffiti Control WB 6 for maximum protection. Apply the second wet-on-wet coat as soon as the first application is dry to the touch or within one hour. Immediately back roll or brush out runs and drips for a uniform appearance and to prevent build up.

Allowing more than one hour between coats could reduce the effectiveness of the second coat or cause darkening.

#### leanup

Clean tools, equipment, and over spray with soap and warm water. Cleanup is more difficult from surfaces hotter than 95°F (35°C).

#### Drying Time

In normal weather (60–80°F; [16–27°C] 50% humidity), Blok-Guard® & Graffiti Control WB 6 dries to the touch in about 1 hour. Drying takes longer at lower temperatures.

Blok-Guard® & Graffiti WB 6 Control gains its water-repellency properties in 24 hours. Graffiti resistance properties fully develop in 3 to 5 days, depending upon climate conditions. Protect treated surfaces from rain for at least 6 hours after application.

#### **Graffiti Removal**

Remove most types of graffiti with PROSOCO's Graffiti Remover or SafStrip®. See product literature or call Customer Care at 800-255-4255.

#### WARRANTY

The information and recommendations made are based on our own research and the research of others, and are believed to be accurate. However, no guarantee of their accuracy is made because we cannot cover every possible application of our products, nor anticipate every variation encountered in masonry surfaces, job conditions and methods used. The purchasers shall make their own tests to determine the suitability of such products for a particular purpose.

PROSOCO, Inc. warrants this product to be free from defects. Where permitted by law, PROSOCO makes no other warranties with respect to this product, express or implied, including without limitation the implied warranties of merchantability or fitness for particular purpose.

The purchaser shall be responsible to make his own tests to determine the suitability of this product for his particular purpose. PROSOCO's liability shall be limited in all events to supplying sufficient product to re-treat the specific areas to which defective product has been applied. Acceptance and use of this product absolves PROSOCO from any other liability, from whatever source, including liability for incidental, consequential or resultant damages whether due to breach of warranty, negligence or strict liability. This warranty may not be modified or extended by representatives of PROSOCO, its distributors or dealers.







# **Breathable Masonry Coating II**

Breathable Masonry Coating (BMC®) II combines the beauty of high-quality paint with the protective power of breathable water repellents. BMC® II lets water vapor escape from masonry, while stopping destructive liquid water from entering. The masonry's appearance is preserved, and its service life is prolonged. BMC® II's unique silicone emulsion formulation makes the coating more resistant to weathering (UV, moisture and soiling) and so more durable and lasting than most conventional paints.

BMC° II dries to an attractive flat finish. It's compatible with the CCE ColorCast Ecotoner colorant system for achieving predictable color matches. BMC° II is available in four different bases, allowing for the greatest range of colors: Pastel, Tint, Deep and Accent. BMC bases are ready to use or can be custom tinted by local distributors. Call PROSOCO Customer Care at 800-255-4255 for your local distributor or for additional information about BMC° II.

## REGULATORY COMPLIANCE

#### **VOC Compliance**

BMC® II bases are compliant with the US Environmental Protection Agency's AIM VOC regulations.

Visit www.prosoco.com/voc-compliance to confirm compliance with individual district or state regulations.

#### SAFETY INFORMATION

Always read full label and SDS for precautionary instructions before use. Use appropriate safety equipment and job-site controls during application and handling.

24-Hour Emergency Information: INFOTRAC at 800-535-5053

#### ΔΟΥΔΝΤΔGFS

- Specifically designed for use on masonry substrates.
- · Highly vapor permeable.
- Meets and exceeds requirements of ASTM E 2357.
- Field-proven technology used on the U.S. Capitol and other U.S. and European landmarks.
- · Excellent UV stability and hiding.
- Easy application with roller, brush or spray.
- No primer needed.
- · Silicone emulsion formula resists soiling.
- · Good adhesion. Exceptional color retention.
- Ideal for interiors or exteriors. No harsh odors.
- Complies with all known national and state AIM VOC regulations.

#### Limitations

- Not for use on horizontal surfaces subject to vehicular or pedestrian traffic.
- · Not suitable for application on some resin paints.
- Manufacturer does not endorse use of organic colorants. Use of organic colorants for color matching may result in color fading.

# Product Data Sheet BMC® II

# TYPICAL TECHNICAL DATA

| FORM                        | White viscous batter-like liquid with mild odor  |  |  |  |
|-----------------------------|--|--|--|--|
| SPECIFIC GRAVITY            | 1.41 Pastel Base<br>1.38 Tint Base<br>1.28 Deep Base<br>1.22 Accent Base                     |  |  |  |
| pН                          | 9.0-10.0   |  |  |  |
| WT/GAL                      | 11.76 lbs Pastel Base<br>11.55 lbs Tint Base<br>10.66 lbs Deep Base<br>10.15 lbs Accent Base |  |  |  |
| PERCENT SOLIDS BY<br>WEIGHT |  |  |  |  |
| PERCENT SOLIDS BY<br>VOLUME | 38 Pastel Base<br>38 Tint Base<br>34 Deep Base<br>31 Accent Base                             |  |  |  |
| VOC CONTENT                 | 100 g/L, maximum   |  |  |  |
| FLASH POINT                 | >200°F (>93°C)<br>ASTM D 3278  |  |  |  |
| FREEZE POINT                | 32°F (0°C)   |  |  |  |
| SHELF LIFE                  | 1 year in tightly sealed,<br>unopened container  |  |  |  |

#### **PREPARATION**

Protect people, vehicles, property, metal, and all surfaces not set for coating from product, residue, splash, fumes and wind drift. Use drop cloths or other proven protective material. Protect and/or divert foot and vehicle traffic.

Surfaces must be clean, dry and absorbent. Correct the causes of moisture-related stains before application. Thoroughly clean efflorescence, algae and other moisture-related stains. In coastal areas, check for salt contamination. Call PROSOCO Customer Care for cleaning recommendations.

Roughen or abrade glazed or glossy surfaces for proper adhesion before application.

BMC® II needs no primer, though a priming coat may be applied if desired. Use Sure Klean® Weather Seal Siloxane WB Concentrate at a dilution ratio of one part product to 19 parts water. Apply BMC® II within 48 hours of primer application.

| Recommended for these substrates. Always test.<br>Coverage is in sq.ft./m. per gallon.            |   |                          |                               |  |  |
|---|---|--------------------------|-------------------------------|--|--|
| Substrate   | Type  | Use?                     | Coverage                      |  |  |
| Architectural<br>Concrete<br>Block  | Burnished<br>Smooth<br>Split-faced<br>Ribbed      | yes<br>yes<br>yes<br>yes | 100–150 sq.ft.<br>9–14 sq.m.  |  |  |
| Concrete  | Brick Tile Precast Panels Pavers Cast-in-place    | yes<br>yes<br>yes<br>yes | 100–300 sq.ft.<br>9–28 sq.m.  |  |  |
| Fired Clay  | Brick<br>Tile<br>Terra Cotta (unglazed)<br>Pavers | yes<br>yes<br>yes        | 150–350 sq.ft.<br>14–33 sq.m. |  |  |
| Marble,   | Polished  | no                       | N/A                           |  |  |
| Travertine,<br>Limestone  | Unpolished  | yes                      | 100–300 sq.ft.<br>9–28 sq.m.  |  |  |
| Granite   | Polished  | no                       | N/A                           |  |  |
|   | Unpolished  | yes                      | 100–300 sq.ft.<br>9–28 sq.m.  |  |  |
| Sandstone   | Unpolished  | yes                      | 100–250 sq.ft.<br>9–23 sq.m.  |  |  |
| Slate   | Unpolished  | yes                      | 100–350 sq.ft.<br>9–33 sq.m.  |  |  |
| Always test to ensure desired results. Coverage estimates depend on surface texture and porosity. |   |                          |                               |  |  |

#### Surface & Air Temperatures

Do not apply if temperatures are colder than  $40^{\circ}F$  ( $4^{\circ}C$ ), or expected to be within 24 hours. Do not apply to surfaces hotter than  $95^{\circ}F$  ( $35^{\circ}C$ ).

#### Fauinment

Apply with roller, brush or airless sprayer.

#### Storage & Handling

Keep from freezing. Store in a cool, dry place. Always seal container after dispensing. Do not alter or mix with other chemicals. Published shelf life assumes upright storage of factory-sealed containers in a dry place. Maintain temperature of 45-100°F (7-38°C). Do not double stack pallets. Dispose of unused product and container in accordance with local, state and federal regulations.



# Product Data Sheet BMC® II

#### APPLICATION

Before use read "Preparation" and the Safety Data Sheet. ALWAYS TEST each type of surface for suitability and results before overall application. Include in the test area any previous repairs and patches, including aesthetic cementitious finishes. Different surface compositions may result in absorption and/or appearance differences. Test using the following application instructions. Let tests dry thoroughly before inspection.

#### Dilution

Do not alter or dilute except for use in sprayers. The concentrate may need thinning with up to 5 percent fresh water, based on surface and drying conditions, and equipment.

Mix well before use.

#### **Color Uniformity**

BMC® II from multiple containers must be "boxed" (mixed) to ensure color uniformity.

#### **Application Instructions**

- Apply a smooth, uniform coating, 7 wet mils thick. Work from the top down. Brush out runs or drips. Back roll spray applications for proper adhesion and good coating performance.
- 2. Let first coat dry 2-4 hours
- 3. Reapply. The second coat should be 4 mils thick.

#### **Drying Time**

Protect from rain for at least 6 hours or until coating is thoroughly dry.

At 77°F (25°C) and 50% relative humidity, coating dries to the touch in approximately 45 minutes. Allow 2 hour dry time before recoating. Coating dries completely in 48 hours.

#### Cleanup

Clean equipment with warm water and mild detergents. Use solvent paint thinner to remove dried-on BMC $^{\circ}$  II.

#### WARRANTY

The information and recommendations made are based on our own research and the research of others, and are believed to be accurate. However, no guarantee of their accuracy is made because we cannot cover every possible application of our products, nor anticipate every variation encountered in masonry surfaces, job conditions and methods used. The purchasers shall make their own tests to determine the suitability of such products for a particular purpose.

PROSOCO, Inc. warrants this product to be free from defects. Where permitted by law, PROSOCO makes no other warranties with respect to this product, express or implied, including without limitation the implied warranties of merchantability or fitness for particular purpose. The purchaser shall be responsible to make his own tests to determine the suitability of this product for his particular purpose. PROSOCO's liability shall be limited in all events to supplying sufficient product to re-treat the specific areas to which defective product has been applied. Acceptance and use of this product absolves PROSOCO from any other liability, from whatever source, including liability for incidental, consequential or resultant damages whether due to breach of warranty, negligence or strict liability. This warranty may not be modified or extended by representatives of PROSOCO, its distributors or dealers.


## **CUSTOMER CARE**

Factory personnel are available for product, environment and job-safety assistance with no obligation. Call 800-255-4255 and ask for Customer Care – technical support.

Factory-trained representatives are established in principal cities throughout the continental United States. Call Customer Care at 800-255-4255, or visit our website at www.prosoco.com, for the name of the PROSOCO representative in your area.












Vieux Carre Commission February 16, 2022



Vieux Carre Commission





















521 Dauphine

February 16, 2022



February 16, 2022





















521 Dauphine, 1858 sketch















- (III)








1236 N Rampart, 1022 Barracks St











1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St






1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St








PROPOSED GALLERY SECTION

SCALE: 4" = 1'-0"

DESIGN REFERENCE: EXISTING BALCONY SUPPORT ON BURGUNDY ST SIDE

1236 N Rampart, 1022 Barracks St

February 16, 2022



STRUCTURAL DETAIL OF MANSION GALLERY SUPPORT 6/13/2023

1236 N Rampart, 1022 Barracks St






1236 N Rampart, 1022 Barracks St











1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St



February 16, 2022



1236 N Rampart, 1022 Barracks St






1236 N Rampart, 1022 Barracks St



February 16, 2022



1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St






1236 N Rampart, 1022 Barracks St






1236 N Rampart, 1022 Barracks St






1236 N Rampart, 1022 Barracks St






1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St

TABLISHED 19




1236 N Rampart, 1022 Barracks St






1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St






1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St






1236 N Rampart, 1022 Barracks St



Vieux Carre Commission




1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St






1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St

ARE COMMANDED TO THE CO



1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St





1236 N Rampart, 1022 Barracks St




February 16, 2022


Vieux Carre Commission



1236 N Rampart, 1022 Barracks St












Vieux Carre Commission




1236 N Rampart, 1022 Barracks St

THE COMMON TO TH










1236 N Rampart, 1022 Barracks St



**Front** 



FIXTURE '10' DOWNLIGHT



# Cylinder series

**Outdoor Ceiling Mount** 

### Dimensions

- 7.00 H x 4.25 W
- Canopy: 4.25 W

#### Finish & Materials

Oiled Bronze

## Lamping/Electrical

- · Damp Listed
- 1 light
- 75 watt
- Medium Base


201 Railhead Road, Fort Worth, TX 76106 - Tel. (817) 626-5483 - www.QuorumInternational.com

Please be advised that all information shown here is subject to verification by Quorum. In the event of a discrepancy, we reserve the right to make any

1236 N Rampart, 1022 Barracks St

February 16, 2022


**Vieux Carre Commission** 



1236 N Rampart, 1022 Barracks St







619-21 Toulouse



February 16, 2022



619-21 Toulouse

















619-21 Toulouse









Vieux Carre Commission February 16, 2022



619-21 Toulouse





619-21 Toulouse





619-21 Toulouse






619-21 Toulouse



















619-21 Toulouse
















Vieux Carre Commission February 16, 2022












$$\frac{\text{SECTION}}{1" = 1'-0"} \underbrace{2}_{\text{S1S1}}$$






 $\frac{\text{PLAN VIEW OF BALCONY}}{1/2" = 1'-0"}$ 







$$\frac{\text{SECTION}}{1" = 1'-0"} \underbrace{\begin{array}{c} 2 \\ \text{S2S2} \end{array}}$$



$$\frac{\text{PLAN VIEW OF BALCONY}}{1/2" = 1'-0"}$$





500 Bourbon


































































EXISTING BOURBON ST. ELEVATION


CBD | ARCHITECTS

CHICAGO . MIAMI . NEW ORLEANS info@cbdarchitects.com






















Vieux Carre Commission February 16, 2022















## PROPOSED BOURBON ST. ELEVATION - OPTION D

SCALE: 3/32"= 1'-0

(NO MODIFICATIONS TO EXISTING FACADE OR FLOOR HEIGHTS, NON-CONTINUOUS GALLERY ONLY. RAILING TYPE E)




HICAGO . MIAMI . NEW ORLEANS info@cbdarchitects.com










## PROPOSED BOURBON ST. ELEVATION - OPTION E

SCALE: 3/32\*= 1'4

(NO MODIFICATIONS TO EXISTING FACADE OR FLOOR HEIGHTS, BALCONY ONLY. RAILING TYPE F)












February 16, 2022















#### PROPOSED REVISIONS TO VCC DESIGN GUIDELINES

Currently, the design guidelines define a **roof top addition** as any new construction on top of an existing rooftop for occupied or unoccupied space, and includes a full-floor addition. This definition should be revised to include "occupied, finished space designed to accommodate outdoor commercial or residential living space including, but not limited to, furniture, landscaping, lighting, etc., all of which must be reviewed and approved by VCC."

Roof deck should be defined as, generally, a platform built above the roof structure, capable of supporting weight, similar to a floor and connected to the main building by stairs and possibly an elevator. It is typically enclosed by a railing or parapet for safety.

Based on research of how other similar historic districts have regulated this condition, we also propose that **food** must be served in such activated, commercial, open-air rooftop additions, not just alcohol, and no rooftop space can be occupied after 10:00 pm. Noise must not exceed prescribed decibel levels, reading to be taken at 5' above deck. No amplified music nor speakers shall be allowed.

For properties located adjacent to residential areas, approved screens, walls, shutters, or other devises shall be required to restrict visual access to the residential units.

Illumination of the activated, open-air rooftop addition shall be restricted to avoid lights that focus outward or upward and should limit spillage of light from the deck.

Guidelines should explicitly indicate that rooftop decks that are highly visible are strongly discouraged. Such

#### ROOFTOP ADDITIONS

### THE VCC REQUIRES:

- Compliance with the Comprehensive Zoning Ordinance (CZO) – A rooftop addition shall not require a variance for height limit or floor area ratios
- Review of all exterior items located on a roof surface including paving, railings and built-in furnishings

#### THE VCC DOES NOT RECOMMEND:

- A rooftop addition on a Green, Pink or Yellow rated building
- A rooftop addition on a building of less than three full stories in height

#### THE VCC DOES NOT ALLOW:

- · A rooftop addition on a Purple or Blue rated building
- A rooftop addition on a building originally constructed as a residential building
- A rooftop addition on a roof with a pitch greater than 3-inches vertically in 12-inches horizontally and an existing parapet less than 18-inches in height – Except at a camelback shotgun
- A roof addition greater than one story and/or 12'-0" in height or with a roof form other than a flat or lowsloped roof – Excluding an elevator override

additions to historic buildings shall be located to the rear of the structure or the most inconspicuous side of the building. Additions to roofs shall not be visible from the front elevation.

To be added to VCC Design Guidelines 14:17 Design Standards for Rooftop Addition Review (at left):

- Activated, open-air rooftop additions shall comply with all Rooftop Addition requirements and recommendations shown on VCC Design Guidelines.
- No activated, open-air rooftop addition shall be allowed such that accessory structures (stair, elevator, etc.) would exceed the max. height allowable as per the CZO.



#### **ROOFTOP ADDITIONS**

As most buildings in the Vieux Carré were built at or close to their property lines, it is often not possible to expand a building's footprint. As a result, some property owners hope to add new space on top of an existing building. The two types of additions on top of an existing building are a camelback and a rooftop addition.

- Camelback: The camelback is a traditional addition design for a wood frame shotgun or shotgun double (Refer to Shotgun, Guidelines for Architectural Building Types & Architectural Styles, page 02-8) - A traditionally designed camelback proposed for a wood-framed shotgun building is not subject to the more rigourous submittal requirements for a rooftop addition; however, it must be compatible with the existing building (Refer to Principles for Additions, page 14-11)
- Rooftop Addition: A rooftop addition is defined as any new construction on top of an existing rooftop for occupied or unoccupied space, and includes a full-floor addition

A rooftop addition is a way to increase the square footage and floor area ratio of an existing masonry building in the Vieux Carré. This method of adding space to a building predominantly occurs between Bourbon Street and the river where conversion of a commercial or warehouse building to residential use is common. In considering a proposed rooftop addition, the VCC considers the historic integrity of the original structure and surrounding area. It is equally important that an addition, when appropriate and allowed, contribute to the character of the area and respect the design and context of the building and its streetscape.

When reviewing a proposal for a rooftop addition, the VCC evaluates the application on a case by case basis. An approved rooftop addition at one location should not be considered a precedent or construed to mean that a similar proposal for another property will be approved. Factors considered by the VCC in its review include:

- . The significance of the building or site as defined by its color rating
- The location of the building and site
- The height of the existing building, the proposed addition and surrounding buildings - It must also meet zoning requirements including height and setback
- The visibility of the proposed addition
- · The architectural treatment of the proposed addition and its compatibility with the existing building - it should not be obtrusive or detract from the architecture of the existing building or the surrounding Vieux Carré Historic District, streetscape or adjacent buildings.

#### **ROOFTOP ELEMENTS**

The VCC has jurisdiction over roof-mounted equipment and rooftop decks, including paving and semi-permanent furnishings. (Refer to Roof Mounted Equipment, Guidelines for Roofing, page 04-11, and Outdoor Furnishings, Guidelines for Site Elements & Courtyards, page 10-9.)



camelback addition typically is found on a woodframed shotaun single or double.




This rooftop addition is set back from the building corner on both sides and has a flat roof without permanent projecting overhangs. The metal railing is nominally visible to pedestrians.

## ROOFTOP ADDITIONS SUBMITTAL REQUIREMENTS

In addition to the submission requirements identified in the New Construction & Addition Review (page 14-2), the following information is required for each application for a rooftop addition:

- · Dimensioned elevations and plans showing the proposed rooftop addition on the existing building
- · Sight-line studies, either photographs or drawings, illustrating the massing of the proposed addition and visibility in all directions, and showing not only the impact on the subject building, but also on the adjacent buildings and the Vieux Carré as a whole
- · A scaled massing model of the addition on the existing building that includes adjacent buildings
- · A section through the building to the boundary of the property on the other side of the street

14-16 Vieux Carré Commission - Guidelines for New Construction, Additions & Demolition



A rooftop addition must be set back from the street walls of the existing building by a minimum of the proposed height of the addition, (i.e. 12'-0" high rooftop addition must be set back from the street wall a minimum of 12'-0".) The VCC discourages a rooftop addition on a building less than three full stories in height because of the increased likelihood of visibility.

## DESIGN STANDARDS FOR ROOFTOP ADDITION REVIEW

If allowable by the Comprehensive Zoning Ordinance (CZO) and appropriate at a particular site, the VCC uses specific design standards to review a rooftop addition proposal. In its review of a proposed rooftop amenity or addition, the VCC:

- · Strives to make a rooftop addition, including an elevator and mechanical equipment, as well as furnishings as unobtrusive and minimally visible as possible
- · Limits the overall height of a rooftop addition, including framing and parapet, to 12'-0" above the lowest surface of the existing roof, except for code-required components, such as an elevator override
- · Requires that a rooftop addition be set back from the street façade(s) of the building by a minimum of the overall height of the proposed addition (i.e., a 12'-0" high rooftop addition should be set back from the street wall a minimum of 12'-0")
- Requires that a rooftop addition incorporate elevator. mechanical and HVAC equipment within the single story and allowable addition footprint
- · Requires that all furnishings including railings, screens, planters, plants and permanent rooftop furnishings taller than the closest parapet be setback from the street wall(s) a minimum of the height of the proposed furnishing from the lowest roof surface
- · Considers a proposal for a rooftop addition that does not conform to these Guidelines at a Green, Pink or Yellow rated building under limited circumstances; however, excellence in design and the architectural character of the existing building are strong factors in the review

#### **Rooftop Addition Review**

Construct a rooftop addition 1 2 3

Commission

#### **ROOFTOP ADDITIONS**

#### THE VCC REQUIRES:

- · Compliance with the Comprehensive Zoning Ordinance (CZO) - A rooftop addition shall not require a variance for height limit or floor area ratios
- Review of all exterior items located on a roof surface including paving, railings and built-in furnishings

#### THE VCC DOES NOT RECOMMEND:

- · A rooftop addition on a Green, Pink or Yellow rated
- A rooftop addition on a building of less than three full stories in height

#### THE VCC DOES NOT ALLOW:

- · A rooftop addition on a Purple or Blue rated building
- A rooftop addition on a building originally constructed as a residential building
- · A rooftop addition on a roof with a pitch greater than 3-inches vertically in 12-inches horizontally and an existing parapet less than 18-inches in height - Except at a camelback shotgun
- A roof addition greater than one story and/or 12'-0" in height or with a roof form other than a flat or lowsloped roof - Excluding an elevator override

Vieux Carré Commission - Guidelines for New Construction, Additions & Demolition 14-17

500 Bourbon



Vieux Carre Commission February 16, 2022



A first floor remnant of the old St. Louis Hotel remains to the right. In 1960, a larger hotel was constructed, incorporating the remnant, with compatible arched ground floor openings and storefront cornice.

#### COMPATIBLE DESIGN PRINCIPLES

The development of the Vieux Carré followed its own pattern and rhythm. As the heart of New Orleans, the heritage and culture of the French Quarter's early inhabitants are expressed through the architectural and built environment. To continue the District's evolution, the VCC encourages design excellence and creative design solutions for a new construction and/or an addition that are sensitive to the character of their historic surroundings. Generally, there are three appropriate design approaches in the Vieux Carré:

- Reconstruction: A design that faithfully duplicates details and materials based upon clear documentary evidence
- Traditional: A design that could have been constructed on a property for which there is insufficient evidence
- Present Day: A contemporary design compatible within the context of the property and neighboring sites

The approach, style and type of compatible new construction or an addition will vary at each site depending on the specific context. The approach for an addition or new secondary building is guided by the architectural and historical importance of the property as identified by its color rating. Recognizing that what might be appropriate at one property is not appropriate at another, the VCC does not mandate specific design "solutions" for new construction or an addition. However, when determining the appropriateness of a new construction or an addition, the VCC is guided by *The Secretary of the Interior's Standards* and the general design principles below.


| DESIGN PRINCIPLES                          | NEW CONSTRUCTION & ADDITIONS   |
|--|--|
| Scale: Height & Width                      | Proportions and size of the new building/addition compared with neighboring buildings/existing building  |
| Building Form & Massing                    | The three-dimensional relationship and configuration of the new building/addition footprint, its walls and roof compared with neighboring buildings/existing building  |
| Setback                                    | Distance of the new building/addition to the street or property line when compared with other buildings on the block/existing building   |
| Site Coverage                              | Percentage of the site that is covered by a building/addition, when compared to nearby sites of compatible size  |
| Orientation                                | Location of the front of the new building/addition and principal entrance relative to other buildings on the block   |
| Alignment, Rhythm & Spacing                | Effect the new building/addition will have on the existing patterns on its block   |
| Architectural Elements & Projections       | Size, shape, proportions and location of each entrance, balcony, gallery, porch, roof overhang, chimney, dormer, parapet and other elements that contribute to the building's overall shape and silhouette relative to neighboring buildings |
| Façade Proportions: Window & Door Patterns | Relationship of the size, shape and location of the new building/addition façade and building elements to each other, as well as when compared to other buildings on the property, block/existing building                                   |
| Trim & Detail                              | Mouldings, decorative elements and features of a building that are secondary to major surfaces such as walls and a roof and how they relate to the neighboring buildings/existing building   |
| Materials                                  | Products with which an addition or new building is composed or constructed and how these relate to neighboring buildings/existing building   |

14-4 Vieux Carré Commission – Guidelines for New Construction, Additions & Demolition









1020 Orleans



# 1020 Orleans






Vieux Carre Commission













1020 Orleans Ave. NOLA





918-20 Bourbon





918-20 Bourbon


















# 1118 Decatur 25 French Market Place



## 1128 Decatur and 25 French Market Place



Vieux Carre Commission February 16, 2022






Vieux Carre Commission











1118 Decatur





Vieux Carre Commission February 16, 2022



1118 Decatur







611 Ursulines





611 Ursulines





611 Ursulines












Vieux Carre Commission













1113 Chartres, 1900

Vieux Carre Commission










1113 Chartres, 1934 HABS

DOUGLASS V. FRERET, Del.

**Vieux Carre Commission** 





N · E · SIDE ELEVATION




1113 Chartres






1<u>113 Chartres</u>
Vieux Carre Co





































910 Royal















910 Royal













910 Royal

















TAMESHED 83



717 Orleans – ca. 1900







717 Orleans – ca. 1940s





717 Orleans – 1964





























717 Orleans




ON THE COMMANDER OF THE













TAMESHED OF



A2.18C


February 16, 2022


Vieux Carre Commission




TABLISHED S








April 11, 2023 **VCC Architecture Committee** 




















VCC Architecture Committee April 11, 2023













327 Bourbon





### 1ST FLOOR NORTH WALL

Brick point
Possibly need to fill in left side opening
to the left
Lintel repair



### 1ST FLOOR WEST WALL

Brick point behind electrical panel wall







2ND FLOOR EAST WALL

Brick pointing Lintel repair



## 2ND FLOOR NORTH WALL

Brick pointing Lintel repair








3RD FLOOR NORTH WALL

Brick pointing Lintel repair



# 3RD FLOOR WEST WALL

Brick pointing Brick/Wood infill







### 4TH FLOOR SOUTH WALL

Brick pointing Lintel repair



### 4TH FLOOR EAST WALL

Brick pointing Lintel repair















VCC Architecture Committee April 11, 2023





1216 Burgundy

VCC Architecture Committee
































April 11, 2023







April 11, 2023







Typical  $19^{th}$  century double hung windows throughout the house have vertical rectangular lites with narrow 5/8" muntin bars with a 1/4" bone, most openings in 1216 Burgundy are either double hung windows or French doors. All have a typical Greek Revival interior casing w/ bullnosed sill.



The ground floor kitchen windows while historic were installed in a later period with 7/8" muntin bars with a 3/8" bone. The shaped profile on the sides of the muntins is similar.





April 11, 2023



The front windows retain their historic character



1216 Burgundy



While the muntin bars of the front street level windows were cut likely in the early 20<sup>th</sup> century in an attempt to update the windows to more of a Craftsman appearance.



The rear opening on the main block of the house that I am proposing new sash for is not the same period as the earlier openings of the house, however does match the muntin and bone for the kitchen windows. The existing historic transom has 7/8" muntin bars w/ a 3/8" bone.








VCC Architecture Committee April 11, 2023

The earliest openings have a narrower 5/8" muntin with a 1/4" bone.




The bathroom window in question is immediately adjacent to a French door to the service wing balcony. The lower sash were removed at some point in the modern era and plate glass window and stops were added.








The 1940's HABS documents this window was once in the stairwell.



The stair has been relocated towards the front of the house at some point in the mid 1900's to create a bathroom on the second floor and a dining room on the first floor.



1216 Burgundy



There were sales in 1921, 1930, 1932, 1941, and 1950, 1951, 1952, 1955, and 1958 with the City owning it from 1937-41, and again in 1946. I doubt the city would have done a whole stair move, so the other dates would most likely coincide with the transom sash. The house wasn't sold again until 1993.

This window also matches the upper sash of the front dormer in character, there is no documentation on when the dormer was built or if it was original to the house.





The frame of the window is beaded and historic, although perhaps not period to the house. The original sill has previously been replaced, but new work has been done to secure the glass, perhaps after Hurricane Ida?



The transom sill if original to the house would likely have had a shaped nosing, it gas either been replaced or installed in the mid  $20^{th}$  century as-is.



1216 Burgundy



On the interior side it appears the historic frame is viable. The rabbet had been filled with a trim piece to cover the original hinge locations.



Removing this interior filler strip revealed the original hinge locations documenting that it was a casement window and not a double hung like the other windows.

The upper 2 1/2" hinge is 4 7/8" from the top of the hinge to the head of the frame.












1216 Burgundy




The following sash options were looked at. Double hung was eliminated once the hinge locations were found on the historic window frame. Given the late 1820's early 1830's date attributed to the house, square lites were also looked at but decided against as no other openings in the house had square lites, all are vertical and rectangular of similar proportions to the 3 lites tall version.







It was noted that this window has the same interior sill bullnosed stool profile, missing the 1x4 board underneath.



The interior casing trim profile does not match the profile of the earlier windows and doors such as the adjacent French door in the bathroom to the rear balcony, this points that it is a later historic modification, most likely to an earlier taller window due to the stair having been moved.



1216 Burgundy



VCC Architecture Committee April 11, 2023

Exterior view of the window with sash proposed to be replaced. In this view, you can also see the upper arched sash of the dormer which inspired this later historic window.










## **INTERIOR ELEVATION**

CALE: I" = I'-0"


























515-19 Toulouse 531 Toulouse 516 Wilkinson




VCC Architecture Committee

April 11, 2023



































































































VCC Architecture Committee April 11, 2023




515 Toulouse




























April 11, 2023















VCC Architecture Committee April 11, 2023











515 Toulouse





































515 Toulouse – previous crack





515 Toulouse – previous crack









515 Toulouse

ARLISHED 93












515 Toulouse



515 Toulouse – previous crack



April 11, 2023












515 Toulouse











































































































February 13, 2023

· CIVIL

· STRUCTURAL

1112 112 112

. MARIN

Ms. Lori Mitchell 212 B Brickell Way Lafayette, Louisiana 70508

> Existing Commercial Building 515 & 517 Toulouse Street New Orleans, Louisiana 70130 Report of Findings - Subsequent Report and Recommendations

Dear Ms. Mitchell:

In accordance with your request, we completed a subsequent limited structural visual observation in an effort to address specific concerns as it relates to the overall structural condition of the building. We understand those concerns to be the following.

- Crack repair (interior)
- Water intrusion
- Structural condition of select wooden members

#### Cracks in Masonry Wall

The cracking in the masonry wall is stable in its present condition. We understand that there are concerns about the condition of the wall as it relates to said cracks. We recommend that the cracks be repaired as a matter of course. We also recommend that the cracks be repaired prior to any work being done on the exterior masonry.

### Water Intrusion

As we stated in our initial report, there is water infiltration into the building. We recommend that you hire a qualified roofing contractor to assess the envelope, and make recommendations on arresting the water intrusion, hence rendering the building watertight.

#### Floor Joists

There are several joists and portions of floor decks that are degraded/deflected due to water infiltration. We recommend that the building envelope be secured (see previous bullet point) and these areas blocked from pedestrian access until such a time that the building is under comprehensive renovation. These isolated condtions have not degraded the overall general structural condition of the building.

0:\Carubba\2023\Inspections\2023.01.16 515 & 517 Toulouse Street\Documents\2023.02.13 Report Subsequent.doc

3400 Hessmer Avenue Metairie, LA 70002

#### Conclusion

Per our previous report, the buildings are structurally sound in their present condition, notwithstanding the isolated conditions noted herein. When the building is renovated, we strongly recommend that the owner hire a qualified structural engineer to address the isolated conditions noted herein and provide the requisite information for their repair. We also recommend that a qualified waterproofing expert examine the roof system closely and also provide a scope of work to restore the building envelope to an acceptable level of integrity. We recommend that renovation work begin at the earliest possible time as the building is structurally sound in its present condition.

Thank you for the opportunity to provide this information to you. Please contact our office if you need further assistance. We reserve the right to amend this report if additional information becomes available.

Respectfully,

Carubba Engineering, Inc.

5/18, M. CARUBBA P. No. 84653

Roy M. Carubba, P.E. w/ attachments

O:\Carubba\2023\Inspections\2023.01.16 515 & 517 Toulouse Street\Documents\2023.02.13 Report Subsequent.doc





## 515 Toulouse - tan front


- Roof:
  - replace missing ridge caps
  - replace missing copper flashing
- replace missing slate to match existing –as needed
- 2x copper downspouts with 2x cast iron boots see drawing 1
- 1x window dormer replacement see drawing 2
- Cosmetic work:
  - · repoint brick as needed
  - remove vegetation

## 516 Wilkinson - rear

- Roof:
  - · replace missing ridge caps
  - · replace missing copper flashing
  - · replace missing slate to match existing -as needed
- 1x copper downspout with cast iron boot see drawing 1
- Brick Arch: repair and replace wrong size bricks with hard tan jumbo brick

# 519 Toulouse - pink


- Front:
  - · repoint bricks on façade
  - · paint building pink to match existing
  - · remove graffiti
  - remove vegetation
  - repair windows and trim paint trim cream white
- Rear (Wilkinson):
  - Replace double doors with door with panels see drawing 3
  - Replace PVC downspout boot with cast iron boot
  - Repoint bricks as needed
  - Remove vegetation
  - Paint to match existing color



S cale 1"= 1

# 515 Toulouse






| scale: |1" = 1'


515 Toulouse








515 Toulouse






515 Toulouse




















729-31 Conti


**VCC** Architecture Committee




729-37 Conti




729-37 Conti




729-37 Conti





































April 11, 2023


































April 11, 2023







































































































# VICINITY MAP



## **PROJECT INFO**

#### OWNE

CAJUN CUISINE LLC 5828 MARCIA AVE NEW ORLEANS, LA 70124

#### APPLICANT

WEBRE CONSULTING 2131 BIENVILLE ST NEW ORLEANS, LA 70112 (504) 605-3699

# SHEET INDEX

|   | Sheet Number | Sheet Name                     | Sheet Issue Date |
|---|--------------|--------------------------------|------------------|
| 1 | A0.0         | TITLE SHEET                    | 05/26/2023       |
| 2 | A1.0         | SITE PLAN                      | 05/26/2023       |
| 3 | A2.0         | FACADE ELEVATIONS              | 05/26/2023       |
| 4 | A3.0         | BUILDING SECTIONS              | 05/26/2023       |
| 5 | A4.0         | ADDITIONAL DETAILS + SCREENING | 06/27/2023       |
| 6 | A5.0         | HVAC SCHEDULE + PHOTOS         | 06/27/2023       |
| 7 | A6.0         | FIRST FLOOR PHOTO KEY          | 05/30/2023       |
| 8 | A7.0         | SECOND FLOOR PHOTO KEY         | 05/30/2023       |
| 9 | A8.0         | THIRD FLOOR PHOTO KEY          | 05/30/2023       |

# FACADE IMAGES



# PROPERTY INFO

## PARCEL IDS

737-CONTIST 733-CONTIST 729-CONTIST

## TAX IDS

206102719 206102720 206102721

### **ZONING DISTRICT**

VCC-2 VIEUX CARRE COMMERCIAL

### **FUTURE LAND USE**

MU-HC MIXED USE HISTORIC CORE

## INTERIM ZONING DISTRICTS

RESIDENTIAL SHORT TERM RENTAL IZD BED AND BREAKFAST IZD

#### HISTORIC DISTRICTS

VIEUX CARRE LOCAL HISTORIC DISTRICT
VIEUX CARRE NATIONAL REGISTER DISTRICT

## GENERAL NOTES

- THE SCOPE IN THIS SUBMITTAL COMPRISES PHASE 1 OF THE RESOLUTIONS OF VCC VIOLATIONS, ADDRESSING THE LIFE SAFETY DEFICIENCES/CONCERNS AS IDENTIFIED BY THE VCC STAFF, AS WELL AS ALL OTHER VIOLATIONS.
- THE CONTRACTOR SHALL CHECK AND VERIFY ALL DIMENSIONS, NOTES AND CONDITIONS ON SITE BEFORE ANY CONSTRUCTION WORK IS STARTED. ALL DISCREPANCIES SHALL BE REPORTED TO THE APPLICANT.
- NO WORK SHALL COMMENCE UNTIL ALL NECCESSARY VCC PERMITS HAVE BEEN OBTAINED.
- NO WORK OR ORDERING OF MATERIAL MAY BE STARTED UNTIL ALL DIMENSIONED ITEMS HAVE BEEN RESOLVED.
- NO EXTRA CHARGE OF COMPENSATION WILL BE ALLOWED ON ACCOUNT OF ANY DIFFERENCE BETWEEN ACTUAL DIMENSIONS AND THE MEASUREMENTS WHICH MAY BE FOUND AS INDICATED ON THE DRAWINGS
- THE CONTRACTOR SHALL ASSUME FULL AND UNDIVIDED RESPONSIBILITY FOR THE ACCURACY, FIT, AND STABILITY OF ALL PARTS OF THE WORK.
- 7. NO PLANS SHALL BE SCALED; DIMENSIONS SHALL BE USED.
- ALL LABOR, MATERIALS AND INSTALLATIONS MUST COMPLY WITH THE CODES, RULES AND REGULATIONS OF ALL AUTHORITIES HAVING JURISDICTION. ANY DISCREPANCY WHICH EXISTS BETWEEN THE REQUIREMENTS BY THE PLANS, SPECIFICATIONS, SAID CODES, RULES AND REGULATIONS, SHALL BE IMMEDIATELY BROUGHT TO THE ATTENTION OF THE APPLICANT, IN WRITING FOR RESOLUTION.
- 9. IF ANY CHANGE IN THE PLANS AND / OR SPECIFICATIONS OCCURS AS A RESULT OF THE REQUIREMENTS OF THE LIFE SAFETY CODE (NFPA 101) OR ANY OTHER AUTHORITIES HAVING JURISDICTION AFTER THE SUBMISSIONS OF BIDS, THEN THE BIDDERS WILL BE GIVEN THE OPPORTUNITY TO ADJUST THEIR BIDS, IF NECESSARY, ONLY FOR THE CHANGE. THE CONTRACTOR SHALL PROVIDE ALL NECESSARY PROTECTION OF EXISTING WORK AND NEWLY ADDED WORK.
- 10. THE CONTRACTOR SHALL BE RESPONSIBLE FOR ADEQUATELY BRACING AND PROTECTING ALL WORK DURING CONSTRUCTION AGAINST DAMAGE, BREAKAGE, COLLAPSE, DISTORTION AND MISALIGNMENT ACCORDING TO APPLICABLE CODES AND STANDARDS.
- 11. THE CONTRACTOR SHALL REPAIR AND RESTORE TO ITS ORIGINAL CONDITION ALL WORK AND ITEMS DAMAGED AS A RESULT OF BUILDING OPERATIONS AND SHALL LEAVE THE WORK COMPLETED TO THE TRUE INTENT OF THE DRAWINGS AND SPECIFICATIONS AND TO THE SATISFACTION OF THE ARCHITECT AND OWNER.
- 12. ANY DISTURBANCE OR DAMAGE TO THE EXISTING BUILDINGS OR UTILITIES RESULTING EITHER DIRECTLY OR INDIRECTLY FROM THE OPERATION OF THIS CONTRACT SHALL BE PROMPTLY REPAIRED, RESTORED OR REPLACED TO THE SATISFACTION OF THE APPLICANT AT NO ADDITIONAL COST TO THE OWNER, ALL REPAIR WORK MUST BE REVIEWED AND APPROVED BY THE VCC.



| REVISIONS |             |     |
|-----------|-------------|-----|
| No.       | Description | Deb |
|           |             |     |
|           |             |     |
|           |             |     |
|           |             |     |

OCEANA GRILL - VCC VIOLATIONS PH 1 + 2
Resolution of Life Safety Issues, Work without
Permit, and Demolition by Neglect Violations




| TITLE SHEET |                 |  |  |  |  |
|-------------|-----------------|--|--|--|--|
| Client ID   | TOG - 739 Conti |  |  |  |  |
| Date        | 5/26/2          |  |  |  |  |
| Drawn by    | RF              |  |  |  |  |
| Checked by  | K               |  |  |  |  |
| F           | 40.0            |  |  |  |  |

729-37 Conti

VCC Architecture Committee April 11, 2023






729-37 Conti


VCC Architecture Committee April 11, 2023






729-37 Conti

NAME COMMANDE OF THE PARTY OF T



729-37 Conti

TAPLISHED ST








## HVAC SCHEDULE

## 733 & 737 CONTI

|    | MAKE     | MODEL                  | TONNAGE | DECIBEL LEVEL  |
|----|----------|------------------------|---------|----------------|
| 1  | TEMPSTAR | MODEL-NXA424GKC101     | 2 TONS  | 50-70 DECIBELS |
| 2  | DAIKIN   | MODEL-DX13SA0603AD     | 5 TONS  | 60-70 DECIBELS |
| 3  | TRANE    | MODEL-2TTB0060A1000AA  | 5 TONS  | 60-70 DECIBELS |
| 4  | GOODMAN  | MODEL-GSC130603BA      | 2 TONS  | 50-70 DECIBELS |
| 5  | GOODMAN  | MODEL-GSC130603BA      | 5 TONS  | 60-70 DECIBELS |
| 6  | GOODMAN  | MODEL-GSC130481A6      | 4 TONS  | 60-70 DECIBELS |
| 7  | GOODMAN  | MODEL-GSC130603BB      | 5 TONS  | 60-70 DECIBELS |
| 8  | LENNOX   | MODEL-13ACX-060-230-17 | 5 TONS  | 60-70 DECIBELS |
| 9  | GOODMAN  | MODEL-GSX130603AA      | 5 TONS  | 60-70 DECIBELS |
| 10 | CARRIER  | MODEL-24ACC460A300     | 5 TONS  | 60-70 DECIBELS |
| 11 | CRANE    | MODEL-2TWA0060A3000AB  | 5 TONS  | 60-70 DECIBELS |
| 12 | CARRIER  | MODEL-24ACC460A300     | 5 TONS  | 60-70 DECIBELS |
| 13 | TRANE    | MODEL-2TTB0060A1000AA  | 5 TONS  | 60-70 DECIBELS |
| 14 | GOODMAN  | MODEL-GSC130481A6      | 4 TONS  | 60-70 DECIBELS |



|    | MAKE    | MODEL                | TONNAGE  | DECIBEL LEVEL  |
|----|---------|----------------------|----------|----------------|
| 15 | TRENTON | MODEL-TESA090L6HT3BF | 7.5 TONS | 80-90 DECIBELS |
| 16 | ICP     | MODEL-24ACC460A300   | 5 TONS   | 60-70 DECIBELS |
| 17 | ICP     | MODEL-24ACC460A300   | 5TONS    | 60-70 DECIBELS |
| 18 | RHEEM   | MODEL-RA1436JINA     | 3 TONS   | 50-70 DECIBELS |
| 19 | LENNOX  | MODEL-TSA06054N44Y   | 5 TONS   | 60-70 DECIBELS |
| 20 | LENNOX  | MODEL-TSA06054N44Y   | 5 TONS   | 60-70 DECIBELS |



## IMAGES

























April 11, 2023 **VCC** Architecture Committee















1. REMOVE AND REPLACE ALL PLYWOOD AND PLEXI-GLASS INFILL IN MILLWORK WITH TEMPERED GLASS. EXISTING PAINTED TO REMAIN, REMOVE EXTERIOR PAINT.

- 2. REPAIR EXISTING MILLWORK AS NEEDED. 3. REPLACE IN INAPPROPRIATE OR ILL FITTING MILLWORK. SUBMIT SHOP DRAWINGS FOR APPROVAL
- 4. REPAIR OR REPLACE MISSING OR DAMAGED
- 5. REMOVE INAPPROPRIATE LIGHTING AND REPLACE WITH VCC APPROVED FIXTURE. SUBMIT CUT SHEET FOR APPROVAL.
- 6. REPLACE PLYWOOD SIDING ON IN-FILL STRUCTURE WITH WOOD LAP SIDING OVER BUILDING WRAP, PROVIDE WD. CORNER BOARDS. ALL WOOD PRIMED AND PAINTED.
- 7. REMOVE INAPPROPRIATE PLANTER/FOUNTAIN. 8. REMOVE AND REPLACE ALL GUTTERS WITH HALF-ROUND GUTTERS AND ROUND DOWNSPOUTS. NO GUTTERS TO BE REINSTALLED AT BALCONIES, ROOF LINE ONLY.
- 9. REMOVE AND REPLACE CHIMNEY CAP FLASHING WITH APPROPRIATE CAP. VCC TO APPROVE FINAL
- 10. REMOVE STEEL HOIST, INSTALL MISSING MILLWORK, SUBMIT SHOP DRAWINGS FOR APPROVALS.
- 11. REMOVE PAVERS, INSTALL HERRINGBONE BRICK PAVERS.
- 12. RETAIN SECURITY CAMERA AS INSTALLED. 13. REMOVE ABANDONED CONDUIT, WIRING AND
- 14. RE-POINT MASONRY WITH VCC APPROVED MORTAR MIX.
- 15. REPAIR DAMAGED STUCCO WITH VCC APPROVED A STUCCO MIX.









729-37 Conti

**VCC Architecture Committee** April 11, 2023





729-37 Conti

ABLISHED S

REVISIONS

Resolution of Life Safety Issues, Work without Permit, and Demolition by Neglect Violations

SECOND FLOOR PHOTOS

A8.0













- KEY NOTES: 1. REMOVE AND REPLACE ALL PLYWOOD AND PLEXI-GLASS INFILL IN MILLWORK WITH TEMPERED GLASS. EXISTING PAINTED TO REMAIN, REMOVE
- 2. REPAIR EXISTING MILLWORK AS NEEDED. 3. REPLACE IN INAPPROPRIATE OR ILL FITTING
- 4. REPAIR OR REPLACE MISSING OR DAMAGED MILL;WORK TRIM.
- 5. REMOVE INAPPROPRIATE LIGHTING AND REPLACE WITH VCC APPROVED FIXTURE. SUBMIT CUT SHEET FOR APPROVAL
- 6. REPLACE PLYWOOD SIDING ON IN-FILL STRUCTURE WITH WOOD LAP SIDING OVER ALL WOOD PRIMED AND PAINTED.
- 7. REMOVE INAPPROPRIATE PLANTER/FOUNTAIN. 8. REMOVE AND REPLACE ALL GUTTERS WITH HALF-ROUND GUTTERS AND ROUND DOWNSPOUTS. NO GUTTERS TO BE REINSTALLED AT BALCONIES, ROOF LINE ONLY.
- 9. REMOVE AND REPLACE CHIMNEY CAP FLASHING WITH APPROPRIATE CAP. VCC TO APPROVE FINAL
- 10. REMOVE STEEL HOIST, INSTALL MISSING MILLWORK, SUBMIT SHOP DRAWINGS FOR APPROVALS.
- 11. REMOVE PAVERS, INSTALL HERRINGBONE
- 12. RETAIN SECURITY CAMERA AS INSTALLED. 13. REMOVE ABANDONED CONDUIT, WIRING AND
- 14. RE-POINT MASONRY WITH VCC APPROVED MORTAR MIX.
- 15. REPAIR DAMAGED STUCCO WITH VCC APPROVED A STUCCO MIX. 16. REMOVE INAPPROPRIATE PARAPET CAP
- FLASHING; RESTORE PER VCC GUIDELINES.









April 11, 2023 **VCC Architecture Committee** 







728 Dumaine



728 Dumaine



Title: 728 Dumaine Date: 05/28/1964





728 Dumaine

