
# Vieux Carré Commission Architectural Committee Meeting

## Tuesday, October 23, 2018

## **Other Business**

## **Old Business**


## 211-19 Royal









Vieux Carre Commission











































VCC Architectural Committee



VCC Architectural Committee



VCC Architectural Committee

**PRODUCT DATA SHEET** 

1. CERTIFICATES AND LISTINGS a. Pre-consumer Recycled Content

e. Texas Department of Insurance

c. Coefficient of Linear Expansion

a. Progressive Engineering

b. Cal Fire (WUI)

d. Cradle to Cradle

g. FL Building Code

b. Flexural Strength

d. Impact Resistance

b. Termite Resistance

c. Water Absorption

e. Smoke Developed

4. MANUFACTURING TOLERENCES

d. Flame Spread

a. Width b. Thickness

c. Length

a. Fungi Rot

2. PROPERTIES

1. ICC-ES

a. Density

Boral TruExterior Siding

TEST METHOD

C2C Certified\* Product Standard

SCS Global Certification

Acceptance Criteria 389

Thermal and moisture

Thermal and moisture

ASTM C 1185

ASTM C 1185

ASTM D 6341

ASTM D 6110

AWPA Eto

AWPA E1

ASTM D 570

ASTME 84

ASTM E 84

CA SFM 12-7A-1

BORAL

RESULTS

Listing No. 8140-2134:0106

Minimum 70%

PER-13069

Bronze

EC-92

ESR-3597

FL17285

40-50 lbs/ft<sup>d</sup>

> 1600 psi

> 50 in.

< 1.5%

< 35

< 450

± 1/16 inch

± 1/16 inch

+2 inches / -0 inches

< 1.40 E-05 m./m./H

> 9.0 (10 being best)

Brown Rot - Negligible Loss White Rot - Negligible Loss

## Build something great"

**TECHNICAL BULLETIN** 

## **Bevel Collection Siding**

Bevel				
Norses Size	Armusi Thickness (A)	Actual Width IIII	Minimum Overtap (C)	
Nxti	0.50*	5.50*	1.07	
No.x.B.	0.50*	7.25*	1.07	
Nx10	0.75	.9.25"	.1.07	



Rabbeted Bevel

Coming Soon!

Beaded Bevel

Coming Soon!



1.888.9BORAL9 | www.BoralTruExterior.com

© 2017 Boral Composites Inc. 09/17

1.888.9BORAL9 | www.BoralTruExterior.com

© 2017 Boyal Composition Inc. 5/17

829 Dumaine

VCC Architectural Committee











VCC Architectural Committee













## 929 St Peter




927-29 St. Peter









927-29 St. Peter- 1896 Sanborn





927-29 St. Peter- 1962







927-29 St. Peter

CONTRACTOR OF



927-29 St. Peter





927-29 St. Peter VCC Architectural Committee



## 927-929 SAINT PETER ST. APARTMENT RENOVATION

### DESIGN SUMMARY:

## SCOPE OF WORK

- This is a renovative to an elisting 3 mill. Ilding in the Prench G arter of New Orleans. The pool e o way includes
- 1. Level 2 Renovation- and: drig enclosing rear stair landings with eating and dours to matche inding (26 total SF)
- 2. Level | Ranovedon- to simplane damaged | Sding elements, leveling a lating o rolation,
- Lavell Transvettors- en arrog arreg arrangel: colorg elements invering a storg o notator, artificit all in special and utility or a storg afforcem and fallware.
   Re bace state new strenges and an arrag no scheating.
   Re bace rule of elements and bacaging not scheating.
   Re bace rule are all realized and arranged andor do not need the "strength" array of the store of elements of the store or note and all realized controls.
- 5. Re all and all all a failer window tim, shi fam, malings and anota o main. Ading and service inding Re all and re and all o tomaris risces in Viel. Care Commission re vecents.
- Pf ny ing-Units B and C are to have new attroom lays to with new attroom and listner. I I res. At three rids are getting new tan less water heaters. Gas lines or accord loor attress.
- to a reincated task lightli

## PROJECT NOTES:

## GENERAL PROPERTY.

- DO NOT REAL DRAWINGE LIVE WRITTEN DRAWINGER ONLY. BARRY TO WONTHET MY DISCREPANCES FOR CLARING TOX. 3 ALL VERSI HHLL BE RECENTLAND WITH THE BE RECENTED ADJUTT EVALUATE, CRETENING DIAMAND, CRETENING
- 1 THE CONTRACTOR & SHALL MEREPARED FOR MADING THE PROJECT MADDRESS WITH THE PLANE AND SECURITY ADDRESS AND THE MADING ADDRESS THE OWNER OF MADINE TO THE CONTRACT OF MEDICAL.
- 4. THE AND RECEIPTION AND ANALYZE THE REPORTANCE OF THE PROJECT IN ANY RESPECT OTHER THAN THAT DUE REPORTS THAT, NOR, AND A BUILDING THE REPORT AND THE STANDARDS IF CARE OF DUR. PROFESSION
- Tes Incommentaria de las construcciones de la construcción de las construccións de las construccións de las de las construcciones de las construcciones de las construcciones de las de las construcciones de l
- 6. YES CONTRACTOR SHALL PROVED ADDISATE BRACING AND BROOMS FOR ALL WORK DURING THE COMPACTION PROVED.
- PERIODE AT LEAST 5 CLASS WELS PRIVATE EXTERNAL INVERTIGATION METATION METATION AND ADDRESS WELS PERIOD AND ADDRESS WELSON LINK.
- EPROVEDE SERVARY FOX DETINEDA ALL ORDINALITATION AND JOINT SERVAS, SALO AND CENER FAITURINE. NEW YORK
- 5. VHERE MATERIAL EASTEMERS AND NOT INDEXATED, PROVIDE NO INTEGRAD BY THE MATERIAL MANUFACTURENT INCOMENSATION AND INTEGRAL REP.
- IN, USE ON F 12X0-FREE FIRE AND SOLUDITION NEW COMPLETE WARTE SYSTEM, CARE DRIVING WARTER ACT OF THE AND SERVICE SECTOR 1211.1.4.
- 11 ALL HEW-CHERN BOWED TO BE PURPLE OF PSUH BOARD.

## U. ALL HEW PLATTER SCHART BROCCHI HIGH

### DIRECTING AND INCOME.

- 1 ALL EXTERNOL AND REPORTS FROM THEM TO BE ANALYSIS. PLEASE REPORT TO EVENT SPECIAL AND REDRESS ANT LEAD PRIVIDENTS AN ARTISTS (SEE NAME TO D.
- 2 INVE ALL SUPPORT TO REMOVE EXCESSION OF CHIPMUD MARY REMOVE RULET ON ALL MOVE. IS MAY ITEMS THAT NEED REPAIR (LACAING STRUCTURAL INTEGRITY), ARE TO BE REPAIRED OF REPLACED
- 4 COLORE INVELLAR CHORENEY THE CHINES ON ARCHITECT ALL RELECTIONS MUST BE APPROVED BY THE MONEY CARRY COMMONNY.


## DALTING.

CALCELETINGAL WORK TO BE UNDER TO BELOWING DRIVEN AND HER PROVIDED.	
2 ALL END/IND CONDITIONE AND PANEL CONTRUMPTIONS TO BE VERIFIED	-
3 ALL OUTLETS AND LIGHT FOTUNDS AND TO REMAIN UNLESS NOTED INFORMALY	
4 ALL OPEN SPLICES SHOULD BE REPLACED WITH NEW YORKS.	
<ol> <li>REMARING, GARCENER BORD WITH MISSING LONDER TO PROVENT SECOND THE PROMICEMENT. LINE Immuno.</li> </ol>	
E INSTALLARM MACHE DETECTORE HAS CARRON INSTACHED COTECTORE AND FLORE LAND.	
Merchalancia:	
1 ALL NECHANICH, WORK TO BE UNDER VILLOD ENUMBERAD DOWNINGERARE NOT PROVIDED	
ELAMOND .	
1 ALL PLIAMONG WORK TO BE INCOME. 10,000 THIS METHOD DRAWING ARE NOT PROVIDED.	
2. VERY CORDITING OF BL RECTRO RAMEY AND DEVELOPMENTARIES PLACE AND REPARE IN MICH.	
E.Commu	
1 ALL WOOD PLICOPING TO RECOVERED AND REPAYEMED TO MATCH EXHIBITING.	
2. ALL CAMPARTS WORD AND CERMANE TO BE WEAKINGD AND REPLACED IN INDEXCATED.	



## 927-29 St. Peter


VCC Architectural Committee


















PROJECT DIRECTORY:

ERAAL: any oky saular prescons

ARCHITECT: GARRITY ACCARDO ARCHITECTS 2401 WHITNEY AVENUE GRIETNA LA TOSSI

PROJECT LOCATION

NEW ORLEANS, LA TOTH

DWNER PH (SNI)-296-7126 CONTACT: Kery Kessier

DRAWING INDEX:

theat follow en

T-100

T-101

A-100

A-300

A-200

M-190

P-100

S-100

A-30

Indo o Drewing Sherert Nation

5 Ading Sections

Interior Elevations

Codes and Hall itemprets

Mechanical Planel Relected

Tills Sheet

Develops

**Daking Plan** 

PL m ing Plana

Fo redation Plan

THESE PLANS AND SPECIFICATIONS HAVE BEEN PREPARED BY ME OR UNDER MY

THE BEST OF MY KNOWLEDGE AND BELEF

THEY COMPLY WITH ALL CITY AND STATE REGULATIONS AND REQUIREMENTS. I AM NOT ADMINISTERING THE CONTRACT.

Dan Macanto


DONNA M. ACCARDO LA LICENSE # 4924

ALL CONSTRUCTION SHALL BE IN ACCORDANCE WITH INTERNATIONAL RESIDENTIAL CODE 2016 EDITION LIFE SAFETY CODE (NFPA 101) 2015 EDITION INTERNATIONAL EXISTING BUILDING CODE 2015 EDITION

CLOSE PERSONAL SUPERVISION AND 10


Plane


SIDE





VCC Architectural Committee






(2) Front Elevation



- REPAINT ENTIRE EXTERIOR OF BUILDING WITH VCC APPROVED.

AFTER REMOVAL OF ROOF, REVEW ROOF STRUCTURE AND



Right Side Elevation

C. La 1 Bido Elovatión

THEOL ORIGINAL PROPERTY OF GARRIETY ACCORDO AND THEOT




### VCC Architectural Committee


927-29 St. Peter

NOTE

COLORS

REPAIR AS NEEDED






# CONTRACTOR OF THE OWNER


VCC Architectural Committee

927-29 St. Peter



927-29 St. Peter





2015/01/02/22



Television Da la Hoo

曰. · Anno a Commune


Que Wat No Heat Gas Pill yes. To be Selected in Owner




# 927-29 St. Peter

VCC Architectural Committee

(1) First Floor Mechanical Rollected Ceiling Plan 1/4" = 5-0"



Second Floor Pl. m. ing Plan
 MP + 11-0\*



1 First Floor Plan


# 927-29 St. Peter

VCC Architectural Committee


SCOPE OF WORK UNITS B.C. - REMOVE EXISTING FULLING FUTURES IN NITCHENS AND BATHFOODS NEW NITCHEN BINKS, BATHROOM FUTURES, TUR AND THE SURROUND INSTALL NEW AS FER FLANS. -FURING OUT WALLS BETWEEN BATHROOM AND LIVING FOR NEW FLUIDENING AND VENTLATION - NEW ELECTRIC TANKLESS WATER HEATERS TO BE INSTALLED AS FER FLANS.

SCOPE OF WORK FIRST FLOOR: - ALL FORTURES TO REMAIN - NEW REJECTIRG TANKLESS WATER HEATER TO BE INSTALLED AS PER PLANS










New Bite Detail
 Ave = 1'-0"




(2)-\$-100-Fo, notation Plan - £, stimpl Demo.




927-29 St. Peter

# 1026 St. Louis



1026 St. Louis















1026 St. Louis – ca. 1940









1026 St. Louis






1026 St. Louis




<u>1026 St. Louis – From N. Rampart</u>








1026 St. Louis – Rear from Parking Lot







1026 St. Louis – Rear from Parking Lot





#### Drawing set

# **1026 St. Louis Street Restaurant**

## 1026 St. Louis St

### Interior Renovation

Architect:

Trapolis-Peer | Architects, APC

1000 Tohsamolae Breat 800 Tohsamolae Breat New Onsale, LA 20120 (BOI) 625-6270 Cantact Shear M Tohas, AM, UKK2 AP Sheat Shalangmaanopee tan

#### Owner: John Stubbe

Elit Burgunds Street New Orkana, LA 70113 (202) 378-0046 Contaut: John Stutter Email programula units

#### MEP Engineer

**BIC Consulting Engineers, Inc.** 3714 Stdependence St Materie LA 19008 (RAT 821 9119) Dontal: Bagene T219<sup>2</sup> Higher Enail: Higher@Stocome.Brightgemen.com

#### **PROJECT INFO** PROPERTY DESCRIPTION

PROPERTY ADDRESS 4(34) § ( 1) Out STREET NEW COLLARS: 14 TOTS SCARE INTRO-VED 2 VED X GARGE CEAMERICAL DISTRICT PUTURE LAND LINE

#### WHEN-JIM PRETONE COME CREAL HEFTORIC DESTRICTS.

INVICENT, RECEIPTER OF WEICHES, PLACED, VIEW, CARDO, CARDO EXISTING OCCUPANCY

#### PRIMATY AND SALES FAMILY REPORTED PROPOSED OCCUPANCY

PERMIT AND DURING STORAGE CONTINUES APPLICABLE CODES

#### NOT LARGE TO THE FOLLOW and hold a little in Addition of Company

2014 A ABA DI WE 3010


#### SITE AND BUILDING AREA DITE AREA

CHISTING DRIDES BUILDING ARCA 1,342.62 SECOND FLOOR YOTA, GROOM BUR (1990) AMLA CONTINUE NET BUILING ANEA

#### SECOND PLOCE SUTING NET BORLOWIG AND A 101.07 VICENTY MA









#### international stations BUILDING BECTION TAS OV BRIDERY



- INSTRUCTORY

and and

DETAIL REFERENCE TAG

(which -

### HINDOW TAG WHEN YO BE PREMIUMO



MALL PARTITION TAG

# - DRAMSHING - NORMAN ROOM TAG NOTIME:

RUCK PROFILMENT

AUDIMILT PERCENTION

	HOX MICRAM HECHI MICRANICH, HIC MARKAN HICL JIT MICRANICH MICRA HICL MICRA HICL MICRA HICL DISHILLINI MICA CASHI	
	DOI DATEN DOI DATENDA EDMANDIA DE DATENDA BODINETA DE DATENDA BODINETA	ŝ
H	PTS PARTIES PSS P	101
6CH	WEI WOOI WEI WOOI	
	PHASE LEGEND	
	ENTING CONTINUETE	iai

# CUBLE CONT Downey's att Downey's att Downey's A Downey's Downey EVPTOM REPORT COM.M ETH. DOLLATING WEADOWNER, P CONTRACTOR STOREMENT, P CONTRACTOR STOREMENT, P CONTRACTOR STOREMENT, P CONTRACTOR STOREMENT MAY TO CONTRACTOR STOREMENT MAY TO CONTRACTOR STOREMENT STOR

PRUPUBLIC CONTINUETER

[\_] (enne)

5523 W000,MD

ABBBEVIATIONS

AMEN DEWEN NUMBER NOTTON OF URSE

CONCRETE CONTRUSIE CARRY

Date: 111




	INDEX OF DRAWINGS			
SHAT NAMED	BIEST HARE	GATE	CURRENT ACUSEDA	HEVED DATE
norak.				
A-1.00	TITLE IN GROT	382214	· · · ·	-
T SKMOA	True same.			
640	LOW R.M.	THE LOCK	1.1	Distantia di
4.2.52	State Awar (199	1001214		-
8.010	ACANAL IN THE B	20012-04		
D AMONG NO.				-
A1.81	PRINT AND DECOME PLOTER PLAN-LIBROR.	381214	1	-
ALIT	PRIST AND DECOME PLOOP PLAN	10022178		19428-14
1210	FIRST MODELEND RUCH FOR	102210		Test in
6.2.11	INTER PLAN	Test 114		
4.3.81	FERTIAL RECOURTS ON POUPART AND FURNITIES PLAN.	200.22.54	· · ·	10414-0
418	DOOR SCHEDULE & PARTIFICA THEES	10011-10		10010-14
44.81	BUILDING ELEVATERI	39822.14		DOCUMPT N
44.00	BULDING SECTIONE	100.014		procession of
6.6.01	Field And Second Process Viets Viets	DOCTOTIA.		hiddan
1.6.82	ATEXICA PLEATORS, REITWOORE	20031110		100000
65.02	attrice of white	Ton York.		-
4.5.04	a true of test	10012140		-
6.5.20	alive a state	20022/14		-
6.6.21	RECOMPACT PLATEORS	382118		-
A7.81	WHITCH CREDUCTOR	382214		1040411
I HICKARD		- 10 and 10.		period (
MUDI	Tanta sources in table too territy	TRANS		-
44-1 01	Terry second diversity of the	100.00.00	-	-
ALC 11	INTEL PRANTIAL PLANT, THE PLANT	100.00/10		-
M-LET.	INECTIMATIAL PLAN- SPECTUCCE	Target a		-
MART	THE PANICAL DEVIALS & SCHEDULES	100014		
PUMPE	The Last of the second se	-100.0014		-
E LUI	THU AND RETAILED AND RETAILED.	TRANS	-	-
P.5.85	A LANCE DATE OF STREET,	100.0034		-
BA.91	IN LARRY DUART, HIT & SHITP, HUTP.	100.00.00		-
P.C.S.	what Benefinit Plans- Kill G. dom	10.045		-
P-Igt	PLIASTRI FLAN - DRI FLOOR	100 100 14		-
FLR	PLANERS FLAN- INVITE & VERT- 2ND FLOOR	-1002		-
FIEL	PUANING OF THEIR IN SPECIAL REAL PROPERTY.	1000		
PLU	THE AMOUNT PETRON DESIGNATION AND AND AND AND AND AND AND AND AND AN	Torvista.		
ITYLE: NO.2		100.0010		-
8.2.81	TUTETHOR, ITOPAD AND INTER-	Top and a	-	-
6.8.92	Hard Trevel (P.C. Frontier)	10/10/14	-	-
8.8.17	TELECTION, BROCHENDER, MAIL 197 FLOOP	101014	-	-
#1.00	BLUCTRON, PLAN ATTR	101014	-	-
8.5.51	LIDETECK, FLAR UTFLOOR	1000	-	-
81.0	PLINER PLAN INT PLOOP	101014		-
8.122	PONEN PLAN. IN FLOOR	100 101 10		-
6.201	PLANTIN PLAN, 200 PLAND PLANTIN AL METALS CONTRACTS A MAILBOARD	10/10/10	-	-
- B4FT	TOTAL MORE ALL AREA AND A DALLARDA	1010046		-




## 1026 St. Louis






October 23, 2018





















- ST. LOUIS STREET ----






1026 St. Louis




October 23, 2018






1026 St. Louis



October 23, 2018

VCC Architectural Committee


1026 St. Louis






1026 St. Louis

October 23, 2018










1026 St. Louis

VCC Architectural Committee


力机间

1.000




Constant Constant

1026 St. Louis





October 23, 2018



AIR DEVICE SCHEDULE										
140	178	102	144CB	-	TITE	HOR.	here			
۲	VARIA	VARE	VANE	viers .	SUMPACE.	AVAILAR OF ORL TITLE	13			
0	in A party	VANES	value.	weeks !	manual di	back on model states	1.1			

1. RECYCLE OFFICE (2014) ALL DAMAGE VALUE (2014) RECEIPTING THE CONTRACT OF THE RECEIPTING THE RECEIPTING OF THE RECEIPT

	_			1111111		IG UINT	-	a ber berbarte		
		. 380		UAN	MITTY	1.1.1.0.4.0	N.ECTIMUM	10. Carlos	NUTRAL R.	
TAIL	10761	100 YU.049		CONLINE)	101100	vinee	HA.	410		
4.00.11	1750	194	- 24	- torbally		1225-091		14	0440801104	1.1
1.08.1.0	1100	- 1990	-84			10000-0041	- 4	18	LL Brief Care	1

1 PROVIDE INCLUSION PROVIDED CONNECTOR 3 HER/CONTLUMP MEDIA VIEW (LINEAR ONLY)

_		_			HEAT	PUMP		DULE	_	1	112
140	-	-			HUCHUS CAPALITY (1998/199		uner	RCP	-	4338	NTR.
101	Child)	9400	4000	80		2	201304	20	191	DAMER JOHON	12
and the	20123-0404-01	10-41-001-	anna i	10	-	4	100.148	18	140	1444691291214	10

HERE 1. PROVIDE UNDERFORT VENUER COMMETTION 3. PROVIDE CONVERTING COMMETTION 4. PROVIDE CONVERTING COMMETTION

FAN SCHEDULE											
			· FA					IL PUTHICH.		_	
ini i	Mercan.		TOTAL UNK		100	80.0.0 1975	5345	autorita.	urnal	# (08).	June
	inclusion and	OR ALL REPORTED	18.1	inter-	8.800	-		ACTOR REPORT	100100	DEBERTH MADE AT	144
#11 L	in restant	titi munimi	19	1000	0.000	100	÷.	ACTO HERE	100100	seeds make of	de .
10 A	+000	16,200	1250	1	8 100	276		(803	1001044	Desired Activity 700	1 k
ani i	1000	16.00	-	10	1 800	1100	-14	1000	1200.000	PROPERTY OF A	Sec.


 Implementation
 Accord
 Name
 4 million
 1
 1
 4 ccord
 Name Handboord Stress

 Version
 Stress Stress Stress
 Name Handboord Stress Stress
 Name Handboord Stress Stress
 Name Handboord Stress Stress
 Name Handboord Stress Stress


			K	TCHE!	N HO	00 5	CHE	DOLE	
THE MONSE	2-6100 BM	19444748	EN MARY ARE		BUPPLI AR				
	tie -	MILEE	0.060	9011	DNA CINA	PO presenta	CPRE	HO HINGS	HOTEL
41	introit.			196	214	140	8 ar	10025	



## 1026 St. Louis




# 336 Decatur


























336-40 Decatur /400 Conti








336-40 Decatur /400 Conti






VCC Architectural Committee

October 23, 2018







① DECATUR STREET ELEVATION 1/8" = 1'-0"

336-40 Decatur /400 Conti





1 <u>N. PETERS ELEVATION</u> 1/8" = 1'-0"


336-40 Decatur /400 Conti









336-40 Decatur /400 Conti







336-40 Decatur /400 Conti













1 SCHEMATIC PARAPET DETAIL 3/4" = 1'-0"




2 STEEL WINDOW HEAD DETAIL 1 1/2" = 1'-0"

336-40 Decatur /400 Conti

VCC Architectural Committee






(4) STEEL WINDOW JAMB DETAIL 1 1/2" = 1'-0"



October 23, 2018



336-40 Decatur /400 Conti





















































CORRECCIONANT OF















October 23, 2018

## 1025 St Peter










1025 St Peter




1025 St Peter – Existing Rear Additions






1025 St Peter – One Story open air structure seen in 1896 Sanborn






1025 St Peter – One Story open air structure in corner of property only; seen in 1908 Sanborn



1025 St Peter – One Story structures similar to current arrangement; seen in 1940 Sanborn

CAPITY COMMON



1025 St Peter - 1964






VCC Architectural Committee


1025 St Peter






1025 St Peter






1025 St Peter





1025 St Peter





1025 St Peter - 2004






1025 St Peter - 2004






1025 St Peter - 2004









October 23, 2018











October 23, 2018






### 1025 St Peter






# **New Business**










































































CORPORATE HEADQUARTERS

www.h-b.com

T: 800.645.0616 F: 631.234.0683


	1104 Day	esquine
Repair and Restoration Anchors	Shee	+3/3
Spira-Lok®	out 4,	201B




**NEW YORK - PENNSYLVANIA - TEXAS** 

UTAH - CANADA

#### 1104 Dauphine






















































Red = 1-1/4" Flat bar frame installed within existing repair wood frame

Purple = 5/8" square pickets, welded and

match below existing

evenly spaced to

gate

Remove inappropriate, rotted wood spindles. Repair and paint existing wood frame




Scrape and paint existing gate

Remove rotted cove molding. Do NOT replace. Repair frame to flat surface and paint.




533 Governor Nicholls

## 327 Exchange Pl
















































































## 926 Chartres



926-28 Chartres



926-28 Chartres VCC Architectural Committee



<u>926-28 Chartres - 1964</u> VCC Architectural Committee





926-28 Chartres





926-28 Chartres VCC Architectural Committee





926-28 Chartres – gallery at neighboring 930-940 Chartres



926-28 Chartres – gallery at neighboring 930-940 Chartres




926-28 Chartres – gallery at neighboring 930-940 Chartres




GALLERY - EXTERIOR VIEW - GALLERY


926-28 Chartres – Approved Gallery Plans













926-28 Chartres – Approved Gallery Plans






# **Appeals and Violations**

## 522 Chartres









522 Chartres





522 Chartres



























522 Chartres













Photo #6-View of cracked section of southwest wall







522 Chartres











522 Chartres








522 Chartres – area 1

VCC Architectural Committee



March 13, 2018











March 13, 2018






March 13, 2018













## 522 Chartres





522 Chartres









March 1. 018



VCC Architectural Committee

March 29, 2016



VCC Architectural Committee

March 29, 2016







































































VCC Architect





1309 Daupł

VCC Architect



04 05



1309 Dauph VCC Architect












1309 Dauph












































1309 Daupł









1309 Dauphine - 2017











1309 Dauphine - 2017












1309 Dauphine - 2017













































# 1309 Dauphine






### 1309 Dauphine

























906 Royal – Prior to Gas Light Installation











October 23, 2018

# 931 St Louis







931 St. Louis








931 St. Louis, 1963


















<u>931 St. Louis</u>


VCC Architectural Committee



# October 23, 2018











<u>931 St. Louis – Previously Existing Hardware - 1963</u>

