
Vieux Carré Commission Architecture Committee Meeting

Tuesday, July 12, 2022















































TERRELL FABACHER HITECTS, L.L.C.


ST


PROPOSAL INVILLE S

GALLERY 08 BIE

ORLEANS

NEW





208 Bienville



BIENVILLE STREET

PROPOSED GALLERY ADDITION TO EXISTING HISTORIC BUILDING

INDEX TO DRAWINGS

LOUISIANA

NEW ORLEANS,

GENERAL SCOPE OF WORK:

DRAWN BY

6-1-22





Page 15 of 465

FABACHER SCHITECTS, L.L.C.

GALLERY PROPOSAL 208 BIENVILLE ST

6-1-22








<u>REFLECTED CEILING PLAN</u>

SCALE: 1/8" = 1'-0"




























VCC Architectural Committee





518 Conti




















518 Conti
















Page 34 of 465












PARTIAL 1ST FLOOR <u>DEMOLITION PLAN</u> SCALE: 1/4"=1'-0"




1 EXISTING/DEMOLITION CONTI STREET ELEVATION SCALE: 1/4"=1'-0"











To: Vieux Carre' Commission

Re: 518 Conti Street

Attn: Erin Vogt

Dear Ms. Vogt:

As you know, the decision on the approval of the new elevator in the windows and the A/C condensing units' locations was deferred by the VCC ARC on June 28th, 2022, pending the receipt of more information regarding the effect of the elevator on the structure, the elevator itself, and the window treatments in the windows in front of the elevator.

Please see the attached excerpts from the Planning Guide of the Inclinator Elevette, the elevator that is being used in the project. The clouded Code 2 model on sheet 7 was chosen as the model number because a new wall is not required on the door/window/exterior wall side of the elevator as all of the structure required to run the elevator is mounted on the other two walls – see attached page 11 of the Planning Guide. The car depth is 39.75" and the car width is 42.5". The structural loads of the elevator are found on the attached sheet 12 of the Planning Guide: the static vertical load is 1,100 lbs. and the impact vertical load (the load on the slab if the elevator falls to the ground) is 2,200 lbs. – the loads are very light. I met with my structural engineer, Walter Zehner, and he blessed our foundation drawing based on the light loads. He also said that the existing corbelled footings do not normally start until 18"-24" below the existing slab and therefore our new elevator foundation shall be above it with no impact on it. We did add a new 12" deep x 24" wide foundation beam under the wall that is the entrance to the elevator as all of the ceiling beams are now being supported by it (there is no existing foundation under that area). The Machine Room is being located under the stair in the retail space and the cables for the pulleys shall run under the stair landing in the front Vestibule.


The windows and doors along the Conti sidewalk shall remain operable as there shall be no wall up against them. Regarding the window treatments that shall be seen from the street, the Owner shall install either curtains or blinds in the windows – please let us know if you have a preference. There are also shutters on the exterior of the building that shall be operable.

Regarding the A/C condensing units, they shall be mounted on grade rather than mounted to the rear yard walls per the Staff's request.


Thank you.


Sincerely, ~

Steve Finegan, AIA











518 Conti Street Renovation






INCLINATOR ELEVETTE®

Planning Guide

> CABLE DRUM 500 lb. (227 Kg)



AMERICA'S MOST CUSTOMIZABLE ELEVATOR




PN 67209703 Rev L



Hoistway Layout

The following data is for typical industry size elevators.

Any size cab is available in $\frac{1}{4}$ " increments to dimensions **A** and **C** or **B** and **D** within the maximum and minimum dimensions shown in the diagram on page 6 not to exceed 12 SQ, FT, or 15 SQ, FT, where allowed.




CABLE DRUM - 500 PLANNING GUIDE

PN 67209703 Rev L






Hoistway Construction



3/4" X 4" RULE / DOOR FRAME DETAILS

Reference ASME 17.1-2016 5.3.1.4.2, 5.3.1.7.2, & 5.3.1.8.3



CABLE DRUM - 500 PLANNING GUIDE

11

PN 67209703 Rev L








Alternate Hoistway Construction

The following recommendations are for hoistways constructed of concrete or hollow concrete block.

When mounting to a solid concrete wall or solid filled concrete block use (2) concrete screw anchors with a minimum ultimate strength in tension of 3000 lbs (i.e. Redhead LDT – Large Diameter Tapcon) per a mounting bracket.

When mounting to hollow concrete block it is best to use ½" threaded rod and thru-bolt the superstrut to the wall. ½" Steel plate should be used on the back side of the wall for additional strength.



NOTE: All mounting points should meet or exceed the minimum pull out force for all rail reactions.

NOTE: Follow the anchor manufacturer's recommendations for type and size of drill bit to be used.

RAIL IS PRE-DRILLED AT FACTORY

4. ALL SHEAVE PITCH DIA. 5 3/4"

3. RAIL FASTENING TO 2"x12" PLANK

2. BOLT FASTENING OF CAR TO TROLLEY ½" - 13 x 4"

SOCKET HD CAP SCREWS

#14 x 1 3/4" TYPE A S.M.S.

CABLE DRUM - 500 PLANNING GUIDE

PN 67209703 Rev L

13









Hoistway Elevation

TRAVEL	Single Drum Double Groove	Double Drum Single Groove
8'-0"	3'-8"	1'-9"
8'-6"	3'-10"	1'-10"
9'-0"	4'-1"	1'-11"
9'-6"	4'-3"	2'-0"
10'-0"	4'-5"	2'-1"
10'-6"	4'-8"	2'-3"
11'-0"	4'-10"	2'-4"
11'-6"	5'-0"	2'-5"
12'-0"	5'-3"	2'-6"
12'-6"	5'-5"	2'-7"
13'-0"	5'-7"	2'-9"
13'-6"	5'-9"	2'-10"
14'-0"	6'-0"	2'-11"
14'-6"	6'-2"	3'-0"
15'-0"	6'-4"	3'-1"
15'-6"	6'-7"	3'-2"
16'-0"	6'-9"	3'-3"
16'-6"	6'-11"	3'-4"
17'-0"	7'-2"	3'-6"
17'-6"	7'-4"	3'-7"
18'-0"	7'-6"	3'-8"
18'-6"	7'-8"	3'-9"
19'-0"	7'-11"	3'-10"
19'-6"	8'-1"	3'-11"
20'-0"	8'-3"	4'-1"
21'-0"	8'-8"	4'-3"
22'-0"	9'-0"	4'-5"
23'-0"	9'-5"	4'-7"
24'-0"	9'-10"	4'-10"
25'-0"	10'-2"	5'-0"







Machine Room Configurations
























VCC Architectural Committee

July 12, 2022











































July 12, 2022






841 Royal, 1885 Sanborn











VCC Architectural Committee










July 12, 2022













937 Dumaine































937 Dumaine



miniFI7

2" MINIFIT MODULE

SPECIFICATION FEATURES

- Mechanical 2" MINIFIT module with external driver snaps into field interchangeable trims and install from below the ceiling. Trim mounted spring action clips accommodate ceiling thicknesses between 1/2" and 2".
- Electrical -120V, 50/60 Hz driver. Dimmable to 10% with Forward phase (TRIAC) / Reverse phase (ELV) dimmers. Plenum rated quick connect cable allows for easy wiring.
- Optical 2700K, 3000K, 4000K and 5000K color temperatures available. 38° narrow beam distribution. COB technology ensures minimum 90CRI with 3-step SDCM. Open Round Flat and Round Deep Trims tilt up to 45°. Field interchangeable reflectors available with Round Deep Trims.
- Thermal Extruded aluminum heat sink, Rated L70 lifetime of 50,000 hours. Ambient temperature rating: -4°F to 104°F (-20°C to 40°C).
- Compliance and Warranty ETL Listed for Damp location. ETL listed for Wet location when used with Glass trims (MM2T/RFT/GL/xx). IC rated. Energy Star® listed. JA8 Certified to meet CA Title 24 requirements. 5 year parts warranty for complete fixture.



BENEFITS









Shallow form factor for easy installation

- IC Rated and wet location listed with glass trims
- 120V dimmable down to 10%
- Multiple choice of finish and options

APPLICATIONS

- New construction and retrofit application
- Shallow plenum applications: including soffits, bulkheads, and casework
- Residential & Hospitality
- Retail & Office

ORDER	ING INF	ORI	MΑ	MOIT					
				Module				Trims	
Series	Size	CRI		COPTY	Beam Angle	Dimming	Trim	Style	Austral A
⊻MM Mini Module	⊻ 2 2* 780lm	⊻ 90 CR		27 2700K 30 30 3000K 40 4000K 500 5000K	Flood 38°	✓ DIM120 120V - Line voltage dimming	MM2T MM2 Trim	RFT/OP Bound Flat - Coen RFT/GL Round Flat - Glass Cover RDT/OP Round Deep - Open RDT/PN Round Deep - Pinhole RDT/WW Round Deep - Wall Wash	BM* Brushed Metal

^{*}Brushed Metal finish is only available for Round Flat trims.



PROJECT: CONTACT: LOCATION: TYPE:



PRODUCT DESCRIPTION

1-Light indoor flush mount with cylinder shade is suitable for dry locations. Cylinder shade provides a directional glow to a specific area. Enjoy modern design that complements homestyle surroundings and décor. Hard surface provides top quality protection against scratches. Easy maintenance—simply clean and polish to achieve an even more lustrous shine. Outer lacquer finish provides an attractive sheen and additional layer of protection. Perfect for dining rooms, bedrooms, and many other indoor areas.

V1015


1-LIGHT INDOOR CYLINDER FLUSH MOUNT DOWNLIGHT


SPECIFICATIONS

	Type of Lighting	Indoor Lighting		
	Product Type	Flush Mount		
	Height	8 in.		
Width		4 ½ in,		
	Available Finishes	Black (V1015-5) White (V1015-6)		
	Main Material	Steel		
	Shade Material	Steel		
	Light Direction	Downward		
	Installation/Mounting Position	Downward		
	Number of Lights	1		
	Watts per Light	75 W		
	Total Wattage	75 W		
	Light Bulb(s) Included	No		
	Lumens per Light	N/A		
	Total Lumens	N/A		
	Dimmable	Yes		
	Base Type	Medium Base (E26)		
	Voltage	120V		
	Installation Location	Dry		
	Safety Ratings	UL Listed		
	Assembly	Assembly Required		
	Warranty	1-Year Limited Warranty		



937 Dumaine







937 Dumaine





Intercom Modular Outdoor Station

Part of the Dahua Modular Intercom System



System Overview

The Dahua Intercom Modular System is a complete intercom solution that offers full customization of the entire system. This intercom system starts with a 2 MP outdoor video intercom module that offers a wide-angle view lens, high-resolution images even in dark environments, and two-way talk. Then, add optional modules that offer door access capability (card reader, fingerprint reader, and keypad), call buttons, information text display, and status light indicators. The system also offers optional accessories to flush-or surface-mount a two-or three-module intercom system

Modular Intercom Components

- DHI-VTO4202F-P-S2: 2 MP Outdoor Video Intercom (Required)
- DHI-VTO4202F-MB5: Five-button Call Panel
- . DHI-VTO4202F-MF: Fingerprint Reader
- DHI-VTO4202F-MK: Keypad
- DHI-VTO4202F-ML: Status Light Panel
- DHI-VTO4202F-MN: Blank Panel
- DHI-VTO4202F-MR: IC Card Reader
- . DHI-VTO4202F-MS: Information Text Display

· 2 MP Wide Angle Camera with Night Vision

- · Built-in Microphone with Two-way Talk
- · Records Call Sessions from the Indoor Monitor
- · Access Control Supports Two Locks
- · Performs Remote Door Unlock
- · Compatible with Two-wire or RJ45 Connection
- · Supports Secure Password Entry
- · Anodized Aluminum Panel can be Surface- or Flush-mounted
- · Fully Customizable System
- · IP65 Ingress Protection and IK07 Vandal Resistance

Technical Specification: DHI-VTO4202F-P-S2

reciliicai specificati	IOII. DHI-V104202F-F-32
System	
Main Processor	Embedded Processor
Operating System	Embedded Linux
Video	
Image Sensor	1/2.5-in. 2 MP CMOS Sensor
Lens	1.9 mm
Angle of View	Horizontal: 168.6° Vertical: 87.1° Diagonal: 176.7°
Wide Dynamic Range	120 dB
Noise Reduction	3D NR
Compression	H.265, H.264
Resolution	Main Stream: 720p at 30 fps Sub Stream: 1080p 30 fps
Bit Rate	256 Kbps to 4 Mbps
Day/Night	Auto (ICR)
Audio	
Compression	G.711a, G.711u, PCM
Input	Omnidirectional Microphone
Output	Built-in Speaker
Bi-directional Talk	Support for Dual-way Bi-directional Talk
Enhancement	Echo Suppression, Digital Noise Reduction
Bit Rate	16 KHz, 16 Bit
Interface	
Ports	One (1) Electric Lock One (1) Exit Button One (1) Door Status Detection One (1) Lock Control
Alarm Output	One (1) Channel
Power Output	12 VDC, 100 mA

Intercom | DHI-VTO4202F Series

Ordering Information Part Number Description Video Intercom DHI-VTO4202F-P-S2 2 MP Outdoor Station DHI-VTO4202F-MB5 Five-button Call Panel Fingerprint Reader DHI-VTO4202F-MF DHI-VTO4202F-MK Keypad Modules, DHI-VTO4202F-ML Status Light Panel optional DHI-VTO4202F-MN Blank Panel DHI-VTO4202F-MR IC Card Reader DHI-VTO4202F-MS Information Text Display Two-module Front Panel Bezel VTM125 (use with VTM127 or VTM02R2) Three-module Front Panel Bezel VTM126 (use with VTM128 or VTM03R3) Two-module Flush-mount Box VTM127 (use with VTM125) Three-module Flush-mount Box VTM128 (use with VTM126) Mounting Three-module Surface-mount Box Accessories VTM03R3 (use with VTM128) optional Two-module Surface-mount Box VTM52R2 (use with VTM125) Three-module Surface-mount Box VTM53R3 (use with VTM128) Intercom Surface-mount Box for VTM54R4 DHI-VTO4202F (2 x 2 system) Intercom Surface-mount Box for VTM5686 DHI-VTO4202F (2 x 3 system) Two-wire Switch, Two-wire Intercom Power Supply DHI-VTNSB2003B-2 optional Power adapter for DHI-VTNS20038-2 ADS-65LSI-52-1 480606 VI Power Input: 100 VAC to 240 VAC Power Output: 48 VDC, 1.25 A Power Supply optional² Power adapter for DHI-EDP-240-48 Power Input: 100 VAC to 240 VAC Power Output: 48 VDC, 5 A

2. One of the listed power adapters is required for the DHI-VTNS2003B-2

Intercom Module Images

DHI-VTO4202F-P-S2 2 MP Outdoor Station





DHI-VTO4202F-MB5 Call Button Panel



DHI-VTO4202F-MF Fingerprint Reader



DHI-VTO4202F-MK Keypad



DHI-VTO4202F-ML Status Light Panel



Page 88 of 465

DHI-VTO4202F-MN Blank Panel



DHI-VTO4202F-MR IC Card Reader

Mounting Accessory Images



DHI-VTO4202F-MS Information Text Display





VTM125 Two-module Front Panel Bezel



VTM126 Three-module Front Panel Bezel



VTM127 Two-module Flush-mount Box



VTM128 Three-module Flush-mount Box



Three-module Surface-mount Box



Two-module Surface-mount Box



VTM54R4 2 x 2 Surface-mount Box




VTM56R6 2 x 3 Surface-mount














815 St. Ann






815 St. Ann




815 St. Ann - 1974





























815 St. Ann – 1st Floor Interior







VCC Architectural Committee





815 St. Ann – 1st Floor Interior






815 St. Ann – 1st Floor Interior




815 St. Ann – 1st Floor Interior



815 St. Ann – 1st Floor Interior







815 St. Ann – 1st Floor Interior

VCC Architectural Committee







VCC Architectural Committee





815 St. Ann – 1st Floor Interior





815 St. Ann – 1st Floor Interior





815 St. Ann – 1st Floor Interior





815 St. Ann – 1st Floor Interior







815 St. Ann – 1st Floor Interior









815 St. Ann – 1st Floor Interior

VCC Architectural Committee





815 St. Ann – 1st Floor Interior






815 St. Ann – 1st Floor Interior







815 St. Ann – 1st Floor Interior











815 St. Ann – 2nd Floor Interior





815 St. Ann – 2nd Floor Interior





815 St. Ann – 2nd Floor Interior






815 St. Ann – 2nd Floor Exterior

VCC Architectural Committee







815 St. Ann – 2nd Floor Exterior




815 St. Ann – 2nd Floor Exterior











815 St. Ann – 2nd Floor Exterior













Established 1840 PHONE 504-488-2671 * FAX 504-482-2862 3319 ORLEANS AVENUE * P.O. BOX 19737 NEW ORLEANS, LA 70179-0737 www.abrybrothers.com

LA CONTRACTORS LICENSE NO. 26319

May 18, 2021

William Wolf Yazoo Restorations, LLC 7611 Maple St New Orleans, LA 70118

An initial inspection was conducted at:

815 St. Ann Street NOLA 70116

As per your request, a visual inspection was conducted at the above address. The purpose of the inspection was to develop a cost estimate for structural shoring at the site.

We are pleased to quote a cost range of \$65,000.00 to \$68,000.00.

The price is based on the following scope of work:

- Shoring the interior framing from the ground up to the roof, the balcony and the balcony roof to allow removal of the front masonry wall. The removal is to be done by others.
- Installing a new foundation under the removed wall.

The quote **does not include** the demo or removal of the wall or any finishes that need to be replaced. It **does not include** rebuilding of the wall.

If you should require further information and/or a contract to make the necessary repairs, please let us know.

Thank you for contacting **ABRY BROTHERS**, **INC.** for your raising/shoring/leveling requirements.

Sincerely,


815 St. Ann

VCC Architectural Committee











VCC Architectural Committee



VCC Architectural Committee



VCC Architectural Committee

MORPHY, MAKOFSKY, INC.

CONSULTING ENGINEERS 336 N. Norman C. Francis Parkway New Orleans, LA 70119 P:504/488-1317 F:504/488-0924 www.mmi-eng.com Jamie L. Saxon Jonathan A. Sofranko H. Stephan Bernick

June 27, 2022

John Williams Williams Architects 824 Baronne Street New Orleans, LA 70113

RE: 815 St Ann Street New Orleans, La.

Dear Mr. Williams,

We are writing this is letter to explain that the front façade wall will need to be rebuilt. The existing building is two stories tall with wood framing at the 1st, 2nd and roof levels. The exterior walls are multiwythe, load bearing, clay masonry brick walls. The front of the building abuts onto St. Ann Street. The floor joists appear to span in the direction parallel with the street.

At the time of our inspection, Tuesday, October 27, 2020, we could see displacement of the front façade wall and cracking in the masonry wall. The footing was damaged due to the ongoing construction. See attached photos. The lower section of the wall has the outer wythe of masonry tilting outwards, the inner wythes tilt inwards and the masonry towards the Dauphine Street side has cracked and begun to separate. The front wall has actually buckled which occurred when the footing under the front wall was undermined and likely rotated. Above the second floor we can also see significant horizontal movement across the wall resulting in large cracks above and adjacent to the windows. In addition, the front wall is separating from the side and central walls.

In consideration that the lower half of the wall needs to be removed to allow for the total replacement of the footing and rebuilding of the lower section of the wall. To shore the front wall needle beams need to be placed thru the wall above the windows of the first level. This will remove a significant portion of the wall. All the masonry below these needle beam will need to be replaced as it has suffered damage and the wythes have separated. The upper wall also has significant issues. The sections at each end have significant cracks above the second level windows and thru the outer jambs each side. These sections of masonry have moved outwards. These sections cannot be safely shored and need to be rebuilt. See attached elevation with notes.

When considering that wall sections are removed to allow for needle beam installation, the lower half of the wall below the needle beams has to be rebuilt, the two outer masonry piers at the second level and corresponding section of masonry above this outer windows will also be replaced, then only the upper interior piers and masonry above the two second level windows is left in place. This is an insignificant portion of the wall that would remain. Also the shoring for this small section would be above the area of footing and wall replacement, making it a very dangerous area to work.





In view of this extent of work, the entire front façade will need to be removed and rebuilt. This also provides the safest means of restoration of the front façade when you consider that this wall is on the property line and close to a very busy part of the French Quarter.

Morphy Makofsky, Inc.

Yours truly

Jamie Saxon, P.E.





Photo 1: DAMAGED FOOTING



Photo 2: DAMAGED/MISSING FOOTING.



Photo 3: DAMAGED/MISSING FOOTING



Photo 4: DAMAGED FOOTING.





Photo 5: CLOSE UP OF DAMAGED BRICK OF FORMER FOOTING.




Photo 6: CLOSE UP OF DMAGED BRICK IN FORMER FOOTING.



Photo 7: CLOSE UP OF DAMAGED AND DISPLACED BRCIK IN FOOTING.


























1039 Burgundy




1039 Burgundy

VCC Architectural Committee


















1039 Burgundy























1039 Burgundy Street

New Orleans, LA. 70116


Exterior Renovations VCC ARC 7/12/2022

3D VIEWS ARE DIAGRAMTIC IN NATURE ONLY, SEE PLANS AND ELEVATIONS FOR DETAILS AND DIMENSIONS

"New building construction is a sign of economic health and vitality in a city. It can take many forms including a new primary building, an addition to an existing building or a new secondary building. All forms of new construction within a historic district can be dynamic and vibrant, but at the same time should be sensitive to their 100- to 250-yearold neighbors. Vacant lots, particularly those located towards the boundaries of the Vieux Carré, provide the greatest opportunity for creative and sensitive new ground-up construction, while an addition or a new secondary building can allow the continued use of a historic building or property to meet current and future needs." VCC Guidelines 14-1















EXISTING

PROPOSED








EXISTING DOORS AND HARDWARE TO BE RELOCATED TO INFILL EXISTING MASONRY ARCHWAY

NEW DOOR TO BE MILLED TO MATCH EXISTING IN MATERIAL AND DIMENSION, INFILL EXISTING MASONRY ARCHWAY

EXISTING, NO CHANGE








EXISTING, NO CHANGE

EXISTING, NO CHANGE












WALL PHASING LEGEND

EXISTING WALLS TO REMAIN

NEW WALLS AND AREA OF INFILL









FIRST FLOOR PLAN

WALL PHASING LEGEND


EXISTING WALLS TO REMAIN

NEW WALLS AND AREA OF INFILL

1/2" = 1'-0"

BUILDING SECTION -

1 PROPOSED




Page 167 of 465

 NEW WOOD FRAME ROOF WI ASPHALT SHINGLE TO MATCH EXISTING IN MATERIAL AND COLOR.
 CONSTRUCTED TO SAME ELEVATION AND SLOPE AS EXISTING ADJOINING ROOF.


NEW GUTTERS TO TO MATCH

GARAGE INTERIOR




THE VCC DOES NOT ALLOW:

- A rooftop addition on a Purple or Blue rated building
- A rooftop addition on a building originally constructed as a residential building
- A rooftop addition on a roof with a pitch greater than 3-inches vertically in 12-inches horizontally and an existing parapet less than 18-inches in height Except at a camelback shotgun
- A roof addition greater than one story and/or 12'-0" in height or with a roof form other than a flat or lowsloped roof Excluding an elevator override



When reviewing a proposal for a rooftop addition, the VCC evaluates the application on a case by case basis. An approved rooftop addition at one location should not be considered a precedent or construed to mean that a similar proposal for another property will be approved. Factors considered by the VCC in its review include:

- The significance of the building or site as defined by its color rating
- The location of the building and site
- The height of the existing building, the proposed addition and surrounding buildings It must also meet zoning requirements including height and setback
- The visibility of the proposed addition
- The architectural treatment of the proposed addition and its compatibility with the existing building it should not be obtrusive or detract from the architecture of the existing building or the surrounding Vieux Carré Historic District, streetscape or adjacent buildings.














1/2" = 1'-0"


Page 170 of 465

NEW SINGLE 18' GARAGE DOOR, WOOD, OUTWARD SWING

3D VIEWS ARE DIAGRAMTIC IN NATURE ONLY, SEE PLANS AND ELEVATIONS FOR DETAILS AND DIMENSIONS







A rooftop addition must be set back from the street walls of the existing building by a minimum of the proposed height of the addition, (i.e. 12'-0" high rooftop addition must be set back from the street wall a minimum of 12'-0".) The VCC discourages a rooftop addition on a building less than three full stories in height because of the increased likelihood of visibility.

DESIGN STANDARDS FOR ROOFTOP ADDITION REVIEW

If allowable by the Comprehensive Zoning Ordinance (CZO) and appropriate at a particular site, the VCC uses specific design standards to review a rooftop addition proposal. In its review of a proposed rooftop amenity or addition, the VCC:

- Strives to make a rooftop addition, including an elevator and mechanical equipment, as well as furnishings as unobtrusive and minimally visible as possible
- Limits the overall height of a rooftop addition, including framing and parapet, to 12"-0" above the lowest surface of the existing roof, except for code-required components, such as an elevator override
- Requires that a rooftop addition be set back from the street façade(s) of the building by a minimum of the overall height of the proposed addition (i.e., a 12'-0" high rooftop addition should be set back from the street wall a minimum of 12'-0")
- Requires that a rooftop addition incorporate elevator, mechanical and HVAC equipment within the single story and allowable addition footprint
- Requires that all furnishings including railings, screens, planters, plants and permanent rooftop furnishings taller than the closest parapet be setback from the street wall(s) a minimum of the height of the proposed furnishing from the lowest roof surface
- Considers a proposal for a rooftop addition that does not conform to these Guidelines at a Green, Pink or Yellow rated building under limited circumstances; however, excellence in design and the architectural character of the existing building are strong factors in the review

Rooftop Addition Review

Construct a rooftop addition



Commission

ROOFTOP ADDITIONS

THE VCC REQUIRES:

- Compliance with the Comprehensive Zoning Ordinance (CZO) – A rooftop addition shall not require a variance for height limit or floor area ratios
- Review of all exterior items located on a roof surface including paying, railings and built-in furnishings

THE VCC DOES NOT RECOMMEND:

- A rooftop addition on a Green, Pink or Yellow rated building
- A rooftop addition on a building of less than three full stories in height

THE VCC DOES NOT ALLOW:

- · A rooftop addition on a Purple or Blue rated building
- A rooftop addition on a building originally constructed as a residential building
- A rooftop addition on a roof with a pitch greater than 3-inches vertically in 12-inches horizontally and an existing parapet less than 18-inches in height – Except at a camelback shotgun
- A roof addition greater than one story and/or 12'-0" in height or with a roof form other than a flat or lowsloped roof – Excluding an elevator override

Vieux Carré Commission - Guidelines for New Construction, Additions & Demolition 14-17




DESIGN PRINCIPLES	NEW CONSTRUCTION & ADDITIONS
Scale: Height & Width	Proportions and size of the new building/addition compared with neighboring buildings/existing building
Building Form & Massing	The three-dimensional relationship and configuration of the new building/ addition footprint, its walls and roof compared with neighboring buildings/ existing building
Setback	Distance of the new building/addition to the street or property line when compared with other buildings on the block/existing building
Site Coverage	Percentage of the site that is covered by a building/addition, when compared to nearby sites of compatible size
Orientation	Location of the front of the new building/addition and principal entrance relative to other buildings on the block
Alignment, Rhythm & Spacing	Effect the new building/addition will have on the existing patterns on its block
Architectural Elements & Projections	Size, shape, proportions and location of each entrance, balcony, gallery, porch, roof overhang, chimney, dormer, parapet and other elements that contribute to the building's overall shape and silhouette relative to neighboring buildings
Façade Proportions: Window & Door Patterns	Relationship of the size, shape and location of the new building/addition façade and building elements to each other, as well as when compared to other buildings on the property, block/existing building
Trim & Detail	Mouldings, decorative elements and features of a building that are secondary to major surfaces such as walls and a roof and how they relate to the neighboring buildings/existing building
Materials	Products with which an addition or new building is composed or constructed and how these relate to neighboring buildings/existing building

14-4 Vieux Carré Commission – Guidelines for New Construction, Additions & Demolition









800 N. Rampart





800 N. Rampart












800 N. Rampart - 1863





N.RAMPART

(GRANITE BLUCK PHYED)





800 N. Rampart





800 N. Rampart





800 N. Rampart

VCC Architectural Committee

July 12, 2022









800 N. Rampart



800 N. Rampart – 9/2021





800 N. Rampart – 9/2021





800 N. Rampart – 9/2021





800 N. Rampart – 06/2022





800 N. Rampart – 06/2022



WHEREAS, Owner is the owner of the real property located at municipal address 800 N. Rampart Street, New Orleans, LA 70116, Lot 1, Square 103, in the Second Municipal District, City of New Orleans, Louisiana (the "Property");

WHEREAS, the Board has certain water and/or sewer lines (the "Board Lines") under the public right of way sidewalk adjacent to the Property, which said Board Lines are subject to a servitude in favor of Board (the "Servitude");

WHEREAS, Owner desires to renovate the existing, historic structure located upon the Property including the addition of a gallery (the "Gallery") to be attached to the structure, extending over and above the public right of way sidewalk and the Board Lines and Servitude, at a height of approximately twelve feet eight inches (12'8") above the adjacent sidewalk, including over the Board Lines and Servitude, which Gallery is planned by Owner to be constructed at 12'8" generally according to plans (the "Plans") as attached hereto as Exhibit "A"; and

WHEREAS, Board has objected to the addition of the Gallery above and over the Lines and Servitude because it needs the Servitude for access to its Lines and related facilities to maintain water and sewer services, for work to be done and performed by Board, its employees, the City of New Orleans or its employees, their respective officials, agents (including contractors and subcontractors) acting within the scope of their authority; and

WHEREAS, Owner recognizes and is willing to assume and indemnify Board for the risks and complexities due to the addition of the Gallery over and above the Board Lines and the Servitude:

NOW THEREFORE, the parties agree as follows:

- The Board withdraws its objection to the construction of the Gallery over the Board Lines and Servitude at a height of twelve feet eight inches (12'8") generally in accord with the Plans attached as Exhibit A.
- 2. Owner acknowledges that damage to or removal of the Gallery may be necessary to the performance of such Board work and Owner agrees that, so long as the Board Lines and/or Servitude exists beneath the Gallery, Owner, to the fullest extent permitted by law, shall indemnify and hold harmless the Board, its employees, officials, agents (including contractors and subcontractors) acting within the scope of their authority, and the Board's assigns (collectively, the "Indemnified Parties") for any damages to, including the removal of, the Gallery caused by the Board, its employees, officials, contractors, subcontractors or agents in the maintenance, servicing, or replacement of the Board Lines, provided the Board, its contractors, and agents exercise reasonable and standard care and are not negligent in causing such damage.

Maintenance Agreement – 800 N. Rampart Gallery 1 3/3/2022


3. Owner agrees that, so long as the Board Lines and/or Servitude exists beneath the Gallery, Owner, to the fullest extent permitted by law, shall indemnify and hold harmless the Indemnified Parties from and against any and all claims, suits, damages, losses, costs, demands, judgments, and liabilities accrued against the Indemnified Parties, for any and all liability arising from or relating to any act or omission of the Owner, its employees, officials, or agents (including contractors and subcontractors) acting within the scope of their authority while the Owner is engaged in, or in connection with the discharge or performance of, any work or other activity that has an effect on the Board's Lines and/or Servitude; and for any and all claims and/or liens for labor, services, or materials furnished to the Owner in connection with performance of work that has an effect on the Board's Line, including but not limited to damages, losses, claims, costs, demands, and judgments of sums of money suffered or incurred by any or all of the Indemnified Parties, specifically including without limitation, all reasonable attorney's fees and related costs..

- 4. Except in the case of emergency, Board agrees to provide written notice to Owner to the address and contact on record for Board billing of the Property no less than thirty (30) days prior to any maintenance, servicing, or replacement of the Board Lines that may damage, cause the removal of, or otherwise impact the Gallery. Upon receipt of such notice, Owner shall have the opportunity to fully or partially remove, fortify, or otherwise prepare the Gallery for the work planned by Board, within such thirty (30) day period.
- 5. The Owner has an immediate and independent obligation, at the Board's option, to: (a) defend the Board from and/or (b) reimburse the Board for its costs (including but not limited to reasonable attorney fees and related costs) incurred in the assertion or defense of any claim that actually falls within this indemnity (even if the allegations are, or may be groundless or the Owner is ultimately absolved from liability in whole or in part).
- 6. The indemnity provided herein does not extend to the extent of any claims, suits, damages, losses, costs, demands, judgments, and liabilities arising from or relating to the gross negligence or willful misconduct by any of the Indemnified Parties.
- All covenants, stipulations, terms, conditions, and provisions of this Agreement shall extend to and are binding upon the respective successors and assigns of the Appearer and the Board.

[THE REMAINDER OF THIS PAGE IS INTENTIONALLY LEFT BLANK]

[SIGNATURES CONTAINED ON THE NEXT PAGE]

Orleans, Louisiana on the 24th day	and the undersigned competent witnesses in New y of, 2022.
J&R RENTAL PROPERTIES, L.L.C.,	
HALF JAMES PROPERTIES, L.L.C.,	
MICHELLE CAHN WOLFSON TRUST,	
JAMES LENARD CAHN TRUST, AND RICHARD M. CAHN TRUST	WITNESSES:
RICHARD M. CAHN IRUSI	Man h M
1 . 4 /1.	PRINT NAME: MICHAEL G Sheman
BY:	PRINT NAME: MICHEL & ShemIN
JAMES LENARD CAHN AS AUTHORIZED SIGNATORY OF EACH	H SIGN: Shulr tall
AS AUTHORIZED SIGNATORY OF EACH	PRINT NAME: Sheila TAHYI dar
	1 1
Miles L. Granderson Orleans Parish, Louisiana	
Orleans Parish, Louisiana	7
Notary Public	
Notary Public Commission No. 148722 My Commission Expires at death	Y PUBLIC
Commission No. 148722 My Commission Expires at death	
Commission No. 148722 My Commission Expires at death	Y PUBLIC in New Orleans, Louisiana on the da
Commission No. 148722 My Commission Expires at death Executed before the undersigned notary	
Commission No. 148722 NOTAR My Commission Expires at death Executed before the undersigned notary of	
Commission No. 148722 My Commission Expires at death Executed before the undersigned notary	
Executed before the undersigned notary of	in New Orleans, Louisiana on the da
Executed before the undersigned notary of	in New Orleans, Louisiana on the da WITNESSES:
Executed before the undersigned notary of	in New Orleans, Louisiana on the da
Executed before the undersigned notary of	witnesses: SIGN: PRINT NAME:
Executed before the undersigned notary of	witnesses: SIGN: PRINT NAME: SIGN:
Executed before the undersigned notary of	witnesses: SIGN: PRINT NAME:
Executed before the undersigned notary of	witnesses: SIGN: PRINT NAME: SIGN:
Executed before the undersigned notary of	witnesses: SIGN: PRINT NAME: SIGN:
Executed before the undersigned notary of	witnesses: SIGN: PRINT NAME: SIGN:



FOOD PREF

203

205

206

POLISHED CONC.

POLISHED CONC

RUBBER TILE

MOOD

MOOD

MOOD

CERAMIC TILE

CERAMIC TILE

CERAMIC TILE

THE SIGNING OF THIS PLAN BY AN ENGINEER OF THE SEWERAGE AND WATER BOARD SIGNIFIES THAT IT HAS BEEN REVIEWED FOR GENERAL COMPLIANCE WITH THE BOARD'S MINIMUN ACCEPTED STANDARDS AND SHALL NOT BE CONSTRUED AS A WARRANTY OF THIS AND THE ACCOMPANYING PLANS AND SPECIFICATIONS.

IT DOES NOT RELIEVE THE DEVELOPER OF THE RESPONSIBILITY FOR ERRORS, DISCREPANCIES, OMISSIONS, ELEVATIONS, OBSTRUCTIONS, OR OTHER REQUIREMENTS OF A COMPLETE AND WORKABLE DESIGN, NOR DOES IT PROHIBIT THE BOARD FROM HAVING THE DEVELOPER MAKE FURTHER MODIFICATIONS TO THE PLANS OR AND JUSTMENTS IN THE FIELD DURING CONSTRUCTION.

SIGNED 8

FOR GENERAL SUPERINTENDENT

DATE \$ 7/97/2622

JOHN C WILLIAMS

ART STREET RLEANS, LA

800 N. Rampart

3'-5 1/2" x 8'-0" x 1 3/4"

104 PR. 2'-1" x T'-0" x 1 3/4"

105 PR, I'-10" x 8'-0" x 1 3/4"

108 2'-0" x 8'-0" x 1 3/4"

3'-6" x 8'-0" x 1 3/4"

3'-0" x 8'-0" x 1 3/8"

205 3'-0" x 8'-0" x 1 3/8"

206 3'-0" x 8'-0" x 1 3/8"

207 3'-0" x 8'-0" x 1 3/8"

INT. FLUSH WOOD SOLID CORE DOOR

INT FLUSH WOOD SOLID CORE DOOR

INT, FLUSH WOOD SOLID CORE DOOR INT, FLUSH WOOD SOLID CORE DOOR

INT. FLUSH WOOD SOLID CORE DOOR

H.M.

H.M.

MOOD

HEAD JAMB SILL

1/A34 5/A33 2/A34 SEE ELEVATION 1/A33


5/A3.4 6/A3.5 4/A3.4 SEE ELEVATION 2/A3.5

5/A3.4 9/A3.5 6/A3.4 SEE ELEVATION 4/A3.5

EXIST, 4'-2" X I'-T' FIXED TRANSOM SEE ELEVATIONS 104


1/2 HR. FIRE RATED, HOLD OPEN DEVICE ACTIVATED BY FIRE AL












800 N. Rampart








800 N. Rampart






800 N. Rampart








800 N. Rampart






800 N. Rampart









800 N. Rampart







800 N. Rampart




800 N. Rampart













June 27, 2022

City of New Orleans Department of Safety & Permits 1300 Perdido St., Room 7E06 New Orleans, LA 70112

Reference: 800 N Rampart St.

New Orleans, La

On March 15, 2021, this office submitted structural drawings for a gallery addition to an existing building located at the above reference address to Williams Architects. During the plan review stage one structural issues arose concerning the structural integrity of the building and the ability of the building to withstand the added dead and live loading of the gallery.

The issue concerning the building was as follows, 'Extensive time has gone by since initial review, and it has been known that structural repairs will be needed on the N. Rampart masonry wall. Meanwhile, the building has continued to deteriorate due to continuing demolition by neglect. In light of these facts, VCC staff is requesting an updated engineer's report based on a recent inspection confirming that the building can carry the necessary dead and live loads for a gallery.' The new structure was designed with auger cast-in-place concrete piles to support the added 3-inch steel columns and steel plate joists and wood decking similar to typical New Orleans type galleries. Past photos show the building had a gallery at one time therefore the building is able to support the added dead and live loading of the gallery. We originally inspected the building in 2020 and re-inspected the building on Friday June 24, 2022 after the request by Mr. John Williams. The building is structurally sounds as a whole, during construction all damaged or deteriorated wood framing shall be replaced in-kind and all masonry walls tuck pointed as needed to restore the original structural integrity of the building. This office is to be contacted as needed during construction to ensure all repairs are performed as per all city and state building codes.

All new construction was designed in compliance with the 2015 International Building Code, ACI 318-05 Building Code Requirements for Structural Concrete and ASCE 7-10 Minimum Design Loads for Buildings and Other Structures.

Sincerely,

James B. Heaslip II, P.E.

















522 Bourbon





































522 Bourbon





522 Bourbon





522 Bourbon






522 Bourbon


















522 Bourbon














































Bill
St Louis Cathedral
1116 Charters
New Orleans, LA 70116

Projec	t		

P.O. Number	Terms	Rep
1100	Due on receipt	HL

11177) Due on ree	in the			
Quantity	Item Code		Description	Price Each	Amount
	22 Specialty	SOFT START METER UPGI AND OTHER COMMUNICA COMMUNICA ALUMINUM BUILDING,G	RAC LIQUID COOLED WITH 200A ATS, 2 S FOR AIR CONDITIONING UNITS, GAS RADE 2LB, 2 REGULATORS I FOR BOILER FOR GENERATOR, CONDUIT FOR ATIONS/ELECTRICAL LINE VOLTAGE, ATION WIRES, ELECTRICAL WIRES, STAND, BATTERY, AS, ELECTRICAL PERMITS. HECTON LOPEZ CONTRACTOR	34,625.08	34,625.08
	full co		CONUNCION	Total	\$34,625.0
Dhana #		E mail	Web Cite	Polones Due	\$34,625.08


1100-1116 Chartres

VCC Architectural Committee

Phone #	E-mail	Web Site	Balance Due \$34,625	.08
504-466-0065	hector@lopezmechanical.net	www.lopezmechanicall.net	Payments/Credits	








1301 Chartres







VCC Architectural Committee


July 12, 2022











1301 Chartres

VCC Architectural Committee







CAPRE COMMUNICATION OF THE PROPERTY OF THE PRO









TAPLISHED 91







1301 Chartres, 1876







Begin forwarded message:

* PLEASE READ THIS LETTER FIRST

From: Melody Douglas <douglas7565@gmail.com>

Date: May 11, 2022 at 1:01:43 PM CDT

To: Ice 1 <markveer1301@gmail.com>

From: Melody Douglas <douglas7565@gmail.com>

Date: April 25, 2022 at 11:13:15 AM CDT

To:lexitaylor8@hotmail.com, Chartres parapet neighbour Mike Roberts <MROBERTS55@cox.net>

Subject: Parapet wall application for removal

Dear Mr. Galbrecht,

Hello, Margarite Roberts visited our property today at 1301 Chartres St., to view a parapet wall of peculiar positioning. It is a 3 course brick structure in the attic of the slaves quarters, resting upon one beam with pieces of 2x8 placed across it to the next beam being it's only support.

We have multiple issues with this parapet wall, first is the parapet itself is leaking and has caused the ceiling to collapse once already after Ida. I as the owner of this unit had no choice but to repair the leaks temporarily & repoint the parapet as it was at risk

of completely collapsing into both upper & lower units.

1301 Chartres

Two;





issues. No engineer will sign off this as being structurally sound, we've tried, so it must be dealt with before the worst does occur.

We are working in cooperation with John Matassa & his property manager Mike Roberts at 603 Barracks to redo our roof in the slate that is required. Mr Matassa plans to replace our parapet with one built upon the existing brick wall & property line, reusing our old bricks from the demo'd parapet.


He has a site survey to have placement of this replacement parapet properly positioned.

Please find Photos of the interior attic & suspect parapet wall.

Sent from my iPhone













DECKTER




CHARTRES

BARRACKS










































440 Bourbon



440 Bourbon











440 Bourbon






440 Bourbon












440 Bourbon



440 Bourbon



440 Bourbon











440 Bourbon





440 Bourbon





440 Bourbon

























440 Bourbon





440 Bourbon







440 Bourbon




FOR CONCEPTUAL APPROVAL ONLY


PROPOSED EXTERIOR ALTERATIONS

440 BOURBON ST.

NEW ORLEANS, LOUISIANA







EXISTING:		
GROUND FLOOR	5445 SF	
2ND FLOOR	2340 SF	
3RD FLOOR	2340 SF	
TOTAL	10,125 SF	32'-8" +/- HIGH
NEW:		
2ND FLOOR	3101 SF	
3RD FLOOR	3101 SF	
PENTHOUSE	620 SF	
TOTAL	6822 SF	47'-0" +/- HIGH
		(TOP OF PENTHOUSE)



SITE PLAN APPROX. SCALE: 1"= 20'-0"



ST. LOUIS ST. VIEW - EXISTING



CORNER VIEW - EXISTING



BOURBON ST. VIEW - EXISTING





ST. LOUIS ST. VIEW - PROPOSED

- RESTORE EXISTING OPENINGS ON GROUND LEVEL. NEW 3 STORY STRUCTURE NEW GALLERY AND BALCONY.



CORNER VIEW - PROPOSED

- ADD GALLERY ON THE SECOND LEVEL. STYLE TO MATCH EXISTING BALCONY. REMOVE CORNER COLUMN AT FRONT ENTRANCE. CLEAN UP AND RESTORE EXISTING EXTERIOR FACADE.



BOURBON ST. VIEW - PROPOSED

- ADD GALLERY ON SECOND FLOOR LEVEL. REMOVE CORNER COLUMN AT FRONT ENTRANCE. CLEAN UP AND RESTORE EXISTING EXTERIOR FACADE.

OSED EXTERIOR ALTERATIONS 440 BOURBON ST

05/26/22 22-1709 Date: Project No.

VCC2







ST. LOUIS ST. VIEW - EXISTING

2.1. 2.3.1.3.2.1.1.2.1. 2.1.1.1.1.

ST. LOUIS ST. VIEW - PROPOSED

- RESTORE EXISTING OPENINGS ON GROUND LEVEL.
- 2. NEW 3 STORY STRUCTURE
- 3. NEW GALLERY AND BALCONY.







CORNER VIEW - EXISTING

440 Bourbon

CORNER VIEW - PROPOSED

- 1. ADD GALLERY ON THE SECOND LEVEL. STYLE TO MATCH EXISTING BALCONY.
- REMOVE CORNER COLUMN AT FRONT ENTRANCE.
- 3. CLEAN UP AND RESTORE EXISTING EXTERIOR FACADE.








440 Bourbon


BOURBON ST. VIEW - EXISTING

BOURBON ST. VIEW - PROPOSED

- ADD GALLERY ON SECOND FLOOR LEVEL.
- REMOVE CORNER COLUMN AT FRONT ENTRANCE.
- CLEAN UP AND RESTORE EXISTING EXTERIOR FACADE.




AERIAL VIEW OF ROOFTOPS




440 Bourbon





440 Bourbon





A rooftop addition must be set back from the street walls of the existing building by a minimum of the proposed height of the addition, (i.e. 12'-0" high rooftop addition must be set back from the street wall a minimum of 12'-0".) The VCC discourages a rooftop addition on a building less than three full stories in height because of the increased likelihood of visibility.

DESIGN STANDARDS FOR ROOFTOP ADDITION REVIEW

If allowable by the Comprehensive Zoning Ordinance (CZO) and appropriate at a particular site, the VCC uses specific design standards to review a rooftop addition proposal. In its review of a proposed rooftop amenity or addition, the VCC:

- Strives to make a rooftop addition, including an elevator and mechanical equipment, as well as furnishings as unobtrusive and minimally visible as possible
- Limits the overall height of a rooftop addition, including framing and parapet, to 12'-0" above the lowest surface of the existing roof, except for code-required components, such as an elevator override
- Requires that a rooftop addition be set back from the street façade(s) of the building by a minimum of the overall height of the proposed addition (i.e., a 12'-0" high rooftop addition should be set back from the street wall a minimum of 12'-0")
- Requires that a rooftop addition incorporate elevator, mechanical and HVAC equipment within the single story and allowable addition footprint
- Requires that all furnishings including railings, screens, planters, plants and permanent rooftop furnishings taller than the closest parapet be setback from the street wall(s) a minimum of the height of the proposed furnishing from the lowest roof surface
- Considers a proposal for a rooftop addition that does not conform to these Guidelines at a Green, Pink or Yellow rated building under limited circumstances; however, excellence in design and the architectural character of the existing building are strong factors in the review

Rooftop Addition Review

Construct a rooftop addition



Commission

ROOFTOP ADDITIONS

THE VCC REQUIRES:

- Compliance with the Comprehensive Zoning Ordinance (CZO) – A rooftop addition shall not require a variance for height limit or floor area ratios
- Review of all exterior items located on a roof surface including paying, railings and built-in furnishings

THE VCC DOES NOT RECOMMEND:

- A rooftop addition on a Green, Pink or Yellow rated building
- A rooftop addition on a building of less than three full stories in height

THE VCC DOES NOT ALLOW:

- · A rooftop addition on a Purple or Blue rated building
- A rooftop addition on a building originally constructed as a residential building
- A rooftop addition on a roof with a pitch greater than 3-inches vertically in 12-inches horizontally and an existing parapet less than 18-inches in height – Except at a camelback shoteun
- A roof addition greater than one story and/or 12'-0" in height or with a roof form other than a flat or lowsloped roof – Excluding an elevator override

Vieux Carré Commission - Guidelines for New Construction, Additions & Demolition 14-17



DESIGN PRINCIPLES	NEW CONSTRUCTION & ADDITIONS				
Scale: Height & Width	Proportions and size of the new building/addition compared with neighboring buildings/existing building				
Building Form & Massing	The three-dimensional relationship and configuration of the new building/ addition footprint, its walls and roof compared with neighboring buildings/ existing building				
Setback	Distance of the new building/addition to the street or property line when compared with other buildings on the block/existing building				
Site Coverage	Percentage of the site that is covered by a building/addition, when compared to nearby sites of compatible size				
Orientation	Location of the front of the new building/addition and principal entrance relative to other buildings on the block				
Alignment, Rhythm & Spacing	Effect the new building/addition will have on the existing patterns on its block				
Architectural Elements & Projections	Size, shape, proportions and location of each entrance, balcony, gallery, porch, roof overhang, chimney, dormer, parapet and other elements that contribute to the building's overall shape and silhouette relative to neighboring buildings				
Façade Proportions: Window & Door Patterns					
Trim & Detail	Mouldings, decorative elements and features of a building that are secondary to major surfaces such as walls and a roof and how they relate to the neighboring buildings/existing building				
Materials	Products with which an addition or new building is composed or constructed and how these relate to neighboring buildings/existing building				

14-4 Vieux Carré Commission – Guidelines for New Construction, Additions & Demolition





A cast iron decorative railing, sometimes found at a window, may include a repetitive pattern of detailed components.

A NEW BALCONY, GALLERY OR PORCH

Adding a new balcony, gallery, porch or overhang will greatly alter the appearance of a building. In select cases, the VCC might approve the installation of a new balcony, gallery, porch or overhang provided that:

- There is documentary evidence supporting a balcony, gallery, porch or overhang previously existed
- . The installation is appropriate for the building type
- The installation does not destroy or conceal an important architectural feature or detail
- The proposed design is compatible in size, scale and design to the building and surrounding streetscape

When installing a new balcony, gallery, porch or overhang, great care should be taken to minimize the removal of existing building fabric during its installation and attachment. In addition, the design of the components should be simple and visually minimized to allow the wall surfaces beyond to remain visible. When installing a new metal gallery, simple posts located along the curb with a plain balustrade are generally most appropriate. (Refer to Guidelines for New Construction, Additions & Demolition for information regarding the reconstruction or installation of a new balcony, gallery, porch or overhang.)



A drop awning installed at either the front or side of a gallery or porch can help to keep it cooler. To be approved, a drop awning must roll-up, extend between bays and be consistent in color, material and details across a façade. To be considerate of neighbors, a drop awning should be rolled-up when not in use. Note the metal security divider between the adjoining galleries.

VCC REVIEW FOR ADDING OR REMOVING A BALCONY, GALLERY OR PORCH

The VCC does not allow the addition of ornamental wrought or cast iron to a gallery or balcony where it is not documented for the particular style or type of building, such as a former warehouse building. The VCC does not allow the removal of contributing ornamental metals or a porch.
























































































529 Bienville






529 Bienville










Site Plan
3/32" = 1'-0"






PROPOSED LOCATION FOR NEW GENERATOR


Existing Aerial Photo



3/8" = 1'-0"



















20/22/24 kW



GUARDIAN® SERIES

Residential Standby Generators Air-Cooled Gas Engine

INCLUDES:

- True Power ** Electrical Technology
- Two-line multilingual digital LCD Evolution™ controller (English/Spanish/French/Portuguese)
- 200 amp service rated transfer switch available
- Electronic governor
- Standard Wi-Fi⁽⁸⁾ connectivity
- System status & maintenance interval LED indicators
- Sound attenuated enclosure
- Flexible fuel line connector
- Natural gas or LP gas operation
- 5 Year limited warranty
- Listed and labeled for installation as close as 18 in (457 mm) to a

*Must be localed away from doors, windows, and fresh air intakes and in accordance with local codes.

Standby Power Rating

G007038-1, G007039-1, G007038-3, G007038-3 (Aluminum - Bisque) - 20 kW 80 Hz G007042-10, G007042-11, G007043-10, G007043-11(Aluminum - Bisquin - 22 kW 60 Hz G007209-10. G007210-10 (Aluminum - Bisque) - 24 kW 60 Hz



Product shown with optional fascia let



Note: CETL or CUL certification only applies to unbundled units and units packaged with limited circuit switches. Units packaged with the Smart Switch are ETL or UL certified in the USA only.

FEATURES

- O INNOVATIVE ENGINE DESIGN & RIGOROUS TESTING are at the heart of Generac's success in providing the most reliable generators possible. Generac's G-Force engine lineup offers added peace of mind and reliability for when it's needed the most. The G-Force series engines are purpose built and designed to handle the rigors of extended run times in high temperatures and extreme operating conditions.
- O TRUE POWER" ELECTRICAL TECHNOLOGY: Superior harmonics and sine wave form produce less than 5% Total Harmonic Distortion for utility quality power. This allows confident operation of sensitive electronic equipment and micro-chip based appliances, such as variable speed HVAC systems.
- O TEST CRITERIA
 - PROTOTYPE TESTED SYSTEM TORSIONAL TESTED / MOTOR STARTING ABILITY

✓ NEMA MG1-22 EVALUATION

MOBILE LINK® CONNECTIVITY: FREE with select Guardian Series Home standby generators, Mobile Link Wi-Fi allows users to monitor generator status from anywhere in the world using a smartphone, tablet, or PC. Easily access information such as the current operating status and maintenance alerts. Users can connect an account to an authorized service dealer for fast, triendly, and proactive service. With Mobile Link, users are taken care of before the next power outage.

- state-of-the-art power maximizing regulation system is standard on all Generac models. It provides optimized FAST RESPONSE to changing load conditions and MAXI-MUM MOTOR STARTING CAPABILITY by electronically torque-matching the surge loads to the engine. Digital voltage regulation at ±1%.
- SINGLE SOURCE SERVICE RESPONSE from Generac's extensive dealer network provides parts and service know-how for the entire unit, from the engine to the small-
- GENERAC TRANSFER SWITCHES: Long life and reliability are synonymous with GENERAC POWER SYSTEMS. One reason for this confidence is that the GENERAC product line is offered with its own transfer systems and controls for total system



20/22/24 kW

2/24 kW




Page 322 of 465


Specifications


Model						
		G007038-1 G007039-1	G007042-10 G007043-10	G007038-3 G007039-3	G007042-11 G007043-11	G00720 G00721
Rated maximum continuous power or	noachy (LP)	(20 kW) 20,000 Watts*	(22 kW)	(20 kW)	(22 kW)	(24 kg
Rated maximum continuous power capacity (NG)		18,000 Watts*	22,000 Watts* 19,500 Watts*	20,000 Wats*	22,000 Watts*	24,000 W
Rated voltage		TO,UUC WASS	13,100 Matts.	18,000 Watts*	19,500 Watts*	21,000 W
Rated maximum continuous load our	rent - 240 volts (LP/NG)	83.3 / 75.0	91.7 / 81.3	83.3/75.0	0.71010	70000
Total Harmonic Distortion		99-07 1-076	31,7701,3		91.7/81.3	100 / 83
Main line circuit breaker		90 amp	100 amp	Less than 5% 90 amp	100	
Phase		ov and	ing and	t average	100 amp	100 am
Number of rator poles				2		
Rated AC frequency				60 Hz		
Power factor				1.0		
Battery requirement (not included)		121	folts, Group 26R 540 C		35AGM 650 CCA mix	imum
Unit weight (lb / kg)		448 / 203	hts, Group 26R 540 CCA minimum or Group 35AGM 650 CCA minimum 466 / 211 436 / 198 445 / 202 455 / 20			
Ownersions (L x W x H) in / cm Sound output in dB(A) at 23 th (7 m) with generator operating at normal load**			48 x	25 x 29 / 121.9 x 63.5	x737	
Sound support in del(A) at 23 ft (7 m) s	with generator operating at normal load**	67	67	67	67	67
Exercise duration	with generator in Quiet-Test " low-spood exercise mode"."	55	57	55	57	57
POSSESSE DE L'ANNE DE L'AN				5 min		
Engine				A New Address		
Engine type Morehan all adjustes			GEN	IERAC G-Force 1000 S	aries	
Number of cylinders Displacement				2		
Ovlinder block				999 oc		
Valve arrangement			Als	minum w/ cast iron sle	eve	
Ignition system				Overhead valve		
Governor system				Solid-state w/ magnets		
Compression ratio				Bectronic		
Starter				9.5:1		
Oil capacity including filter				12 VDC		
Operating opm				Approx. 1.9 qt / 1.8 L		
Fuel consumption				3,600		
Natural gas	#9hr (m9hr)					
	1/2 Load	204 (5.78)	228 (6.46)	164 (4.64)	203 (5	
Liquid propane	Full Load 03/hr (pal/hr) (L/hr)	301 (8.52)	327 (9.26)	287 (8.13)	306 (8	
	1/2 Load Full Load	87 (2.37) [8.99] 130 (3.56) [13.48]	92 (2.53) [9.57] 142 (3.90) [14.77]	86 (2:36) [8:96]	92 (2.53	
Note: Fuel pipe must be sized for fa gas. For BTU content, multiply \$200 a.	ill lead. Required hust pressure to generator fuel inlet at al 2500 (LP) or h ⁵ /hr x 1000 (NG). For Magajoule content, m				142 (3.90) 12 in water column (2	.49-2.99 kPa)
Controls	The state of the s	11 (L	- / us myst x 37.28 (N	a).		
Two-line plain test multilingual LCD			200000			
Mode buttons: AUTO			Simple use	er interface for ease of a	operation.	
MANUAL		Automat	ic start on utility failure	. Weekly, Bi-weekly, gr	Monthly selectable er	eerciser,
OFF		Sight W	nth stanter control, unit	stays on, if utility fails,	transfer to load takes	place.
Ready to Rus/Maintenance messages			oxops und. Power is	removed. Control and o	harger still operate.	
Engine run hours indication				Standard		
Programmable start delay between 2-1	500 seconds		Standard	Standard (programmable by dear	he make	
Utility Voltage Loss/Return to Utility adj	justable (brownout setting)			programmacie by dea n 140-171 V / 190-216		
Future Set Capable Exerciser/Exercise 5	Get Error warning		rigi	Standard		
Run/Alarm/Maintenence logs				50 events each		
Engine start sequence			Cyclic cranking: 16 a	ec on, 7 rest (90 sec n	renimum duration!	
Starter lock-out			Starter cannot re-env	page until 5 sec after er	noise has stronger	
Smart Battery Charger			15,014	Standard	A-v is subject	
Charger Fault/Missing AC warning				Standard		
Low Battery/Battery Problem Protection	and Battery Condition Indication			Standard		
Automatic Voltage Regulation with Over	and Under Voltage Protection			Standard		
Under-Frequency/Overload/Stepper Ove	rourent Protection			Standard		
Safety Fused/Fuse Problem Protection	A STATE OF THE STA			Standard		
Automatic Low Oil Pressure/High Oil Te	mperature Shutdown			Standard		
Divercranil/Overspeed (@ 72 Hz)/rpm S	ense Loss Shuldown			Standard		
				Standard		
High Engine Temperature Shutdown				Standard		
Internal Fault/Incorrect Wiring protection				Standard		
Internal Fault/Incorrect Wiring protection Common external fault capability						
Internal Fault/Incorrect Wining protection Common external fault capability Field upgradable firmware				Standard		
Internal Fault/Incorrect Wining protection Common external fault capability Field upgradable Inmwase Rating definitions - Optional Standby: A (All oblists in accompany with RSSS14.	pplicable for supplying backup power for the duration of the	e utility power outage	with correct maintenan	ce performed. No over	load capability is avail	table for this rat
Internal Fault/Incorrect Wining protection Common external fault capability Field upgradable Inmwase Rating definitions - Optional Standby: A (All oblists in accompany with RSSS14.	pplicable for supplying backup power for the duration of the ISO3046, UL2200, and DN6271]. We subject to and irritate by such factors as fuel STU/med OR my show sor lead and also will decrease.	is utility power outage	with correct maintenan	ce performed. No over	load capebility is avail	lable for this ra












































































1011 St. Philip





1011 St. Philip


VCC Architectural Committee





1011 St. Philip















NATURE SERIES

R-SIDED CEILING FLUSH

Page 346 of 465




ndmade flush mount electric light some discreet beauty and illuminat area.







1011 St. Philip







1011 St. Philip






1011 St. Philip












521 St. Louis






521 St. Louis – c. 1858








521 St. Louis






521 St. Louis




521 St. Louis


































































USA DE LA COMPANIA DEL COMPANIA DE LA COMPANIA DEL COMPANIA DE LA COMPANIA DE LA







600 Decatur =

VCC Architectural Committee










VCC Architectural Committee

July 12, 2022













6.15.22

PHOTO'S


A-9












PHOTO'S








624 Dumaine
























TAPLISHED TO



TABLESHED ST




























































512-16 Conti






512-16 Conti



512-16 Conti






512-16 Conti – 2018














512-16 Conti












512-16 Conti


































512-16 Conti














632 Bourbon























































































3 BLDG 630 - A/C COND UNIT & DAIQUIRI COND UNITS





6 BLDG 630 - WALK-IN COOLER COMP & A/C COND UNITS



6 BLDG 630 - KITCHEN HOOD EXHAUST & SUPPLY FANS



7 BLDG 632 -(4) A/C COND UNITS, HOOD EXHAUST FAN & COOLER COMP



8 BLDG 632 -(4) DAIQUIRI CONDENSING UNITS





Page 450 of 465



June 15, 2022

· STRUCTURAL

· INDUSTRIAL

· MARINE

Mr. Charles Ward Jr Rozas Ward Architects 1100 Poydras Street Suite 3550 New Orleans, Louisiana 70163

> 630 & 632 Bourbon Street New Orleans, Louisiana 70130 Report of Findings

Dear Mr. Ward:

In accordance with your request, we completed a limited visual structural observation of the above captioned first floor ceiling and second floor roof framing at the circled location on the attached drawing in an effort to determine if its overall structural construction is able to carry the intended service loads.

Observations

We completed our observation and noted that this portion of the roof is currently carrying six mechanical units along with miscellaneous systems of mechanical piping and, of course, the roof membrane system itself. We were able to partially view the framing at the first ceiling/low roof at the second level. We also noted that there was partially exposed framing on the ground level. This framing is supported by interior loadbearing walls that have limited the span of the roof members to under 10 feet (were visible). Accordingly, we concluded that the existing framing is carrying the intended service loads with no visible signs of distress, deflection, or any other condition that would cause visible structural degradation.

Conclusion

We therefore consider this portion of the building framing to be structurally sound in its present condition.

Thank you for the opportunity to provide this information to you. Please contact our office if you are in need of further assistance. We reserve the right to amend this report if additional information becomes available.

Respectfully,

Carubba Engineering, Inc.

Roy M. Carubba, P.E. w/ attachments

O:\Carubba\2022\089 630 & 632 Bourbon Street\Documents\2022.06.15 Report.doc


3400 Hessmer Avenue - Metairie, Louisiana 70002 Phone: 504.888.1490 - www.carubbaengineering.com













VCC Architectural Committee


























CONSTRUCTION DOCUMENTS

327 BOURBON ST FACADE RENOVATION

327 BOURBON ST NEW ORLEANS, LA 70130

PROPERTY DESCRIPTION SQ 69 LOT 6 OR A BOURBON 43X128

PROJECT DESCRIPTION
BOURBON ST FACADE RENOVATION. NEXT PHASE OF A MULTI-PHASE RENOVATION.

RELATED PERMITS: DEMO (UDHYU3), ROOF (VL738P)

OWNER KARNO 327 BOURBON REAL ESTATE LLC 4828 JAMES ST METAIRIE, LA 70003

ZONING DISTRICT: VCE - VIEUX CARRÉ ENTERTAINMENT DISTRICT OVERLAY DISTRICT: VIEUX CARRE HEIGHT INTERIM ZONING DISTRICT

CONSTRUCTION TYPE: IBC/IFC: NFPA: TYPE III-B III (200)

OCCUPANCY TYPE:
IBC: VACANT
NFPA: VACANT

APPLICABLE CODES:
2015 IBC WITH CITY OF NEW ORLEANS CODE ADOPTIONS
2015 INTERNATIONAL MECHANICAL CODE
2013 LOUISIANA STATE PLUMBING CODE
2014 ANTONAL ELECTRIC CODE

2015 ADA ADDA GUIDELINES

ARCHITECT:
M3 DESIGN GROUP LLC
3328 BANKS ST.
NEW ORLEANS, LA 70119
MYLES M MARTIN LIC#7597
MYLES@M3-DESIGN-GROUP.COM
504-345-8350

PROJECT INFORMATION

- 1. THE GENERAL CONTRACTOR IS RESPONSIBLE TO SUPPLY ALL SUBCONTRACTORS WITH CONSTRUCTION DIAWNINGS AND SPECIFICATIONS INCESSANT TO BIG ANDIOR CONSTRUCT THE PROJECT.

 2. TO THE GENERAL CONTRACTOR AND ALL SUBCONTRACTORS ALL CONTRACTORS ARE RESPONSIBLE TO THE CONSTRUCTION SHOULD ALL SUBCONTRACTORS ALL CONTRACTORS ARE RESPONSIBLE TO THE CONSTRUCTION DOCUMENTS.

 3. ALL DIMENSIONS ON THE FLOOR PLANS, ILLUESS OTHERWISE NOTES, ARE TEXTED FROM INSIDE FACE OF STUDIO OF EXTERIOR WALLS, CONTRACTOR STUDIOS ON KIN WITEROOR PARTITIONS, FACES OR CENTRELINE OF STUDIOS OF EXTERIOR WALLS, CONTRACTOR STUDIOS ON KIN WITEROOR PARTITIONS, FACES OR CENTRELINE OF THE CONTRACTOR FOR ALL WILL HINKS ITS AND THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR WILL LIFE SOCIETY AND CONTRACTOR WILL LIFE SOCIETY AND CONTRACTOR WILL PERSONS AND PROPERTY DURING PERFORMANCE OF WORK, THIS REQUIREMENT WILL APPLY CONTRINUOUS LIFE AND CONTRACTOR WILL PERSONS AND PROPERTY DURING PERFORMANCE OF WORK, THIS REQUIREMENT WILL APPLY CONTRINUOUS ACCOUNTY OF THE CONTRACTOR WILL PERSONS AND PROPERTY DURING PERFORMANCE OF WORK, THIS REQUIREMENT WILL APPLY CONTRINUOUS ACCOUNTY OF THE CONTRACTOR OF THE CONTRACTOR WILL PERSONS AND PROPERTY OF THE PUBLE, THE CONTRACTOR WILL PERSONS AND PROPERTY DURING PERFORMANCE OF WORK, THIS REQUIREMENT WILL APPLY CONTRINUOUS ACCOUNTY OF THE PUBLE AND PUBLIC PROPERTY AND ACCOUNTY OF ACCOUNTY.

 4. WHETHER OR NOT SPECIFICALLY MOICHED ON THE DRAWNINGS, ALL, CONTRACTORS SHALL BE RESPONSIBLE.

 5. WHETHER OR NOT SPECIFICALLY MOICHED ON THE DRAWNINGS, ALL, CONTRACTORS SHALL BE RESPONSIBLE FOR THE PROPERTY OF ACCOUNTY.

- REPRESENTATIVE.

 8. COORDINATE WITH OWNER'S REPRESENTATIVE THE LOCATION OF CONTRACTOR'S EQUIPMENT AND
- B. COCRDIANTE WITH DOWNERS REPRESENTATIVE THE LOCATION OF CONTRACTOR'S EQUIPMENT AND MATTERIAL STRUCK DIDAMNINGS CONTRACTION FOR MAIL THE CONTRACTOR'S CONTRACTOR'S CONTRACTOR'S CONTRACTOR'S CONTRACTOR'S CONTRACTOR'S CONTRACTOR SHALL VERSIVE AND INSTALLED ITEMS AND COORDINATE INSTALLATION WITH CONTRACTOR SHALL VERSIVE CONTRACTOR SHALL WEIGHT INSTALLATION WITH CONTRACTOR SHALL VERSIVE AND CONTRACTOR SHALL PROVIDE AND INSTALLA LLA MATERIALS IN ACCORDIANCE WITH ALL LOCAL STATE, AND FEDERAL COORS SHALL BE FOR SHALL SHALL SHALL WITH SHALL WITH SHALL SH

GENERAL NOTES



SHEET LIST					
Sheet		Sheet Issue		Current Revision	Current Revision
Number	Sheet Name	Date	Current Revision	Date	Description
A1.0	TITLE SHEET	06/07/22			
A2.0	SPECIFICATIONS - COMMERICAL	06/07/22			
A3.0	EXTERIOR ELEVATION	06/21/22			
A4.0	DETAILS	06/07/22			







A1.0 TITLE SHEET



OURBON m

ENOVATION

 $\overline{\mathbb{Z}}$

CADI

ST

27 õ





CONSTRUCTION DOCUMENTS

06/07/22

SPECIFICATIONS

DIVISION 01 00 00. GENERAL REQUIREMENTS 01 50 00 - TEMPORARY FACILITIES AND CONTROLS

IS WORK SHALL CONSIST OF THE APPLICATION OF TEMPORARY MEASURES THROUGHOUT THE LIFE OF THE PROJECT.

31 07 - LEMPORARY UTILITIES

L CONNECTIONS AND EXTENSIONS REQUIRED TO PROVIDE TEMPORARY UTILITIES SHALL BE MADE BY THE CONTRACTOR AT THE CONTRACTOR

01 51 13 - TEMPORARY ELECTRICITY

0.5113.TEMPORANY ELECTRICITY

OFFICIAL TEMPORANY ELECTRICITY

OFFICIAL TEMPORANY

OFFI

01 S2 19 - SANITARY FACILITIES

EXSTING PACLITIES SHALL NOT BE USED. CONTRACTOR SHALL PROVIDE AND MAINTAIN HA NEAT AND SANITARY CONDITION SUCH

ACCOMMODATION FOR THE USE OF HIS EMPLOYEES AS WILL COMPLY WITH LAWS AND REGULATIONS. TRAPPGRAPY TOLET FACILITIES MAY CONSIST

ACCOMMODATION FOR THE USE OF HIS EMPLOYEES AS WILL COMPLY WITH LAWS AND REGULATIONS. TRAPPGRAPY TOLET FACILITIES MAY CONSIST

SUPPLIED AND CLEAR AND IN SANITARY CONDITION UNTIL THE COMPLETION OF THE WORK AND THEN SHALL BE REMOVED FROM THE STEEL UPON

01 58 00 - PROJECT IDENTIFICATION

WITHIN 15 DAYS AFTER THE COMMENCEMENT OF WORK, PROVIDE ONE PROJECT IDENTIFICATION SIGN AT THE LOCATIONS INDICATED. MAINTAIN SIGN THROUGHOUT THE LIFE OF THE PROJECT. ON THE SIGN, LIST TWO POINTS OF CONTACT BY NAME AND TELEPHONE NUMBER.

9 59 09 - PRODUCT REQUIREMENTS (BCOPF OF WORK)
ALL MATERIALS SHALL BE RISTALLED IS TREET AS TO STREET AS THE MANUFACTURERS WRITTEN SPECIFICATIONS OR MATERIALS INSTITUTE
STANDARDS WHERE THE MANUFACTURERS RECOMMENDED DETAILS ARE USED. THE MANUFACTURERS SHALL BE RESPONSIBLE FOR THE
PERFORMANCE OF THEIR PRODUCT. ALL TERM NOT SPECIFICALLY MENTIONED THAT ARE REQUIRED TO MAKE THE WORK COMPLETE AND
THE PROPRIEMENT OF THEIR PRODUCT ALL TERM NOT SPECIFICALLY MENTIONED THAT ARE REQUIRED TO MAKE THE WORK COMPLETE AND
THE PROPRIEMENT OF THE REPORT OF THE PROPERTY O OPERATIONAL SHALL BE INCLUDED.

01 62 90 INSTALLATION AND STORAGE- ALL MATERIALS, SUPPLIES AND EQUIPMENT SHALL BE INSTALLED PER MANUFACTURERS RECOMMENDATIONS AND PER APPLICABLE CODES AND RECORDINGEMENTS. MATERIAL STORED ON SITE SHALL BE PROTECTED FROM DAMAGE BY MOISTURE, WIND, SUN, ABUSE OR ANY OTHER HARMING. EFFECTS.

OT 100 - SECURION AND CLOSEDY ROUTEWINDS.

THE EXECUTION OF ALL WORK SHALL BE IN STRUCT ACCORDANCE WITH THESE SPECIFICATIONS AND LIABILITATIONS FOR DIAMPLACTURER WRITTEN SPECIFICATIONS.

THE EXECUTION OF ALL WORK SHALL BE IN STRUCT ACCORDANCE WITH THESE SPECIFICATIONS. THE MANUFACTURER WRITTEN SPECIFICATION SPECIFICATION AND SECURITY OF THE PERFORMANCE OF THEIR PRODUCT ALL WORK NOT PSECIFICATION SHALL BE INCLUDED.

COMPLETE AND OFFERATIONAL SHALL BE INCLUDED.

COMPLETE AND OFFE

0171 00 - LOCAL CONDITIONS
BUILDING REQUIREMENTS SHALL BE IN COMPLIANCE WITH ALL APPLICABLE LOCAL AND REGIONAL CODES, CONSTRUCTION TECHNIQUES AND
WEATHER CONDITIONS.

0174 00 - CLEANING AND WASTE MANAGEMENT
CONSTRUCTION SITE TO BE IN A CLEAN AND ORDERLY CONDITION THROUGHOUT THE CONSTRUCTION PROCESS. CLEAN INTERIOR SPACES PRIOR
TO THE START OF PRISE! PARTING NO THE PRIVATION OF OTHER PRISERS AT THE CONCLUSION OF CONSTRUCTION. THE PROJECT SHALL BE
TO THE START OF PRISE! PARTING NO THE PRIVATION OF OTHER PRISERS.
THE CONCLUSION OF CONSTRUCTION. THE PROJECT SHALL BE
REMOVE TEMPORARY LABELS. STAINS AND FOREIGN SUBSTANCES, POLISH TRANSPARENT AND GLOSSY SURFACES, VACUUM CAPPETED AND SOFT
SURFACE AREAS, SWEEP AND MOW ALL TILE OS SUPPLICES. ETC. REPLACE E HERE OF OPERATION COMPITIENT, CHARLES AND FOREIGN SUBSTANCES. POLISH TRANSPARENT AND GLOSSY SURFACES, VACUUM CAPPETED AND SOFT
A SANITARY CONDITION. CLEAN EXTERIOR SUCH AS DEBRIS FROM ROOF, GUTTERS, LANDSCAPE AREAS, DRIVEWAYS AND WALKS, ETC. REMOVE ALL
WASTE AND SURPLY MANTERUAS.

0176.00 - PROTECTING INSTALLED CONSTRUCTION
CONTRACTOR TO PROTECT ALL INSTALLED CONSTRUCTION. IF PRODUCTS OR MATERIALS COME WITH A PROTECTIVE COATING, CONTRACTOR SHALL
MAINTAIN PROTECTIVE COATING UNTIL CONSTRUCTION IS COMPLETE. CONTRACTOR SHALL REPLACE ANY ITEMS THAT BECOME DEFECTIVE OR

CONTRACTOR SHALL REVIEW CONSTRUCTION DOCUMENTS AND PROVIDE NECESSARY SITE WORK, EXCAVATION AND GRADING AS REQUIRED TO CONSTRUCT SAID PROJECT.

0.4 14 to - DEMOLITION
PROVIDE ALL ADDIS MATERIALS AND EQUIPMENT TO PERFORM THE REQUIRED DEMOLITION OF EXISTING PAVEMENT NO LONGER NEEDED FOR ACCESS ON PARMINA, AGAINGHOUS UTLITIES AND STRUCTURES WHICH INTERPRET WITH THE PROPOSED CONSTRUCTION, WHEN REQUIRED INSTITUTED ACCESS ON PARMINA, AGAINGHOUS AND STRUCTURES WHICH INTERPRET WITH THE PROPOSED CONSTRUCTION, WHEN RECUIRED INSTITUTED ACCESS ON PARMINA AND ACCESS OF THE DESIGNATION BEGINS.

02 81 00 - TRANSPORTATION AND DISPOSAL OF HAZARDOUS MATERIALS REMOVE AND DISPOSE OF ANY HAZARDOUS MATERIAL BEFORE BEGINNING CONSTRUCTION. CONTACTOR SHALL CONTRACT WITH A PROPERLY LICENSED AND QUALIFIED HAZARDOUS MATERIAL CONTRACTOR.

IS 10 R. FOULD CARPOITTY

LIMBER SHALE OF IVE. SOUND STOCK AND PROPERLY DRIED. PRESSURE TREATED LUMBER SHALL BE USED WHERE ANY LUMBER SHALL COME
INTO CONTRACT WITH CONCRITE, MAGGINFY BLOCK OR SOIL AND WHEN LIBING AS SUPPORT MEMBERS FOR DECKS, PORCHES OR BALCOWES.

INTO CONTRACT WITH CONCRITE, MAGGINFY BLOCK OR SOIL AND WHEN LIBING AS SUPPORT MEMBERS FOR DECKS, PORCHES OR BALCOWES.

PROVIDE AREDINE REMONED AND SHORNED DURBNER FOR CONSTRUCTION REPORTS. STUDIES AND DISTS DUTT ON STATE, LIMBERING ANDOW WRING
SHALL BE REINFORCED BY ADDING METAL OR WOOD STRUCTURAL REPROPICTION. TO STRENGTHER MEMBER BACK TO ORIGINAL CAPACITY AND
MAKING STRUCTURAL REVERTINY. THE SORDED MALK HOT SELEMENT HAN 10 THE EXPENT HAND NOT CLOSES THAT YET THE TOP OR SOTTOM
MAKING STRUCTURAL REVERTINY. THE SORDED MALK HOT SELEMENT HAN 10 THE EXPENT HAND AND TOLCHISCEN HAY TO THE TOP OR SOTTOM
MAKING STRUCTURAL REVERTINY. THE SORDED MALK HOT SELEMENT HAND 10 THE EXPENT HAND THE TOP THE OR SOTTOM
MAKING STRUCTURAL REVERTINY. THE SORDED MALK HOT SELEMENT HAND 10 THE EXPENT HAND 10 THE COPY FOR THE TOP THE TOP OR SOTTOM
MAKING STRUCTURAL REVERTINY. THE SORDED MALK HOT SELAMENT HAND 10 THE EXPENT HAND 10 THE COPY FOR THE TOP THE TOP OR SOTTOM
MAKING STRUCTURAL REVERTINY. THE SORDED MALK HOT SELAMENT HAND 10 THE EXPENT HAND 1 WOOD SPECIES: #2 SOUTHERN YELLOW PINE, DOUGLAS FIR. ETC.

16 1 16 1. WOOD FINAMING.
PROPERTIES AND STANDARD OF THE THE PROPERTIES OF CONVENTIONAL STICK FRAMING, PRESSURE TREATED LUMBER SHALL BE USED WHERE ANY LUMBER SHALL COME INTO CONTROL WITH THE PROPERTIES OF THE P

INTERIOR WALLS

ALL INTERIOR WALLS

ALL INTERIOR WALLS

ALL INTERIOR WALLS SHALL BE WOOD STUDS, WITH SINGLE BOTTOM PLATES AND DOUBLE TOP PLATES THROUGHOUT. PROVIDE SOLD BLOCKING

AT MID-REIGHT OF ALL WALLS WHICH EXCEED \$\phi\$ or IN HEIGHT.

72.4 STUDED PLACED INFOR CERTER (PC). "TYPICA"

97 32 09 - JOHT SEALANTS
USE AS VERY SEALANTS
USE AS VERY SEALANTS
USE AS VERY SEALANTS
USE AS VERY SEALANTS
ADDITION OF THE SEALANTS
ADDITION OF

08 00 00 - OPENINGS
CONTRACTOR SHALL REVIEW CONSTRUCTION DOCUMENTS AND PROVIDE LABOR AND MATERIALS PERTAINING TO THE DOORS AND WINDOWS AS REQUIRED IN SAID DOCUMENTS AND AS SPECIFIED HEREIN, WHILE COMPLYING WITH ALL APPLICABLE BUILDING CODES. IN ALL SLEEPING AREAS PROVIDE AN OPERABLE EGRESS STANDARD WINDOW OR DOOR DIRECTLY TO EXTERIOR.

- 1. THE GENERAL CONTRACTOR IS RESPONSIBLE TO SUPPLY ALL SUBCONTRACTORS WITH CONSTRUCTION ROWNING AND SPECIFICATIONS NECESSARY TO BIO ANDIOR CONSTRUCT THIS PROJECT.

 2. TO THE GENERAL CONTRACTOR AND ALL SUBCONTRACTORS: ALL CONTRACTORS ARE RESPONSIBLE TO NOTIFY THE ACCHIETCE OF ANY CHANGE STRONG OF DISCREPANCIES PROJE TO MAKING ANY CHANGE TO ANY CHANGE TO THE CONTRACTOR AND ALL SUBCONTRACTORS.
- NOTIFY THE ANCHITECT OF ANY ENTONS, UNIQUEDITY ON DISJONERATIONS OF THE CONSTRUCTION DOCUMENTS.

 THE CONSTRUCTION DOCUMENTS.

 ALL DIMENSIONS ON THE FLOOR PLANS, UNLESS OTHERWISE NOTED, ARE TAKEN FROM INSIDE FACE OF STUDS OF STERRIOR WALLS, CENTER OF STUDS OF NEW INTERIOR PARTITIONS, FACES OR CENTERLINE OF
- STUDIS OF EXTERIOR WALLS, CENTER OF STUDIOS OF NEW INTERIOR PARTITIONS, FACES OR CENTERLINE C STRUCTURAL COLUMNS, AND FACES OF EXISTING WALLS.

 4. THE OWNER SHALL BE RESPONSIBLE FOR NOTHER THE GENERAL CONTRACTOR FOR ALL WALL HUNG ITEMS TO BE INSTALLED THAT ARE NOT ON THE DRAWINGS.
- TEMS TO BE INSTALLED THAT ARE NOT ON THE DRAWNINGS.

 5. IN ACCORDANCE WITH GENERALLY ACCEPTED CONSTRUCTION DAY.

 5. IN ACCORDANCE WITH GENERALLY ACCEPTED CONSTRUCTION DAY.

 5. IN ACCORDANCE WITH GENERALLY ACCEPTED CONSTRUCTION DAY.

 5. IN ACCORDANCE WITH GENERALLY ACCEPTED CONSTRUCTION OF THE JOB SITE. INCLUDING SAFETY OF ALL PRESSONS AND PROPERTY DURING DEFEORMANCE OF WORK. THIS REQUIREMENT WILL APPLY CONTINUOUSLY AND NOT BE LIMITED TO NORMALL WIGHING HOURS. THE CONTINUOUS PARALLY ACCEPTED AND ALL PROPERTY OF CONTINUOUSLY AND NOT BE LIMITED TO NORMALLY ACCEPTED AND ACCEPTED THE PRESSURS. THE CONTRACTOR SHALL COMPLY WITH ALL LAWS, ORDINANCES, CODES, RULES AND REGULATIONS RELATIVE TO SAFETY AND THE PREVENTION OF ACCIDENTS OF THE PREVENTION OF ACCIDENTS.

 6. WHETHER OR NOT SPECIFICALLY SOLICIATED ON THE DRAWNINGS, ALL CONTRACTORS SHALL BE RESPONSIBLE FOR REMOVING OF DEMOLSHING EXISTING CONSTRUCTION (INCLUDING UTILITIES) WHICH WILL HEREFERE
- PRIOR TO THE SHUT-DOWN OR TYING INTO ANY UTILITY, APPROVAL SHALL BE OBTAINED FROM THE OWNER'S
- COORDINATE WITH OWNER'S REPRESENTATIVE THE LOCATION OF CONTRACTOR'S FOUIPMENT AND 9. THE CONSTRUCTION DRAWINGS CONTAIN INFORMATION FOR MULTIPLE CONTRACTORS, OWNER PROVIDED
- AND INSTALLED ITEMS ARE SHOWN FOR INFORMATIVE PURPOSES. THE GENERAL CONTRACTOR SHALL VERIFY OWNER PROVIDED AND INSTALLED ITEMS AND COORDINATE INSTALLATION WITH OWNER'S REPRESENTATIVE
- 10. CONTRACTOR SHALL PROVIDE AND INSTALL ALL MATERIALS IN ACCORDANCE WITH ALL LOCAL STATE, AND FEDERAL CODES.

 11. ALL PERMIT FEES SHALL BE PAID BY CONTRACTOR.
 12. CONTRACTOR SHALL BE RESPONSIBLE FOR AND PAY FOR ALL UTILITY DEPOSITS, IMPACT FEES AND CONNECTION FEES REQUIRED.

VIEUX CARRé COMMISSION APPROVED STANDARD MORTAR & STUCCO DETAILS

MORTAR PREPACKAGED MIXES ARE NOT PERMITTED.

- PREPAZAGUEM MAS ARE NOT PERMITTED.

 NO MORE TO THAN DECEMENT, TO

 3 PARTS LIME.

 3 PARTS LIME.

 9 PARTS SAND, AND

 ENOUGH WATER TO FORM A WORKABLE MIX.

 THE RESILLTION MORTRAS SHOULD RANGE IN COLOR FROM WHITE TO BEIGE BUT SHOULD NOT BE GREY IN COLOR, WHEN REPORTING, ALL MORTRAS TO BE TOOLED TO MATCH EXISTING JOINT PROPELES CONSULT WITH VCC STAFF IF EXISTING JOINT PROPELES MORTRAINED.

- STUCCO

 PREPACAGED MIXES ARE NOT PERMITTED

 BASE COAT CONSISTS OF 2 COATS, DOUBLED UP WORK OF 58" TOTAL THICKNESS, PROPORTIONED AS FOLLOWS:

 1. NO GREATER THAN 112 PART PORTLAND CEMENT, TO

 1.3 PARTS LIME, AND
- 6 LBS/CUBIC YARD HAIR OR FIBER, AND
- ENOUGH WATER TO FORM A WORKABLE MIX.
 FINISH COAT IS 1/4" IN TOTAL THICKNESS PROPORTIONED AS FOLLOWS:
- NO MORE THAN 1 PART PORTLAND CEMENT.
- LI 9 PARTIS SANUL.

 E BANQUEN WHER TO FORM A WORKABLE MIX.

 THE RESULTING MIX SHOULD RANGE IN COLOR FROM WHITE TO BEIGE BUT SHOULD NOT BE GREY IN COLOR. NOTE: RATIO
 OF PORTLAND CEMENT NOT TO EXCEED 1:12. AN INCORRECT MORTAR CAN DAMAGE AN HISTORIC BUILDING AND ITS

WHEN RE-PORTING MASORRY
THERE ARE NUMBEROUS JOINT PROFILE TYPES, OR SHAPES, OF MORTAR JOINTS, EACH PRODUCING DIFFERENT SHADOW
FINES AND HIGHLIGHTS. WHEN REPAINTING AN AREA OF NASORRY, IT IS IMPORTANT TO TOOL THE MORTAR TO MARCH
RIVE EXISTING JOINT PROFILE FOR A CONSISTENT APPEARANCE.

GENERAL NOTES - VCC STUCCO & MORTAR DETAILS













SALVAGED UPPER TIN CORNICE FROM 327 BOURBON ST, IN SAFE STORAGE, TO BE RE-INSTALLED






3 BOURBON ST ELEVATION
3/16" = 1'-0"





SCOPE ITEM (ELEVATION)






A3.0


327 Bourbon

SCHEDULED FOR RESTORATION ELEVATION TAG

SPECIFIC NOTE
WINDOW TAG, SEE WINDOW SCHEDULE

LEGEND





LIMITS OF WORK-

BOURBON ST



July 12, 2022


327 Bourbon

VCC Architectural Committee

3 BOURBON ST ELEVATION
3/16" = 1'-0"








WINDOW DETAILS - WOOD DBL HUNG,




W03 PAINTED WOOD, SINGLE HUNG, 6 OVER 9
RESTORE

W002 W00D, DOUBLE HUNG, 6 OVER 6
RESTORE




1 UPPER CORNICE ATTACHMENT DETAIL
1 1/2" = 1'-0"




VERIFY WITH EXISTING WINDOW OPENING

NEW SHUTTER TO BE INSTALLED



CONTRACTOR TO SUBMIT MILLWORK SHOPDRAWINGS FOR ARCHITECT / VCC REVIEW & APPROVAL PRIOR TO FABRICATION OR INSTALLATION.

2 SHUTTER ELEVATION1
3/4" = 1'-0"



WINDOW DETAILS - WOOD DBL HUNG,

3 EXISTING OPENING

