
# Vieux Carré Commission Meeting

Wednesday,
September 16, 2020










#### WHAT THIS MEANS FOR NEW ORLEANS

The FCC has granted certain rights to carriers and infrastructure providers allowing them the right to install small cells in your Public ROW. If you don't get ahead of the problem and put into place the designs necessary to mitigate what these installs look like you could find yourself with an onslaught of poles that actively degrade your ROW's aesthetic.



### PREVIOUS FRENCH QUARTER SMALL CELL PROPOSA<sup>®</sup>L7 of 128





Each orange square represents one (1) linear foot.

## CURRENT FRENCH QUARTER SMALL CELL PROPOSAL 128





**BEFORE** 


**AFTER** 

# 4G OR 5G GAS LAMP SMALL CELL COLOCATION DESIGN



Toro Blanco Group, LLC

#### **POLE SIZE COMPARISONS**



Each orange square represents one (1) linear foot.




Each orange square represents one (1) linear foot.


20' PROPOSED SMALL CELI








1005-09 St Philip





1005-09 St Philip









Vieux Carré Commission








Vieux Carré Commissio
























































































































524 Esplanade - 1939




















524 Esplanade - 2005





524 Esplanade - 2005







524 Esplanade
























































Vieux Carré Commission









Vieux Carré Commissio

**OPTION A** 


SCALE: 1/2" = 1"-0"


(OMNER'S PREFERENCE DUE TO
GEOMETRY OF THE SUPPING CURVE
FROM THE WINDING STEPS)


**OPTION B**SCALE: |/2" = |'-0"











## **OPTION A**

SCALE: 1/2'' = 1'-0''

(OWNER'S PREFERENCE DUE TO GEOMETRY OF THE SLOPING CURVE FROM THE WINDING STEPS)

## **OPTION B**

SCALE: 1/2" = 1'-0"


## **OPTION C**


SCALE: 1/2'' = 1'-0''

(VCC STAFF PREFERENCE)









921 Chartres





Vieux Carré Commission








Vieux Carré Commission
































921 Chartres – Previously Existing Gutters and Downspouts






921 Chartres – 1998 – Previously Existing Railing







921 Chartres – 1998 – Previously Existing Railing








A Creole home, such as this townhouse, often has a simple balustrade and convex bulging posts.

## **BALUSTRADES & RAILINGS**

A balustrade is a railing with upper and lower horizontal members, known as rails, and vertical balusters of wood or metal. A replacement balustrade should match the overall style and character of the building.




A turned wood balustrade, produced by turning and carving square balusters on a lathe, are appropriate for most Italianate, Queen Anne, Eastlake, Classical Revival and Colonial Revival homes. Historic balusters tend to be wider than many new, mass-produced balusters.






A discrete, higher secondary safety rail has been installed behind the cast iron balustrade to meet building code requirements. An alternative would be to raise the historic balustrade to the required height.




The VCC does not approve requests for a wood "deck" balustrade (A), applied decorative scrolled metal ornament balustrade (B) or a balustrade composed of metal pickets welded to metal bars (C).






Colonial Revival homes. Historia balasters than many new, mass-produced balasters.



The VCC does not approve requests for a w (B) or a balustrade composed of metal pick

921 Chartres – From Guidelines







3200 Veterans Memorial Blvd. ste. A Metairie, La 70002

Phone (504) 214-5026 Fax (504) 469-3571

August 17, 2020

## **Estimate**

# Repairs

Here is an estimate for your property located at 921 Chartres St., New Orleans, La.

Exterior Repairs:

Remove and replace approx. 220 ft of lower rail, handrail, spindles, and posts as needed to conform to current VCC guidelines

Prime and paint as needed new materials

Remove and replace approx. 612 ft of 6" half round gutters and downspouts

Profit and overhead:

Materials and labor: \$118,360.00

Total: \$118,360.00

Thank you Samuel Zavala 214-5026





2632 Oak Forest Blvd. Marrero, La, 70072 504-415-5771

AJ. Dantin

09/03/2020

Chartres Street Condo Association

#326

921 Chartres Street NEW ORLEANS, LA. 70130

DESCRIPTION OF WORK			
Following prices are subject to change due to the 17% increase in lumber in			
Lumber in the last month.			
HANDRAILS Approx. 220 lineal feet			
Removal of 220 L/F of existing railings and post. Remove all			
debris from site and haul away.	2221/5	624.001.75	*****
	220 L/F	\$21.00 L/F	\$4620.00
Replace 220 lineal feet of handrails and post			
Top rail half round 4" pine treated, bottom rail			
spindle groved 4" pine treated, 2x2 pine treated			
spindles, 4" pine treated spindle rest plate upper and			
lower. All rails primed and painted.			
	220 L/F	\$168.00 L/F	\$36,960.00
	Approx.	11%	\$4065.60
	Increase	1176	\$4003.00
4"x 4"x 4' Support Post pressure treated pine.	32	\$72.00	\$2304.00
18- 4"x 6" Balcony treated support post with one		£750.00	£43.500.00
rounded ring and cap.		\$760.00	\$13,680.00
6" Half Round Copper Gutters			
Prices due to change depending on current penny weight.			
Removal of Approx. 612 lineal feet of existing gutters	612 L/F	\$8.00	\$4896.00
Replace with 6" half round copper gutters and holders	612 L/F	\$58.00	\$35,496.00
Replace 24' down spouts with 6" copper rounded spout.	288 L/F	\$62.00	\$17,856.00
Install 12- 24"x24" copper water catcher boxes	12	\$279.00	\$3348.00
Architectural Drawings-Permits-VCC Inspections & Approvals		Approx. cost	\$4100.00
	Approx. Total is		\$122,705.60

just an estimate

\$122,705.60

921 Chartres – Estimate From Applicant

Looking forward to serving you when needed!



Page 79 of 128




451-8/31 Cell Chuck.rans	deil@gmail.com			
921 Chartres Railing/gutter replacement				9/8/2020
GENERAL JOB ITEMS	Materials	Labor	Subs	
City permits - City & VCC (approximate cost)	1,500	650		
Site protection protection	375	950		
Demo existing balcony handrails	600	1,980		
Trash hauls/daily clean-up	600	2,400		
Final clean-up	200	550		
•				9,805
CARPENTRY - Exterior	Materials	Labor	Subs	
Rebuild 2nd courtyard balconies railings 220 sq ft	6,500	34,000		
				40,500
PAINT	Materials	Labor	Subs	
Complete exterior trim	1,950	37,850		
				39,800
ROOFING	Materials	Labor	Subs	
Remove/replace 6" 1/2-round gutters & 3" downspouts w/ copper			17,300	
				17,300
TOTALS	11,725	78,380	17,300	107,405

B-TOTALS			
GENERAL JOB ITEMS	Ç	9,805.00	
OPENINGS & FINISH CARPENTRY - Exterior	Ş	40,500.00	
PAINT	Ş	39,800.00	
ROOFING	<u> </u>	17,300.00	_
Sub-Total	\$	107,405.00	_
Gen Liability Ins (6% of Sub-Total 1)	6% \$	6,444.30	
Workers Comp (16% of LABOR total)	16% \$	12,540.80	
Oversight/P&O (16% of Sub-Total 1)	16%_\$	17,184.80	_
TOTAL		143,574.90	-


## NOTES:

- Price does not include costs of electrical/lighting fixtures
- HVAC work is not included
- Remedial framing/trim repair after handrail demo










1118 Burgundy















1118 Burgundy




1118 Burgundy



# **BOUNDARY SURVEY OF** LOT 1 **SQUARE 83** SECOND DISTRICT ORLEANS PARISH, LA DAUPHINE (SIDE) STREET //31.11.5 3.6.0 STREE OUTDOOR URSULINES 601. 0.6.0 0.7.2 3.11.5 #1118-20 127.2.7 BURGUNDY STREET ALL ANGLES ARE 90' UNLESS OTHERWISE NOTED. SOME ITEMS MAY NOT BE TO SCALE FOR CLARITY, DIMENSIONS ON SURVEY PREVAIL OVER THE SCALE. FENCES ARE SHOWN FOR GENERAL INFORMATION PURPOSES ONLY AND DO NOT REFLECT EXACT LOCATION OR CONDITION. GENERAL NOTES THE SERVITUDES SHOWN ON THIS SURVEY ARE LIMITED TO THOSE FURNISHED US AND THERE IS NO REPRESENTATION THAT ALL APPLICABLE SERVITUDES ARE REFLECTED OR SHOWN HEREON. THE SURVEY HAS MADE NO TITLE SEARCH OR PUBLIC RECORD SEARCH IN COMPILING THE DATA FOR THIS SURVEY. RICHMOND W. KREBS REG. NO 4835 THIS PERIMETER SURVEY SHALL NOT CONSTITUTE A LEGAL OPINION OF TITLE, AND SHALL NOT BE RELIED UPON FOR THAT PURPOSE, THERE IS NO WARRANTY THAT IT CONFORMS TO THE LEGAL TITLE, AND WAS MADE SOLELY ACCORDING TO THE INFORMATION PROVIDED THE SURVEYOR. ELEVATION NOTES THIS IS CERRPY THAT SUBJECT PROPERTY IS LOCATED IN THE FOLLOWING FLOOD ZONE, PER FLOOD INSURANCE RATE MAP (FIRM) DATED: 9/30/16 FLOOD ZONE: X BASE FLOOD ELEVATION: NO. PROFESSIONAL LAND SURVEYING, LLC OMINISTRATIVE CODE TITLE: 46:LXI, CHAPTER 29 FOR A CLASS "C" RICHMOND W. KREBS, SR., PLS 3445 N. CAUSEWAY BLVD, SUITE 201 ADE AT THE REQUEST OF PENTEK HOMES METAIRIE, LA. 70002 PHONE: (504) 889-9616 FAX: (504) 889-0916 E-MAIL: infonola@rwkrebs.com WEB: www.rwkrebs.com CHECKED BY: RWK JOB #: 201561

# 1118 Burgundy











1118 Burgundy – unpermitted exterior kitchen





1118 Burgundy – unpermitted exterior kitchen





1118 Burgundy – unpermitted exterior kitchen





1118 Burgundy – unpermitted exterior kitchen





1118 Burgundy – unpermitted exterior kitchen







1118 Burgundy – unpermitted exterior kitchen

Vieux Carré Commission

September 16, 2020



1118 Burgundy – unpermitted exterior kitchen





1118 Burgundy – unpermitted exterior kitchen





1118 Burgundy – unpermitted exterior kitchen





1118 Burgundy – unpermitted exterior kitchen








1118 Burgundy – unpermitted exterior kitchen




## DIMENSIONAL RENDERINGS









Overall Product Dimensions				
Model No.	Height	Width	Depth	
C2SL42	23"	42 1/2"	25 1/2"	
CJAKTCS42	11"	44 1/8"	23"	

Cutout Dimensions for Island					
Model No.	Height	Width	Depth		
C2SL42	10 1/4"	39 1/2"	20 1/2"		
CJAKTCS42	11"	42 1/4"	22 1/8"		


√ When using a Coyote insulated jacket, you will want to build your island to the jackets Cutout and Overall Dimensions. listed above (detailed on 2nd page). Once the jacket is installed, the grill will rest on/inside the insulated jacket


Model No.	Gas Supply	BTU's	Regulator	WC Pressure	Max PSI	Electrical Requirements
C2SL42LP	Propane	110,000	20 lb Tank Regulator	11"	.5 PSI	Qty 1 - 120 VAC 60 Hz Grounded Plug
C2SL42NG	Natural Gas	110,000	1/2" Female Pipe	4"	.5 PSI	Qty 1 - 120 VAC 60 Hz Grounded Plug

Important Note to Installer: This file is not intended to replace your Owners' Manual which contains specific safety requirements and consumer guidelines. Please refer to your Owners' Manual prior to installing or operating your built-in grill.



### NON-COMBUSTIBLE CONSTRUCTION Insulated Jacket NOT Required






FRONT VIEW

- ✓ Combustible material can not be within 24" of the grills frame
- ✓ This applies to all directions horizontal & vertical ✓ Shaded area above on "TOP VIEW" illustrates the 24" minimum
- requirement (not to scale for rendering purposes)
- ✓ The grill is designed to hang from the counter top with no support
- ✓ Minimum rear clearance for the hood to open is 2"
- If you have a wall/partition behind the grill, the minimum rear clearance to that wall should be at least 7" to allow for ventilation of the exhaust

## **COMBUSTIBLE CONSTRUCTION**

Insulated Jacket Required - Model # CJAKTCS42



### FRONT VIEW

- If using combustible material within 24" of the grill frame, you MUST use the corresponding Coyote Insulated Jacket
- Using a insulated jacket, does not waive any other standard installation procedure (ventilation, connections, etc)
- The jacket is designed to hang from the counter top with no support underneath
- Minimum clearance for hood to open is 2"
- If you have a wall/partition behind the grill, the minimum rear clearance to that wall should be at least 7" to allow for ventilation of the exhaust

- ✓ Regardless if you are using a combustible or non-combustible building material, you must include at least two vents within the island.
- ✓ These vents must be at least 20 sq. in. each and allow fresh air to move from the grill cabinet to the exterior environment.
- √ For a propane setup, the vents should be installed lower as propane is heavier than air
- ✓ For a natural gas setup, the vents should be located higher in the island, as natural gas is lighter than air.
- ✓ Do not locate the two vents on the same wall of the island. Cross ventilation is key to allow any excess heat or trapped gas to dissipate.

Important Note to Installer: This file is not intended to replace your Owners' Manual which contains specific safety requirements and consumer guidelines. Please refer to your Owners' Manual prior to installing or operating your built-in grill




1118 Burgundy – unpermitted exterior kitchen







Page 102 of 128









### **Key Features**

- Makes clear cubes approx. 7/8" W x 7/8" H x 7/8" L
- · Produces up to 60 lb of ice per day
- · Stores up to 30 lb of ice
- · Digital touch pad control with blue LED display
- . U-Choose™ feature offers five levels of ice fullness
- · Silent setting temporarily suspends ice making for 3 hours
- . Indicator alert notifies user when cleaning is needed
- · Easiest clear ice machine cleaning process in the industry

- · Bright white LED lighting
- Milata Introduce
- · Stainless steel cabinet, toe-kick, and full-wrap door

Stainless Solid

1 U-LINE

- Stainless steel handle (7/8" diameter)
- Field reversible door is shipped right-hand hinged
- · Built-in or freestanding
- · Four adjustable leveling legs
- Factory installed drain pump model recommended if a gravity drain is not accessible

### **Model Details**

Model	Voltage/Hz	Door Swing	Pump	Finish	Shipping Weight
UOCL115-SS01A	115 / 60	Field Reversible	=:	Stainless Solid	96 lb.
UOCP115-SS01A	115 / 60	Field Reversible	Pump Included	Stainless Solid	101 lb


### Accessories

Model	Description	Finish	Shipping Weight
ULACLRCLEAN	Clear Ice Machine Cleaner (1 box of 6 packets)	N/A	1 lb
ULAWATERHOOKUP	Braided Water Supply Line Kit	N/A	2 lb


### **Specifications**

Model	OCL115
Amps: Running	4
Amps: Ice Harvest	5.5
Dimensions: Product Depth	22 ¼" / 562 mm
Dimensions: Product Height	34 1/8" / 867 mm
Dimensions: Product Width	14 <sup>15</sup> / <sub>16</sub> " / 379 mm
Energy Consumption: Avg. Per Year	N/A
ENERGY STAR	N/A
Ice Production Per Day	60 lb
Ice Storage	30 lb
Product Weight: Max	101 lb
Refrigerant Type	R134a
Sabbath (Star K Certified)	No

### Back



### **Cabinet Cut-Out**



### Warranty

- 1 Year (parts & labor) / 5 year sealed system (parts)
- 2 Year (parts & labor) / 5 year sealed system (parts) upgrade at no cost with product registration

See complete warranty for details

## •

### 15" cutout width sufficient if door protrudes beyond adjacent cabinetry

- No additional clearance is needed for ventilation
- Do not obstruct front grille air flow

**Installation Notes** 




All specifications are subject to change without notice.

# 1118 Burgundy – unpermitted exterior kitchen



-Page 103 of 128


### **Dimensions**



### **Specifications**

Model	ODR124
Amps: Running	1.2
Capacity: Bottle (12 oz)	98
Capacity: Can (12 oz)	150
Capacity: Volume (cu ft)	5.4
Capacity: Wine Bottle (750 ml)	N/A
Dimensions: Product Depth	23 ¼" / 591 mm
Dimensions: Product Height	34" / 864 mm
Dimensions: Product Width	23 <sup>15</sup> / <sub>16</sub> * / 608 mm
Energy Consumption: Avg. Per Year	305 kWh
ENERGY STAR	N/A
Product Weight: Max	142 lb
Refrigerant Type:	R600a
Sabbath (Star K Certified)	Yes
Temperature Range	34°F - 60°F





- . 1 Year (parts & labor) / 5 year sealed system (parts)
- · 2 Year (parts & labor) / 5 year sealed system (parts) upgrade at no cost with product registration

### **Installation Notes**

- . No additional clearance is needed for ventilation
- · Do not obstruct front grille air flow



Please visit u-line.com to view this model's User Guide & Service Manual. All Specifications are subject to change without notice.

8900 North 55th Street • Milwaukee, Wisconsin 53223 USA • Phone +1.414.354.0300 • Fax +1.414.354.7905 • u-line.com



### **Key Features**

- · Convection cooling system provides a quick cool down and consistent temperature
- . Digital touch pad control with blue LED display
- · Stainless steel cabinet, toe-kick, and drawer fronts
- . Volume of 5.4 cu ft holds up to 98 bottles (12 oz) or 150 cans
- Temperature range: 34°F 60°F

- · Bright white LED lighting
- · Two full-extension stainless steel drawers
- · Stainless steel handles (% diameter)
- · Built-in or freestanding
- · Four adjustable leveling legs

### **Model Details**

Model	Voltage/Hz	Door Swing	Finish	Shipping Weight
UODR124-SS01A	115 / 60	Field Reversible	Stainless Solid	142 lb

### Accessories

Model	Description	Finish	Shipping Weight
U-FSK-S	Freestanding Kit	Stainless	3 lb

# 1118 Burgundy – unpermitted exterior kitchen











# Back



## **Cabinet Cut-Out**

### Warranty



See complete warranty for details
















715-19 Bourbon












715-19 Bourbon












September 16, 2020



September 16, 2020






ORLEANS STREET

# 1 FIRST FLOOR DEMOLITION PLAN A-1 SCALE: 1/4" = 1'-0"




















715-719 Bourbon

- EXISTING STEPS TO BE REMOVED







Vieux Carré Commission



Historic Case Study



#### DESCRIPTION

Vieux Carre Commission Rating: Green

Alterations: c1988

Type: c1898 Eastlake double townhouse

There is a long history of removing stoops and altering the floor height of buildings throughout the French Quarter and particularly on commercial dense Bourbon Street. These alterations reflect the changing needs and demands of the district which although is of extreme historic significance is not a time capsule to a bygone era but a living breathing neighborhood.

This report contains multiple examples of buildings within the French Quarter which have been allowed to be altered in order to service modern business needs and safety codes. All of these buildings which where built for a residential use no longer exists in a residential zone and have little hope of ever returning to that use.

The current floor level of 717 Bourbon is not suited to its current and long-standing use and the stoops required to access the interior of the building create daily struggles for the owner and patrons. The stoop, A detail which is prized and celebrated among New Orleans residential buildings is problematic in this entertainment zone bring the occupants of this building daily pain. As these are the only stoops on Bourbon for a considerable distance along the street people often congregate there preventing entry into the building and frequently putting the employees of the business in danger of physical harm when those congregating are asked to leave. An issue which has been addressed with the NOPD with little assistance offered.

The stoops themselves as well as those that congregate there limit the flow of pedestrian along this section of the sidewalk often causing people to have to step into the street creating a further safety issue. Some elements of this building which were common for its use when the building was constructed have now become burdensome and dangerous under its current function.











### 818 ROYAL

Vieux Carre Commission Rating: Yellow

Alterations: c1980 & 2019 (currently under renovation)

Type: 1910 raised frame bungalow

A raised bungalow is an atypical building type for the district and through it was built as a residence it has been functioning as a commercial building for most of its life. Though the lower level was never intended to occupiable space it occupied by various businesses for decades before code compliance made it no longer possible. Even though this building was not significantly altered and maintained nearly all of its original detailing the Vieux Carre Commission approved the raising of this structure in order to add height to the lower lever so it could continue to function for business use.









#### **626 BOURBON**

Vieux Carre Commission Rating: Yellow

Alterations: c1920, c1970, & 2017 (currently under renovation)

Type: A 2-story Spanish revival building originally constructed as a 1-story building, between 1876 and 1896. In the 1920s a second floor was added, and the first-floor façade was set back to create a porch which has since been infilled (approx. 1970).

Currently under renovation this building has had several iterations throughout its history. Adjustments have been made to suit both popular style and use and once again it has been altered in order to better accommodate its use in a heavily commercial area. The floor has been lowered and a gallery which has never previously existed on this building has been approved to be added as a desirable feature on Bourbon Street.







#### **615 BOURBON**

Vieux Carre Commission Rating: Green

Alterations: c1970 & 1984

Type: c1830 typical 11/2-story masonry double Creole cottage.

This building's facade was altered significantly from its original 1830s detailing in the late 19<sup>th</sup> century; it is supposed the alterations permitted in the 1970s were to restore the building's original appearance in many aspects. Though it was still permitted to be lowered to street level in order to accommodate a commercial use which has altered the proportions and door heights. The building was then altered again in 1984 to add the stucco banding on the front façade and to shift the door openings to be evenly space.











## **420 BOURBON**

Vieux Carre Commission Rating: Green

Alterations: c1975

Type: c1830 typical 1½-story masonry double Creole cottage.

This building's façade has not experience significant alterations for the sake of changing fashions but it is unclear if the orientation of windows and doors present in 1959 was original to the structure or if the four door layout was in fact a façade restoration. What is clear is that this building was lowered to street level to accommodate its commercial use and it is evident in the number of lights present in the doors they were lengthened to accommodate this drop in floor level.





From: Braud, Andres [andres.braud@engelvoelkers.com]

Sent: Wednesday, September 9, 2020 11:15 AM

To: irl@silversteinlawplc.com
Subject: 717 Bourbon St. - Steps Letter

#### To Whom It May Concern:

During my time at 717 Bourbon Street, there were a number of problems experienced that were only exacerbated by the city's lack of effective policing, and insignificant and cumbersome architectural features of our building, namily the steps protruding into the middle of the sidewalk. This made it nearly impossible for disabled people to get in and out of the building, much less traverse the sidewalk.

Another big problem experienced was the vagrants and drug dealers sitting on the steps of the building. This blocks the sidewalk, the entrance to the business, and made a great place for people to urinate, defecate, and vomit on. The vagrants would not move unless the police forced them to and then they would always come back a short while later. The drug dealers were always combative and threatening. This was not good for the businesses, or the city as a whole.

Allowing this building to be modified while still preserving its architectural uniqueness is possible. The preservation of architecturally significant buildings is important, but progress for the greater good of the general public, ADA compliance, is more important and is the ethical thing to do.

Please work with the property owners on this matter as it will help make the French Quarter a better place for everyone.

Sincerely Yours,

Andres Braud Real Estate Adviser

#### Engel & Völkers New Orleans

Licensee of Engel & Völkers U.S. Holdings, Inc.
Independently Owned and Operated
Licensed Realtor in Louisiana

722 Martin Behrman Avenue Metairie, LA 70005

USA

Tel: +1 504 875 3555 Fax: +1 504 875 3550 Mobile: +1 504 377 7838 Internet: neworleans.evusa.com Mailto: andres.braud@evusa.com

This e-mail and any attachments are confidential. If you are not the intended recipient of this e-mail, please immediately delete its contents and notify us. This e-mail was checked for virus contamination before being sent - nevertheless, it is advisable to check for any contamination occurring during transmission. We cannot accept any liability for virus contamination.

---- Forwarded Message -----

From: Margarita Bergen < margaritabergen@hotmail.com >

To: Khaliq Siddiqui <<u>khaliqsiddiqui@yahoo.com</u>>
Sent: Saturday, September 12, 2020, 06:13:32 PM CDT

Subject: Re: Bourbon St Statement

Darling Khali Siddiqui,

I have tried several times to come by -HANG IT Up Gallery on Bourbon Street to check out some of your sales items but I am afraid to go in because there are

always people sitting in the steps leading to the gallery.

Why don't you report it to the Vieux Carre Commission or put a big sign that says "Not Sitting on the Steps "? Sitting in those steps is definitely

a

deterrent for people to patronize your business and we need at this time all the business that you can. I hope this problem could be solved ASAP. Margarita Bergen

Randy McClendon <mcclendonrandy829@gmail.com>
To:Randy McClendon,aks1321@gmail.com

Mon, Sep 7 at 9:05 AM

Mr. Khaliq Siddiqui,

Good morning,

This email is in follow-up of our conversation from Saturday September 5th, when I explain to you that it was difficult for me and my young daughters (10 & 12) to come into your businesses. You seem to empathize with our shopping dilemma as I empathize with your dilemma to be able to have customers come freely into your businesses.

All the people standing and sitting on the stairs in front of your businesses makes patronizing your businesses very difficult. It was very frustrating to say excuse me and have them give us a dumb look as if we were doing something wrong. I've seen people picketing businesses that interfere less with customers entering the businesses.

After leaving your store, we decided that we were no longer going to walk/tour the area so we went home, making it a sad day for tourism.

If you have any questions about our unpleasant adventure, please call me 504-782-3554. Please also call me if you are able to have your "picketers" move on. We would love to tour the area and businesses further.

Randy McClendon





715-719 Bourbon – Photos from Applicant









715-719 Bourbon – Photos from Applicant













LNP17060200002110 7/30/2020 11:47:35 AM OPCD501 Page 128 of 128 Title Proximity Type WARNING 817 BURGUNDY 817 BURGUNDY ST, NO Outer Previous Incidents Name Address Incident # Date N CLAIBORNE AVE 100 LNP17053100 17:02:05 5/31/2017 (5A04) / PAUGER ST, NO 038820 Associated Incidents Attachments History -Time/Date Trans Type User ID Console ID 18:18:14 6/2/2017 **UNIT MGMT** opcd104 Unit ID: NP/801B Unit Location Location: NULL (719 BOURBON ST) City: NULL (NO) 18:18:14 6/2/2017 FREE UNIT opcd104 Unit Freed Unit ID: NP/801B 18:18:14 6/2/2017 INC UPDT opcd104 Disposition Dispo: NAT Unit ID: NP/801B 18:18:14 6/2/2017 **UNIT STAT** opcd104 Unit Status Unit ID: NP/801B Status: C (AR) 18:18:14 6/2/2017 INC STAT E3 opcd104 Incident Status Status: Closed (Active) 18:17:19 6/2/2017 PRIM UNIT opcd104 Primary Unit Primary: NP/801B (NP/803B) 18:17:11 6/2/2017 UNIT MGMT opcd104 Unit ID: NP/803B Unit Location Location: NULL (719 BOURBON ST) City: NULL (NO) 18:17:11 6/2/2017 FREE UNIT opcd104 Unit Freed Unit ID: NP/803B UNIT STAT 18:17:11 6/2/2017 opcd104 Unit Status Unit ID: NP/803B Status: C (OS) 18:05:19 6/2/2017 **UNIT STAT** opcd104 E3 Unit Status Unit ID: NP/803B Status: OS (EN) 17:58:37 6/2/2017 UNIT STAT NP/HORNER1949 /B15041 Unit Status Unit ID: NP/801B Status: AR (EN) Submitted: 17:58:37 6/2/2017 17:57:50 6/2/2017 **UNIT STAT** opcd104 E3 Unit ID: NP/803B Unit Status Status: EN (OS) 17:57:50 6/2/2017 UNIT STAT opcd104 Unit Status Unit ID: NP/801B Status: EN (OS) 17:57:43 6/2/2017 UNIT STAT opcd104 E3 Unit Status Unit ID: NP/803B Status: OS (DS) 17:57:43 6/2/2017 **UNIT STAT** opcd104

Unit ID: NP/801B

Unit Status

Status: OS (DS)

715-719 Bourbon – Example of Reports Submitted by Applicant

