## SAMPSON PLAYGROUND: Existing Conditions





### SAMPSON PLAYGROUND: Existing Conditions



Playset with broken playground tiles.



Basketball court facing south.



Rusted backstop fence and uneven walkway.



Existing benches around basketball court and entrance to park.




Basketball court facing the pool house.




ADA ramp to sidewalk but no ADA access to the play structure.


#### SAMPSON PLAYGROUND: Site Improvements Plan



#### SAMPSON PLAYGROUND Landscape Plan



# SAMPSON PLAYGROUND: Impervious Surfaces - existing and proposed



#### SAMPSON PLAYGROUND: Materials




**Location of New Poured in Place Safety Surfacing** 



**50% Blue 50% Black**Safety Surface Color



**Example of Basketball Court Surfacing** 



**High School Basketball Court Surfacing Colors** 



**Basketball Hoops**